



Carolina Power & Light Company

Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461-0429
March 9, 1984

FILE: B09-13510C
SERIAL: BSEP/84-0531

Mr. James P. O'Reilly, Administrator
U. S. Nuclear Regulatory Commission
Region II, Suite 3100
101 Marietta Street N.W.
Atlanta, GA 30303

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-324
LICENSE NO. DPR-62
SPECIAL REPORT PER TECHNICAL SPECIFICATION 3.7.8 AND
PURSUANT TO TECHNICAL SPECIFICATION 6.9.2 (2-SR-84-4)

Dear Mr. O'Reilly:

During Unit No. 2 power operation on February 4, 1984, a fire barrier LCO was initiated to permit the repair of an inoperable fire door in the Control Building (door No. 108, located at fire barrier penetration seal No. CB-1-302). Misalignment of the door resulting from distortion of the door upper hinge prevented the door from latching properly. Appropriate repairs were made to the door and on February 23, 1984, the door was returned to service. During the time period the subject door was inoperable, appropriate stationed fire watches were maintained.

Very truly yours,

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

RMP/ag/LETJ03

cc: Mr. R. C. DeYoung
NRC Document Control Desk

8403130406 840309
PDR ADOCK 0500C324
S PDR

IE22
1/0