

DMB

UNION ELECTRIC COMPANY
1901 GRATIOT STREET
ST. LOUIS, MISSOURI

DONALD F. SCHNELL
VICE PRESIDENT

March 12, 1984

MAILING ADDRESS:
P. O. BOX 149
ST. LOUIS, MISSOURI 63186

Mr. James G. Keppler
Regional Administrator
U. S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

ULNRC-762

Dear Mr. Keppler:

FINAL 10CFR50.55(e) REPORT NO. U-46
CALLAWAY PLANT

Reference: ULNRC-727, dated January 18, 1984

The reference letter provided an interim report on a potential 10CFR50.55(e) deficiency involving structural steel bolts that were found by visual inspection not to be tightened to specification requirements. The structural steel connections at the time of inspection had been considered complete.

The final report has been completed and concludes that the structural adequacy of the connections was sufficient in the as-found condition.

Based on the above, we are withdrawing this potential 10CFR50.55(e).

Very truly yours,

Donald F. Schnell
Donald F. Schnell

DBS/DWC/sla

cc: J. E. Konklin, NRC Region III
Richard DeYoung, Director I&E
NRC Resident Inspectors, Callaway Plant (2)
Missouri Public Service Commission

54483

8403200028 840312
PDR ADUCK 05000483
S PDR

MAR 15 1984

IE27
10