

Commonwealth Edison Company  
LaSalle Generating Station  
2601 North 21st Road  
Marseilles, IL 61341-9757  
Tel 815-357-6761



April 27, 1995

U.S. Nuclear Regulatory Commission  
Washington, DC 20555  
Attn: Document Control Desk

SUBJECT: Environmental Protection Plan Operating Report Appendix B to Facility  
License No. NPF-11 and NPF-18

Attached is the Annual Environmental Operating Report for 1994 for the Environmental Protection Plan as required by Section 5.4 of Appendix B to Facility License No. NPF-11 and NPF-18.

This report includes information required by the following subsections of Appendix B:

- 3.1 Plant Design and Operation
- 4.2.1 Vegetative Integrity on Cooling Pond Dike
- 5.4.1 EPP Noncompliances and the Corrective Actions to Remedy Them
- 5.4.2 Nonroutine Reports

In accordance with Regulatory Guide 10.1, 18 copies are being submitted.

Sincerely,

A handwritten signature in dark ink, appearing to read "D. J. Ray", is written over the typed name.

D. J. Ray  
Station Manager  
LaSalle County Station

DJR/JB/mkl

cc: J. B. Martin, Region III Administrator  
P. G. Brochman, Sr. Resident Inspector, LaSalle  
Environmental Services Department, ComEd  
R. H. Jacobs  
G. G. Benes  
LaSalle Station Central File

SM-94-32

A Unicom Company

9505040121 941231  
PDR ADDCK 05000373  
R PDR

JE25'

**LaSalle County Station  
Environmental Protection Plan**

**1994 Annual Operating Report**

**Plant Design and Operation**

No changes in station design or operation, tests or experiments were made in accordance with subsection 3.1 which involve a potentially significant unreviewed environmental issue.

**Vegetative Integrity on the Cooling Pond Dike**

The vegetative integrity on the cooling pond dike was inspected in accordance with LaSalle County Surveillance LTS-1000-5. Inspections were completed on 4/29/94, 5/27/94, 6/30/94, 7/29/94, 9/8/94 and 10/27/94. The results of the inspections were as follows:

The ground cover integrity on the cooling pond dikes remained intact. One small bare spot was noted at marker 139 due to fiber optic cable installation; however, this area was reseeded and is growing normally.

Canadian Thistle was present on the cooling pond dike. A program of thistle control is in progress for 1995.

There were no other vegetative concerns noted during the 1994 cooling pond dike inspections.

**EPP Noncompliance and Action Taken to Remedy Them**

There were no EPP noncompliances that occurred in 1994.

**Nonroutine Reports**

No nonroutine reports were submitted.