



Wisconsin Electric POWER COMPANY

231 WEST MICHIGAN, MILWAUKEE, WISCONSIN 53201

August 8, 1974

Mr. James G. Keppler, Regional Director
Directorate of Regulatory Operations, Region III
U. S. Atomic Energy Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

COPY SENT TO: PDR ☒
LPDR ☒
NSIC ☐
TIC ☐

Dear Mr. Keppler:

DOCKET NOS. 50-266 AND 50-301
HYDRAULIC SHOCK SUPPRESSORS
POINT BEACH NUCLEAR PLANT

In our letter of December 4, 1973, we advised you of the interim inspection results of Unit 2 hydraulic shock suppressors. As we noted in our letter, we planned to repeat this inspection during a Unit 2 shutdown to verify details and serial numbers. On July 1, 1974, after continuously operating for 197 days, Unit 2 was shut down for maintenance purposes. At this time, the hydraulic shock suppressors were reinspected with the following results:

<u>Manufacturer</u>	<u>Serial/Model No.</u>	<u>Oil Level</u>
Anker-Holth	37149-A, 500K-17	O.K.
Anker-Holth	37149-A, 500K-18	O.K.
Anker-Holth	37149-A, 500K-19	O.K.
Anker-Holth	37149-B, 800K-11	O.K.
Anker-Holth	37149-B, 800K-12	O.K.
Anker-Holth	37149-A, 500K-15	O.K.
Anker-Holth	37149-A, 500K-16	O.K.
Anker-Holth	37149-A, 500K-20	O.K.
Anker-Holth	37149-B, 800K-13	O.K.
Anker-Holth	37149-B, 800K-14	O.K.
Grinnell	3377, 2 1/2" Q-3	O.K.
Grinnell	3379, 2 1/2" HS-30	O.K.
Grinnell	7763, 3", Type 2	O.K.
Grinnell	3181, HB-28	O.K.
Grinnell	3378, 2" HS-29	O.K.
Grinnell	3367, HS-16	O.K.
Grinnell	3370, HS-11	O.K.
Grinnell	3366, 2 1/2" HS-15	O.K.
Grinnell	3365, 2 1/2" HS-12	O.K.

AUG 12

8403270346 750708
PDR ADOCK 05000266
P PDR

Handwritten signature and date: 8/2/74

Mr. James G. Keppler

- 2 -


August 8, 1974

We wish to point out that various model numbers were reported erroneously in our interim report and that we have made the necessary corrections in this report.

A detailed visual inspection was performed to verify the integrity of split cotter pins which hold the clevice pins in place. No abnormalities were found during this inspection.

In summary reply to your July 27, 1973, letter, and its attached Regulatory Operations Bulletin No. 73-3 concerning "loss of hydraulic oil", this report advises you that neither our Unit 1 nor our Unit 2 have fluid level problems with their Anker-Holth and Grinnell hydraulic shock suppressors.

Very truly yours,

A handwritten signature in dark ink, appearing to read "Sol Burstein". The signature is fluid and cursive, with a large, sweeping initial "S".

Executive Vice President

Sol Burstein

PD

MEMO ROUTE SLIP Form AEC-93 (Rev. May 14, 1967) CM 0240		See me about this. Note and return.	For concurrence. For signature.	For action. For information.
TO (Name and unit) RO Chief ES&EB RO:HQ (4) Licensing (4) DR Central Files Region I	INITIALS DATE	REMARKS Wisconsin Electric Power Company Point Beach 1 & 2 50-266 and 50-301		
TO (Name and unit) Region II PDR Local PDR NSIC DTIE	INITIALS DATE			
TO (Name and unit) OGC, Beth, P-506A F. Rizzo, RO:HQ	INITIALS DATE			
FROM (Name and unit) G. Fiorelli RO:III <div style="font-size: 2em; margin-left: 100px;">8</div>	REMARKS Attached is a copy of licensee's reply dated August 8, 1974, to BO Bulletin 73-3. <div style="text-align: right; font-family: cursive; font-size: 1.5em; margin-top: 20px;"> [Signature] 50-266/301 </div>			
PHONE NO.	DATE 8-12-74			

USE OTHER SIDE FOR ADDITIONAL REMARKS

GPO : 1971 O - 445-469