



March 9, 1984
L-84-60

Mr. James P. O'Reilly
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 2900
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

Re: St. Lucie Units 1 and 2
Docket Nos. 50-335, 50-389
Inspection Report 83-43/71

Florida Power & Light Company has reviewed the subject inspection report and a response is attached.

There is no proprietary information in the report.

Very truly yours,

for 
J. W. Williams, Jr.
Vice President
Nuclear Energy

JWW/PLP/js

Attachment

cc: Harold F. Reis, Esquire
PNS-LI-84-82

8403290114 840319
PDR ADOCK 05000335
Q PDR

ATTACHMENT

Re: St. Lucie Units 1 and 2
Docket Nos. 50-335, 50-389
Inspection Report 83-43/71

Finding

10 CFR 50, Appendix B, Criterion VI, as implemented by Section 6.0 of Florida Power and Light Topical Report FPLTQAR 1-76A, requires in part that Measures assure that documents are distributed to and used at the location where the prescribed activity is performed.

Contrary to the above, during a routine periodic audit of Unit 2 Control Room procedures (Administrative, Operating, Emergency and Off-Normal), several examples were found of failure to properly control procedures.

Response

1. FPL concurs with the finding.
2. The finding occurred due to personnel oversight as a result of reorganizing the Operating Procedure Index and reidentifying some procedures from "Plant" (affecting both units) to individual unit procedures. Individuals were not paying close attention to the pre-fix when preparing and issuing procedures.
3. As corrective action, all indexes have been reviewed against master copies and the procedures in Control Room have been verified against those indexes.
4. To preclude further problems, the personnel involved have been instructed to pay close attention to detail when handling procedure revisions.
5. Full compliance was achieved by February 24, 1984.