

Indian Point 3
Nuclear Power Plant
P.O. Box 215
Buchanan, New York 10511
914 739.8200



March 21, 1984
IP3-JAS-912

Dr. Thomas E. Murley
Regional Administrator
Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406


SUBJECT: I.E. Bulletin No. 83-07
Apparently Fraudulent Products Sold
By Ray Miller, Inc.

Dear Dr. Murley:

Attachment A of this letter provides the results of the Authority's review of the subject bulletin and its supplements. Approximately 220 man hours of staff time were spent in the research and preparation of this report.

Should you or your staff have any questions regarding this matter, please contact Mr. J. Schivera of my staff.


Very truly yours,


John C. Brons
Resident Manager

JAS:jmd

Attachment

SUBSCRIBED AND SWORN TO
BEFORE ME THIS 21st DAY
OF March, 1984



RUTHANNE B. BOWMAN
Notary Public, State of New York
No. 4651904, Westchester County
Commission Expires March 30, 1985

8403300175 840321
PDR ADDCK 05000286
G PDR

TE 11

ATTACHMENT A

With IE Bulletin 83-07 the NRC provided to licensees listings of Ray Miller, Inc. customers who had received apparently fraudulent materials. Two supplements were later issued identifying secondary recipients and end users of the apparently fraudulent materials. Bulletin 83-07 requested licensees to review the listings and to determine if any of the apparently fraudulent materials were supplied for use in their facilities. If any Ray Miller, Inc. materials were identified, licensees were requested to follow additional action items outlined in Bulletin 83-07.

The Authority has completed a detailed review of the IE Bulletin 83-07 listings and has determined to the best of our abilities and knowledge, that none of the apparently fraudulent Ray Miller, Inc. materials were ever provided to or used at the Indian Point 3 facility during the Authority's ownership of Indian Point 3. Companies who had provided services and/or materials to the Authority and whose names appeared on the NRC supplied listings were contacted. In addition, all past and current suppliers of pipe, fittings and flanges were contacted. The Authority has received confirmation from these companies that no direct or indirect purchases of Ray Miller, Inc. materials were made for use at Indian Point 3. An in-depth purchase order audit revealed that no direct purchases of Ray Miller, Inc. materials were made during the Authority's ownership of Indian Point 3.

The Indian Point 3 facility was acquired by the Authority from the Consolidated Edison Company in 1975. Two Plant Completion Items (PCI's) were identified by Consolidated Edison as having been accomplished during their ownership of Indian Point 3 that incorporated components supplied by Ray Miller, Inc. The PCI's involved non-safety related controllers and used fittings supplied by Ray Miller, Inc. Although the Ray Miller, Inc. materials were installed in non-safety related systems, an in place physical inspection was performed. No evidence of physical tampering or items of noncompliance were identified. No other Ray Miller, Inc. supplied components were identified by Consolidated Edison.

Based on the above findings, no further action is required by the Authority on IE Bulletin 83-07.