

NRC FORM 366
(12-81)

U.S. NUCLEAR REGULATORY COMMISSION
LICENSEE EVENT REPORT

APPROVED BY OMB
3150-0011
EXPIRE: 4-30-82

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 MDCN 1000-000000-000034111145
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CON'T

01 REPORT SOURCE L605000317708168380330849
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At 1142 during normal operations, swing diesel generator (DG) #12 shut
03 down on loss of fuel oil during the performance of surveillance testing
04 rendering it inoperable (T.S.3.8.1.1). Investigation revealed the level
05 switches for the day tank were isolated preventing operation of the fuel
06 oil transfer pump and actuation of the low level alarm. It was determined
07 that this condition existed from 10 to 16 August during which time 11 and
08 21 DGs remained operable. Similar events: none.

09 SYSTEM CODE E E 11 CAUSE CODE A 12 CAUSE SUBCODE C 13 COMPONENT CODE XXXXX 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
17 LER/RO REPORT NUMBER 83 EVENT YEAR 83 SEQUENTIAL REPORT NO. 046 OCCURRENCE CODE 01 REPORT TYPE X REVISION NO. 1
ACTION TAKEN H 18 FUTURE ACTION G 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0000 ATTACHMENT SUBMITTED N 23 NPRO-4 FORM SUB. Y 24 PRIME COMP. SUPPLIER Z 25 COMPONENT MANUFACTURER Z999

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of this event was personnel error, procedures were not followed.
11 The open commitments of this LER are addressed in NRC Inspection Report
12 50-317/83-22 and 50-318/83-22, detail item No. 5, sub-items f and g.
13 Since the Inspection Report commitments parallel this LER's commitments,
14 no further LER related actions are deemed necessary.

15 FACILITY STATUS E 28 % POWER 100 OTHER STATUS N/A 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Operator Observation 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
16 ACTIVITY CONTENT RELEASED Z 33 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36

17 PERSONNEL EXPOSURES NUMBER 000 TYPE Z 37 DESCRIPTION N/A 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

18 PERSONNEL INJURIES NUMBER 000 DESCRIPTION N/A 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

20 PUBLICITY ISSUED N 44 DESCRIPTION N/A 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER J. W. Raynor

PHONE: 301-260-4313

IE22

8404050070 840330
PDR ADOCK 05000317
S PDR

NRC USE ONLY

BALTIMORE GAS AND ELECTRIC COMPANY

P.O. BOX 1475

BALTIMORE, MARYLAND 21203

NUCLEAR POWER DEPARTMENT
CALVERT CLIFFS NUCLEAR POWER PLANT
LUSBY, MARYLAND 20657

March 30, 1984

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Docket No. 50-317
License No. DPR-53

Dear Sirs:

The attached supplemental report to LER 83-46/3X, Revision 1, is being sent to you as required by 10 CFR 50.73.

Should you have any questions regarding this report, we would be pleased to discuss them with you.

Very truly yours,

LBR Russell

L. B. Russell
Plant Superintendent

JWR
LBR:JWR:mst

cc: Dr. T. E. Murley
Director, Office of Management Information
and Program Control
Messrs: A. E. Lundvall, Jr.
J. A. Tiernan

IE22
11