

DMB

UNION ELECTRIC COMPANY

1901 GRATIOT STREET  
ST. LOUIS, MISSOURI

DONALD F. SCHNELL  
VICE PRESIDENT

April 4, 1984

MAILING ADDRESS:  
P. O. BOX 149  
ST. LOUIS, MISSOURI 63166

Mr. James G. Keppler  
Regional Administrator  
U.S. Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

ULNRC- 785

Dear Mr. Keppler:


INTERIM REPORT NO. U-73  
UNDERSIZED POWER-OPERATED RELIEF VALVE RELAY  
CALLAWAY UNIT 1

---

On Friday, March 2, 1984, we provided Mr. Bob Lerch of Region III verbal notification of a 10CFR50.55(e) report regarding a deficiency in the design of the PORV relay circuit. On Friday, March 30, 1984, an extension was granted to April 6, 1984, by Mr. Jay Harrison of Region III. The problem involves the sizing of the PORV relays associated with PORV's PCV-455A and PCV-456A which renders the PORV's inoperable.

Since the same problem is applicable to both Callaway and Wolf Creek units, the deficiency is considered generic. The final report is currently expected to be submitted by SNUPPS prior to April 13, 1984.

Very truly yours,

  
for Donald F. Schnell

NRI/lkr

cc: B. L. Forney, NRC Region III  
Richard DeYoung, Director I&E  
NRC Resident Inspectors, Callaway Plant (2)  
Missouri Public Service Commission

8404120137 840404  
PDR ADCK 05000482  
S PDR

IE27  
APR 6 1984 40