

## [PLEASE PRINT ALL REQUIRED INFORMATION]

EVENT	DESCRIPTION
1	...
2	...
3	...
4	...
5	...
6	...
7	...
8	...
9	...
10	...
11	...
12	...
13	...
14	...
15	...
16	...
17	...
18	...
19	...
20	...
21	...
22	...
23	...
24	...
25	...
26	...
27	...
28	...
29	...
30	...
31	...
32	...
33	...
34	...
35	...
36	...
37	...
38	...
39	...
40	...
41	...
42	...
43	...
44	...
45	...
46	...
47	...
48	...
49	...
50	...
51	...
52	...
53	...
54	...
55	...
56	...
57	...
58	...
59	...
60	...
61	...
62	...
63	...
64	...
65	...
66	...
67	...
68	...
69	...
70	...
71	...
72	...
73	...
74	...
75	...
76	...
77	...
78	...
79	...
80	...
81	...
82	...
83	...
84	...
85	...
86	...
87	...
88	...
89	...
90	...
91	...
92	...
93	...
94	...
95	...
96	...
97	...
98	...
99	...
100	...

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION			
0	7	E						A	Z	Z	Z	Z	N			
7	8	9	10	11	12	13	14	15	16	17	43	44	45	46	47	48

09	Found loose 120 V control fuse holder on terminal block. Apparent vibration caused	80
7 8 9		
09	the loosening and interruption of control voltage.	80
7 8 9		
10		80
7 8 9		

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	H	0	22			a		Attempt to start.	
7	8	9	10	12	13	44	45	46	80
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
12	Z	0		N/A					
7	8	9	10	11		44	45		80

NUMBER				TYPE	DESCRIPTION	
1	3	0	0	0	Z	N/A
7	8	9	11	12	13	RD

NUMBER				DESCRIPTION	
1	4	0	0	0	N/A

1	5	None
---	---	------

8 9 10  
PUBLICITY  
17 None  
7 8 9

8302180133 751001  
PDR ADOCK 05000220  
S PDR

80

PHONE: (315) 343-2110