

LICENSEE EVENT REPORT

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME		LICENSE NUMBER										LICENSE TYPE					EVENT TYPE								
01	N	Y	N	M	P	1								4	1	1	1	1	0	1					
7	8	9				14	15							25	26			30	31	32					
CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER								EVENT DATE					REPORT DATE						
01	CON'T	M	I	L	L	0	5	0	-	0	2	2	0	0	9	2	2	7	5	1	0	0	1	7	5
7	8		57	58	59	60	61						68	69				74	75					80	

EVENT DESCRIPTION

02	During routine surveillance involving calibration check, a Main Steam Line Temperature																			80
03	Switch was found to actuate at 173°F or more conservative than the - 200 ±10°F.																			80
04	Readjusted to required limits.																			80
05																				80
06	AOR 75-28																			80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE								PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07	I	B	E	I	N	S	T	R	U	N	F	0	8	0	N				
7	8	9	10	11	12					17	43	44		47	48				

CAUSE DESCRIPTION

08	Set point drift.																			80
09																				80
10																				80

FACILITY STATUS		% POWER			OTHER STATUS				METHOD OF DISCOVERY		DISCOVERY DESCRIPTION							
11	D	0	0	0	N/A	b	N/A											
7	8	9	10	12	13	44	45	46							80			
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE			AMOUNT OF ACTIVITY				LOCATION OF RELEASE									
12	0	Z	N/A															
7	8	9	10	11	44	45									80			

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION											
13	0	0	0	Z	N/A										
7	8	9	11	12	13										80

PERSONNEL INJURIES

NUMBER		DESCRIPTION													
14	0	0	0	N/A											
7	8	9	11	12											80

WASTE CONSEQUENCES Probable

15	None																			80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION													
16	Z	N/A													
7	8	9	10												80

PUBLICITY

17	None																			80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	None																			80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																				80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: Thomas J. Dente

PHONE: (315) 543-2110

Line Temperature Switch which was found acutuate ...
(33 Copies Enclosure Received)