

LICENSEE EVENT REPORT

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME		LICENSE NUMBER		LICENSE TYPE		EVENT TYPE	
01	M	N	P	I	N	2	00-000000-00
04	1	1	1	1	1	1	03
CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER	
01	CONT	L	L	L	L	L	050-0306
EVENT DATE		REPORT DATE		EVENT DATE		REPORT DATE	
040677		050677		040677		050677	

EVENT DESCRIPTION

02	With Cooling Tower Bus CT 11 out of service for preventive maintenance at Unit 1	80
03	refueling. Cooling Tower Bus CT 12 was lost when a relay specialist erroneously	80
04	reinstalled a relay on Bus Tie Breaker CT-BT112. Bus CT 12 was reenergized in half	80
05	an hour.	80
06	(P-RO-77-11)	80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE		PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER		VIOLATION	
07	E	A	A	E	Z	Z	Z	Z	Z	Z	Z
9		10		11		12		13		14	

CAUSE DESCRIPTION

08	Personnel error. This report will be circulated to individual personnel.	80
09		80
10		80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	E	1	0	0	NA	B	NA		
9		10		11		12		13	
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
12	Z	Z	NA			NA			
9		10		11		12		13	

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION	
13	0	0	0	Z	NA
9		10		11	

PERSONNEL INJURIES

NUMBER		DESCRIPTION	
14	0	0	0
9		10	

OFFSITE CONSEQUENCES

15	NA	80
----	----	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION	
16	Z	NA	
9		10	

PUBLICITY

17	NA	80
----	----	----

ADDITIONAL FACTORS

18	All safeguards circuitry responded correctly to the loss of voltage on Bus CT 12.	80
19		80

NAME: A A Hunstad PHONE: 612-388-4767

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

May 6, 1977



IE FILE COPY



Mr J G Keppler, Director, Region III
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr Keppler:

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-206 License No. DPR-60
3

Loss of CT 12 Supply to Unit 2 Safeguards
Bus While CT 11 Was Out of Service

The Licensee Event Report for this occurrence is reproduced on the back of this letter. (Enclosed are 3 copies.)

Yours very truly,

David M. Mayer FOR

L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/deh

cc: Director, IE, USNRC (30)
Director, MIPC, USNRC (3)
G Charnoff
MPCA
Attn: J W Ferman