

LICENSEE EVENT REPORT

CONTROL BLOCK

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME					LICENSE NUMBER										LICENSE TYPE					EVENT TYPE					
0	1	N	J	O	C	P	1	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	0	0	1
7	8	9					14	15									25	26				30	31	32	

CONT		CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER				EVENT DATE				REPORT DATE																		
0	1	M	I	T	L	0	5	0	-	0	2	1	9	1	2	1	2	7	5	1	2	2	3	7	5							
7	8	57	58	59	60	61							68	69										74	75							80

EVENT DESCRIPTION During a routine 6-month load test on A station batteries, personnel error in following procedure 601.2.2 caused the 125 volt D.C. distribution center to be deenergized. After reenergizing the center, the A, C and E recirculation pumps, A feedwater pump and cleanup system A recirculation pump tripped. (This is expected for the return of D.C. power). Plant shutdown commenced immediately because of license requirements. Recirculation pumps became operable and load reduction was terminated.

G <sub>5</sub>		
7	8	9
G <sub>6</sub>		
7	8	9

SYSTEM CODE		CAUSE CODE	COMPONENT CODE						POINT COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION		
0	7	E	C	A	Z	Z	Z	Z	Z	Z	Z	9	9	9	9	Y
7	8	9	10	11	12	13	14	15	16	17	43	44	45	46	47	48

CAUSE DESCRIPTION Personnel error in following procedure 601.2.2 caused the 125 volt D.C. distribution center to be deenergized. The distribution center was immediately reenergized. A change has been drafted to existing procedure 601.2.2 to define more clearly the steps to be taken in preparation for conducting the battery load test.

7 8 9

FACILITY STATUS		N POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	1	0	8	6	NA		B	NA		
7	8	9	10	12	13	44	45	46	60	

FORM OF ACTIVITY RELEASED: 1 2 7 8

CONTENT OF RELEASE: Z 9 10

AMOUNT OF ACTIVITY: NA 11 44

LOCATION OF RELEASE: NA 45 80

## PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
1	3	0	0	0	NA

## PERSONNEL INJURIES

NUMBER				DESCRIPTION
14	0	0	0	NA

### OFFSITE CONSEQUENCES

1	8	NA
7	8	9

LOSS OR DAMAGE TO FACILITY

[illegible]

## PUBLICITY

1	2	NA
7	B 9	

### ADDITIONAL FACTORS

1 11 7 8 9 PDR ADUCK 05000219 S PDR

7 8 9


NAME

201 530 0111

# Jersey Central Power & Light Company



MADISON AVENUE AT PUNCH BOWL ROAD • MORRISTOWN, N. J. 07960 • 201-539-6111

MEMBER OF THE  
General  Public Utilities Corporation  
SYSTEM

December 23, 1975  
GN-75-055




Mr. R. Boyd, Acting Director  
Division of Reactor Licensing  
Office of Nuclear Reactor Regulation  
United States Nuclear Regulatory Commission  
Washington, DC 20555

Dear Mr. Boyd:

Subject: Oyster Creek Station  
Docket No. 50-219  
Licensee Event Report --  
Abnormal Occurrence No. 50-219/75-33

This letter forwards the attached Licensee Event Report to report Abnormal Occurrence No. 50-219/75-33 in compliance with paragraph 6.6.2.a of the Technical Specifications.

Very truly yours,



Donald A. Ross, Manager  
Generating Stations-Nuclear

CS  
Enclosures

cc: Mr. J. P. O'Reilly, Director  
Office of Inspection and Enforcement, Region 1

14379

COPY SENT REGION I