

CONTROL BLOCK

LICENSEE NAME: 01 N Y N M P 1  
 LICENSE NUMBER: 11-111111  
 LICENSE TYPE: 41111  
 EVENT TYPE: 01  
 CONT: 01  
 CATEGORY: M I  
 REPORT TYPE: L  
 REPORT SOURCE: L  
 DOCKET NUMBER: 050-0220  
 EVENT DATE: 041475  
 REPORT DATE: 050375

02	During normal power operation, the relay coil in RPS relay 12K30 (turbine trip	80
03	1 out of 2 twice) shorted. EP# GEH-2024, part no. GEF-2757. Redundant relays were	80
04	fully operable. Relay assumed tripped condition upon failure. Relay coil was	80
05	replaced and unit tested.	80
06		80
AOR 75-08		80

08	Appears to be normal failure, the result of the environment and high usage. Coil	
09	is always energized.	80
10		80
		80

NUMBER	TYPE	DESCRIPTION
000	0	7

NUMBER	DESCRIPTION
00	Z

15 None as redundant component available and operable.

TYPE		DESCRIPTION
1	6	Z

17	None
----	------

18	None
----	------

19 L

NAME: T.J. Dente

PHONE: (315) 343-2110