

LICENSEE EVENT REPORT

CONTROL BLOCK:

| | | | | | |
|--|--|--|--|--|--|
| | | | | | |
|--|--|--|--|--|--|

1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME: 01 F L T P S 4
 LICENSE NUMBER: 00-00000-00
 LICENSE TYPE: 41111
 EVENT TYPE: 01
 CATEGORY: 01 CONT
 REPORT TYPE: T
 REPORT SOURCE: 0
 DOCKET NUMBER: 050-0251
 EVENT DATE: 080576
 REPORT DATE: 081976

[illegible]

02 The NSSS vendor has informed FPL of recent developments that affect
7 8 9
03 certain safety analyses at Turkey Point. The consequence has been a
7 8 9
04 reduction in the maximum allowable F_Q and $F_{\Delta H}$ as described in the
7 8 9
05 attached report.
7 8 9
06
7 8 9

| SYSTEM CODE | | CAUSE CODE | | COMPONENT CODE | | | | | | PRIME COMPONENT SUPPLIER | | COMPONENT MANUFACTURER | | | | VIOLATION | |
|-------------|---|------------|----|----------------|----|---|---|---|----|--------------------------|----|------------------------|---|----|----|-----------|--|
| 0 | 7 | Z | Z | Z | Z | Z | Z | Z | Z | N | W | 1 | 2 | 0 | N | | |
| 7 | 8 | 9 | 10 | 11 | 12 | | | | 17 | 43 | 44 | | | 47 | 48 | | |

CAUSE DESCRIPTION

| | | |
|----|------------------------|-----------|
| 06 | See Event Description. | |
| 09 | | 80 |
| 10 | | 80 |
| | FACILITY | METHOD OF |

| | | | | | | | | | | |
|---------------------------|---|--------------------|----|--------------------|-----|---------------------|----|-----------------------|--|----|
| FACILITY STATUS | | % POWER | | OTHER STATUS | | METHOD OF DISCOVERY | | DISCOVERY DESCRIPTION | | 80 |
| 11 | E | 1 | 0 | 0 | N/A | d | | N/A | | |
| 7 | 8 | 9 | 10 | 12 | 13 | 44 | 45 | 46 | | 80 |
| FORM OF ACTIVITY RELEASED | | CONTENT OF RELEASE | | AMOUNT OF ACTIVITY | | | | LOCATION OF RELEASE | | |
| 12 | Z | Z | | N/A | | | | N/A | | |
| 7 | 8 | 9 | 10 | 11 | 44 | 45 | | | | |

PERSONNEL EXPOSURES

| NUMBER | | | | TYPE | DESCRIPTION | |
|--------|---|---|---|------|-------------|-----|
| 1 | 3 | 0 | 0 | 0 | 2 | N/A |

PERSONNEL INJURIES

| NUMBER | | | DESCRIPTION |
|--------|-----|--|-------------|
| 14 | 000 | | N/A |

PROBABLE CONSEQUENCES

| | |
|----|-----|
| 15 | N/A |
|----|-----|

LOSS CR DAMAGE TO FACILITY

| TYPE | | DESCRIPTION |
|------|---|-------------|
| 15 | Z | N/A |

PUBLICITY

| | |
|----|-----|
| 17 | N/A |
|----|-----|

ADDITIONAL FACTORS

18 8304040015 760819 N/A

19 | PDR ADOCK 05000251
S PDR 60

89

NAME: M. A. Schoppman

PHONE: 305/552-3779



August 19, 1976

PRN-LI-76-221

Mr. Norman C. Moseley, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N. W., Suite 818
Atlanta, Georgia 30303

Dear Mr. Moseley:

REPORTABLE OCCURRENCE 251-76-7
TURKEY POINT UNIT 4
DATE OF OCCURRENCE: AUGUST 5, 1976

ECCS ANALYSIS

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9.2 to provide prompt notification of the subject occurrence.

Very truly yours,

for J.R. Benssen
A. D. Schmidt
Vice President
Power Resources

MAS/cpc

Attachment

cc: Jack R. Newman, Esquire
Director, Office of Inspection and Enforcement (40)
Director, Office of Management Information and
Program Control (3)

8876

COPY SENT REGION 