

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME				LICENSE NUMBER												LICENSE TYPE				EVENT TYPE					
01	F	L	T	P	S	4	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	1	
7	8	9				14	15											25	26				30	31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE				REPORT DATE									
01	CONT	T	0	0	5	0	-	0	2	5	1	0	5	1	7	7	6	0	5	2	7	7	6
7	8	57	58	59	60	61					68	69			74	75							80

EVENT DESCRIPTION

02	During the current refueling outage, a section of the sixth tube support	80
03	plate was removed from Steam Generator 4C by the manufacturer. The section	80
04	was sent to the manufacturer's Research and Development Laboratory for	80
05	evaluation. Based on preliminary results, some cracking of the tube	80
06	support plate section has been identified. Several observations were	80

SYSTEM CODE	CAUSE CODE	COMPONENT CODE				PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER			VIOLATION					
07	C	C	F	H	T	E	X	C	H	N	W	1	2	0	N
7	8	9	10	11	12				17	43	44			47	48

CAUSE DESCRIPTION

08	Laboratory examination results and evaluations have not determined the	80
09	cause of this occurrence. The manufacturer has undertaken a diagnostic	80
10	program to develop an understanding of the observed conditions.	80

FACILITY STATUS	% POWER	OTHER STATUS		METHOD OF DISCOVERY	DISCOVERY DESCRIPTION				
11	H	0	0	0	N/A	C	Vendor Inspection		
7	8	9	10	12	13	44	45	46	80

FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE				
12	Z	N/A	N/A				
7	8	9	10	11	44	45	80

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION				
13	0	0	0	2	N/A	
7	8	9	11	12	13	80

PERSONNEL INJURIES

NUMBER	DESCRIPTION				
14	0	0	0	N/A	
7	8	9	11	12	80

PROBABLE CONSEQUENCES

15	N/A	80
----	-----	----

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION			
16	2	N/A		
7	8	9	10	80

PUBLICITY 8304040054 760527
PDR ADOCK 05000251
S PDR

17	N/A	80
----	-----	----

ADDITIONAL FACTORS

18	See Page Two for Continuation of Event Description.	80
----	---	----

19		80
----	--	----

NAME: M. A. Schoppman

PHONE: 305/552-3779



June 4, 1976

PRN-LI-76-138

Mr. Norman C. Moseley, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N.W., Suite 818
Atlanta, Georgia 30303

Dear Mr. Moseley:

251
REPORTABLE OCCURRENCE 351-76-3
TURKEY POINT UNIT 4
DATE OF OCCURRENCE: MAY 17, 1976

CORRECTION

A Licensee Event Report for the subject occurrence was sent to you on May 27, 1976. Line 2 of the Event Description contained the words "Steam Generator 4". The correct wording is "Steam Generator 4C". A corrected LER, page 1, is attached.

Very truly yours,

A. D. Schmidt
A. D. Schmidt
Vice President
Power Resources

MAS/ghf

Attachment

cc: Jack R. Newman, Esquire
Director, Office of Inspection and Enforcement (30)
Director, Office of Management Information and
Program Control (3)

5939

COPY SENT REGION *TH*