

[PLEASE PRINT ALL REQUIRED INFORMATION]

PHONE: 305/552-3779

REPORTABLE OCCURRENCE 250-76-10
LICENSEE EVENT REPORT
PAGE TWO

Event Description (continued)

therefore, the "2 out of 3" trip logic requirement was satisfied. Similar events have occurred, and were described in reports 250-74-10, 250-75-2, 250-75-7, and 251-75-3.

(250-76-10)

Cause Description (continued)

superimposed on the DC voltage from the power supply. Corrective action was to replace the defective capacitors. Also, a program is in progress to replace this type capacitor in other comparators.



LE FILE COPY

December 22, 1976

PRN-LI-76-312

Mr. Norman C. Moseley, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N. W., Suite 813
Atlanta, Georgia 30303

Dear Mr. Moseley:

REPORTABLE OCCURRENCE 250-76-10
TURKEY POINT UNIT 3
DATE OF OCCURRENCE: NOVEMBER 25, 1976

STEAM FLOW COMPARATOR

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9.2 to provide 30-day notification of the subject occurrence.

A. D. Schmidt
Vice President
Power Resources

MAS/cmp

Attachment

cc: Robert Lowenstein, Esquire
Director, Office of Inspection and Enforcement (30)
Director, Office of Management Information and
Program Control (3)