

LICENSEE EVENT REPORT

CONTROL BLOCK 1 2 3 4 5 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME 01 M N M N P 1 14 15 0 0 - 0 0 0 0 0 - 0 0 25 26 4 1 1 1 1 30 31 0 1 32

CATEGORY 01 CONT 57 58 P O 59 T 60 61 0 5 0 - 0 2 6 3 68 69 0 9 1 4 7 3 74 75 0 9 2 4 7 5 80

EVENT DESCRIPTION

02 7 8 9 During cold shutdown, snubber located inside drywell on B Loop LPCI line 80
03 7 8 9 discovered low on oil. Subsequent test verified snubber capable of performing 80
04 7 8 9 intended function. Two previous similar occurrences. Affected part replaced 80
05 7 8 9 in kind. (AO 263/75-18) 80
06 7 8 9 80

SYSTEM CODE 07 8 9 10 C F 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CAUSE DESCRIPTION

08 7 8 9 A Bergen-Paterson Model HSSA-10 leaked oil due to improperly installed seal. 80
09 7 8 9 Snubber last rebuilt in November, 1973. Subsequent maintenance experience 80
10 7 8 9 should minimize possibility of recurrence. 80

FACILITY STATUS 11 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

PERSONNEL EXPOSURES

13 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

PERSONNEL INJURIES

14 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

OFFSITE CONSEQUENCES

15 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

LOSS OR DAMAGE TO FACILITY

16 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21

REGULATORY DOCKET FILE COPY
NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

September 24, 1975

Mr R S Boyd, Acting Director
Division of Reactor Licensing
U S Nuclear Regulatory Commission
Washington, DC 20555

Dear Mr Boyd:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Licensee Event Report to the NRC
Low Oil Level in B LPCI Line Snubber

The Licensee Event Report for this occurrence is reproduced on the back of this letter.

Yours very truly,

L. O. Mayer

L O Mayer, PE
Manager of Nuclear Support Services

LOM/MHV/ak

cc: J G Keppler
G Charnoff
MPCA
Attn: J W Ferman



10257