

Duke Power Company
Catawba Nuclear Generation Department
4800 Concord Road
York, SC 29745

M. S. TUCKMAN
Vice President
(803)831-3205 Office
(803)831-3426 Fax



DUKE POWER

February 12, 1992

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555

Subject: Catawba Nuclear Station, Unit 2
Docket No. 50-414
Special Report
Vibration and Loose Parts Monitoring System

Pursuant to Technical Specification 3.3.3.9, find attached a Special Report concerning the inoperability of the Unit 2 Vibration and Loose Parts Monitoring System Channel 11 (Steam Generator C).

Very truly yours,

M. S. Tuckman

CRL/SR21292.SGC

Attachment

xc: S. D. Ebner
Regional Administrator, Region II

R. E. Martin, ONRR

W. T. Orders
Senior Resident Inspector

9202210372 920212
PDR ADDCK 05000414
S PDR

IE22
11

SPECIAL REPORT

CATAWBA NUCLEAR STATION, UNIT 2

Vibration and Loose Parts Monitoring System Channel 11

On January 10, 1992 Channel 11 (Steam Generator C) of the Vibration and Loose Parts Monitoring System was declared inoperable due to a 60 Hz noise on the channel. A grounding problem with the cable is suspected to be the cause. A work request has been written to repair the channel during a future outage of sufficient length. This is being scheduled for an outage because a containment entry is necessary to make the repair. Channel 7, which is the other Steam Generator C channel, is functioning and provides coverage.

Since the channel has been inoperable for more than 30 days, it is reportable to the NRC pursuant to Technical Specification 3.3.3.9.