

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

84 JUN 25 P12:41 June 22, 1984
BLRD-50-438/81-35
BLRD-50-439/81-38

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - AUXILIARY BUILDING FUEL HANDLING
ZONE VENTILATION FANS - BLRD-50-438/81-35, BLRD-50-439/81-38 - SECOND
SUPPLEMENTAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on May 6, 1981 in accordance with 10 CFR 50.55(e) as NCR BLN BLP 8111. This was followed by our interim reports dated June 5 and December 14, 1981; June 11 and September 28, 1982; and February 16, 1983, our final report dated August 3, 1983 and our supplemental report dated January 13, 1984. Below is our second supplemental report.

As discussed with NRC-OIE Inspector P. E. Fredrickson on June 11, 1984, the date of June 15, 1984 for completion of corrective actions indicated in our final report would not be met. The extended cold weather of this past winter prevented TVA from deenergizing the heating coils, thus the necessary modifications could not be performed. The corrective action on this matter will be completed by September 17, 1984.

If you have any questions concerning this matter, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

8407020152 840622
PDR ADOCK 05000438
S PDR

L. M. Mills
L. M. Mills, Manager
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

OFFICIAL COPY

1/0 IE27