

DMB

Wayne H. Jens
Vice President
Nuclear Operations

**Detroit
Edison**

2000 Second Avenue
Detroit, Michigan 48226
(313) 586-4150

June 26, 1984
EF2-67824

Mr. James G. Keppler
Regional Administrator
U. S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reference: 1. Fermi 2,
NRC Docket No. 50-341
2. USNRC IE Bulletin 74-12, October 25, 1974
3. EF2-29758, November 12, 1974

Subject: Follow-Up Report on NRC IE Bulletin 74-12

Bulletin 74-12 identified a problem wherein a utility had been supplied Westinghouse Type SG relays with incorrectly sized coils. In Detroit Edison's response (Ref. 3) to the bulletin, we stated that Westinghouse Type SG relays will not be used at Fermi 2. Since Detroit Edison felt that this problem could occur in other relays, a testing program procedure was developed that called for verification of relay types and their coil rating prior to preoperational testing. Reference 3 documented this position and program commitment. This bulletin was subsequently closed by the NRC in Inspection Report 50-341/83-05, covering the inspection conducted from January 1 through February 28, 1983.

While investigating another problem, our Instrumentation and Controls Section recently discovered that two relay panels supplied by General Electric were unexpectedly equipped with Westinghouse relays-Type SG.

As was committed to you in Reference 3, Detroit Edison has developed a procedure as part of our testing program that calls for the verification of the relay type and correctness of the coils at the time of equipment approval for service, prior to preoperational testing. The Procedure is identified

8407100463 840626
PDR ADOCK 05000341
Q PDR

JUL 2 1984


JEH 1/0

Mr. James G. Keppler
June 26, 1984
EF2-67824
Page 2

as: Generic Checkout And Initial Operation Test Procedure, CAIO.000.045, "Multi-Contact Auxiliary Relay". The testing program is applied to all auxiliary relays and would detect the deficiency identified via Reference 2. Accordingly, continued implementation of this procedure will assure that the concerns raised in Bulletin 74-12 will not become a problem at Fermi 2. As a consequence, Detroit Edison has revised its previous position and presently allows the use of Westinghouse Type SG relays.

Should you require additional information from Detroit Edison concerning this matter, please contact Mr. Lewis P. Bregni, (313) 586-5083.

Sincerely,

A handwritten signature in cursive script, reading "Wayne H. Jens".

cc: Mr. P. M. Byron
Mr. R. C. DeYoung
Mr. R. C. Knop
Mr. M. D. Lynch
USNRC, Document Control Desk
Washington, D. C. 20555