



GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704


AREA CODE 713 838-6631

September 26, 1984
RBG-19014
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Final Report/DR-181



Gulf States Utilities Company (GSU) has completed its evaluation of DR-181 concerning surface conditions on field welds FW-002A and FW-004A. Indications originally detected by radiographic testing (RT) are not considered weld defects but surface conditions that require additional grinding and preparation for RT. After grinding the inside diameter of these welds to remove the surface conditions, a final RT verified adequate surface preparation. Because no hardware deficiency exists, the original weld would not have been compromised. Therefore GSU has determined this condition does not meet the reporting criteria of 10CFR50.55(e).

Sincerely,

William J. Reed Jr.
for J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

JEH
JEB/PJD/lp

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector-Site

8410100595 840926
PDR ADOCK 05000458
S PDR

IE-27
1/0