



PECO ENERGY

Robert W. Boyce
Plant Manager
Limerick Generating Station

PECO Energy Company
Limerick Generating Station
PO Box 2300
Sanatoga, PA 19464-0920
215 327 1200 Ext. 2000

10CFR 50.73

October 13, 1995
Docket No. 50-353
License No. NPF-85

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

SUBJECT: Licensee Event Report
Limerick Generating Station - Unit 2

This LER reports a Unit 2 reactor SCRAM, an automatic Reactor Protection System actuation resulting from low reactor water level, and automatic actuation of various Engineered Safety Features. This event also resulted in the automatic actuation of the Reactor Core Isolation Cooling (RCIC) system and subsequent water injection as a result of low-low reactor water level. The cause of the event was a relay coil failure combined with an inappropriate action by a licensed operator.

Reference:	Docket No. 50-353
Report Number:	2-94-010
Revision Number:	01
Event Date:	October 19, 1994
Report Date:	October 13, 1995
Facility:	Limerick Generating Station P.O. Box 2300, Sanatoga, PA 19464-2300

This revision provides the results of an analysis performed for the N-relay coil failure addressed in this report. The changes are indicated by revision bar markers in the right hand margins. This LER is being submitted pursuant to the requirements of 10CFR50.73(a)(2)(iv) and Technical Specifications (TS) Reporting Requirement 6.9.2, as required by TS Action 3.7.3.

Very truly yours,

KOS\DMS:cah

cc: T. T. Martin, Administrator Region I, USNRC
N. S. Perry, USNRC Senior Resident Inspector, LGS

9510240195 951013
PDR ADDCK 05000353
S PDR