

10/02/84

REGION 5
LICENSEE EVENT REPORT

PAGE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	10-10-83	OTHER	S		0		INITIAL HOMB THREAT ON SITE TARGET-CONTROL ROOM
	11-04-83	OTHER	S		0		SHERIFF'S DEPT ARRESTS FIVE SUBCONTRACTOR EMPLOYEES FOR MARIJUANA
	81-08-X1	SPECIAL RPT.	C		0		RY FOLLOWUP-PROBLEMS WITH CRANE TILTING DISC CHECK VALVES
	81-10-21	PART 21	C		0		PART 21-(PARBONS PEEBLES) DIESEL GENERATOR SYSTEM DEFECT
	84-02-P	PART 21	C		0		PR 21 BY TERRY/ING-RAND AFW TURBINE VALVES NEED NEW SPRINGS

8410220027 841022
PDR ADOCK 05000528
S PDR

NOTE: CRIB #1 C4 REGION V

1005
1/3

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	IB-79-14	IE BULLETIN	C	8231	0		SEISMIC ANAL OF AS-BUILT SAFETY RELATED PIPING SYSTEM - LATEST EFFECTIVE REV: 1/SUP: 2
	IB-79-21	IE BULLETIN	C	8308	0		TEMPERATURE EFFECTS ON LEVEL MEASUREMENTS
	IB-80-06	IE BULLETIN	C		0		ESP RESET CONTROLS - OL'S RESPOND BY JUL 1, 1980 - CP'S FOR INFO ONLY
	IB-80-09	IE BULLETIN	C		0		HYDRAMOTOR ACTUATOR DEFICIENCIES RESPOND BY JUL 6, 1980
	IB-80-12	IE BULLETIN	C	8121	0		DECAY HEAT REMOVAL SYS OPERABILITY
	IB-80-16	IE BULLETIN	C	8308	0		
	IB-81-01	IE BULLETIN	C		0		SURVEILLANCE OF MECHANICAL SNURBERS-INSPECT ACCESSABLE WITHIN 30 DAYS
	IB-81-02	IE BULLETIN	C	8234	0		POW ISULATION OR BLOCK VALVE FAILURES AGAINST DIFF PRESSURE 90 DAYS FOR CONST
		IE BULLETIN	C	8305	0		
	IB-82-02	IE BULLETIN	C	8422	0		DEGRADATION OF THREADED FASTENERS IN PRIMARY PRESSURE BOUNDARIES
	IB-83-01	IE BULLETIN	C	8422	0		FAILURE OF REACTOR TRIP BREAKERS TO OPEN ON AUTO TRIP SIGNAL

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 2

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
90528	18-83-03	IE BULLETIN	C	8422	0		CHECK VALVE FAILURES IN RAW WATER SYS OF DIESEL GENERATORS
	18-83-04	IE BULLETIN	C	8422	0		FAILURE OF UNDERVOLTAGE TRIP FUNCTION OF REACTOR TRIP BREAKER
	18-83-07	IE BULLETIN	C		0		APPARENTLY FRAUDULENT PRODUCTS SOLD BY RAY MILLER, INC
	18-84-02	IE BULLETIN	0		0		FAILURE OF GE TYPE MFA RELAYS USED IN CLASS 1E SAFETY SYSTEMS

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 3

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
90528	IC-79-21	IE CIRCULAR	C	8231	0		
	IC-80-01	IE CIRCULAR	C	8308	0		GE INDUCTION RELAYS
	IC-80-05	IE CIRCULAR	C	8308	0		EMERG DIESEL GEN LUBE OIL ADDITION AND ONSITE SUPPLY
	IC-80-09	IE CIRCULAR	0		0		PROBLEMS WITH PLANT INTERNAL COMMUNICATIONS SYSTEMS
		IE CIRCULAR	0	8308	0		TRANSFER TO OPS PER PJ/PN DISCUSSION 3/21/83
	IC-80-10	IE CIRCULAR	C	8308	0		FAILURE TO MAINTAIN ENVIRONMENTAL QUALIFICATION OF EQUIPMENT
		IE CIRCULAR	C	8422	0		
	IC-81-03	IE CIRCULAR	C	8422	0		INOP SEISMIC INSTRUMENTATION
	IC-81-10	IE CIRCULAR	0	8422	0		STEAM VOIDING IN RCS DURING COOLDOWN
	IC-81-14	IE CIRCULAR	C	8311	0		EVALUATE MSIV PROGRAMS & PROPOSE CHANGES TO MINIMIZE PROBLEMS
		IE CIRCULAR	C	8422	0		

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 4

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-34-09	INSP RPT (DEV)	C	8406	0		ACCEPTANCE CRITERIA FOR VISUAL INSPECTION OF WELDING
		INSP RPT (DEV)	C	8436			TWO FBAR CHANGES NEED NRR APPROVAL TO CLOSE THIS ITEM
	84-25-03	INSP RPT (DEV)	C	8425			NO AUDITS OF SPRAY ON FIREPROOFING
	84-25-04	INSP RPT (DEV)	C	8425	0		FP HGRS DESIGNED TO SEISMIC IX VS I

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 5

DOCKET ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	82-30-01 INSP RPT (ENF)	P		0		NONCOMPLIANCE STEAM GENERATOR CHEMICAL
83-10-01	INSP RPT (ENF)	C		0		TERMINATION CARDS INACCURATE
83-34-01	INSP RPT (ENF)	C	8436	0		QC PERSONNEL ACCEPTING CONDITIONS NOT IMA DRAWING
83-34-06	INSP RPT (ENF)	C		0		UNSATISFACTORY BOLTING ACCEPTED BY QC
83-34-17	INSP RPT (ENF)	C		0		CABLE TRAY CONNECTIONS DISCONNECTED
83-34-18	INSP RPT (ENF)	C		0		HANGER WELDS NOT IAW DRAWING
83-34-19	INSP RPT (ENF)	C		0		WELD OVERLAP ON INSTRUMENT RACK SUPPORT
83-34-20	INSP RPT (ENF)	C		0		LUMBER IN CHANNEL C ELECTRICAL RACEWAY
83-40-01	INSP RPT (ENF)	R		0		FAILURE TO FOLLOW PROCEDURES
84-15-01	INSP RPT (ENF)	C	8436	0		WELDERS QUALIFIED AFTER THE FACT
84-15-12	INSP RPT (ENF)	C		0		ALL UNITS MINIMUM THREAD ENGAGEMENT CRITERIA FOR THREADED FASTENERS SEE REPORT 50-530/84-07

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 6

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	84-18-01	INSP RPT (ENF)	R		0	0884	NONCOMPLIANCE-NONCONTROL OF EQUIPMENT AND PARTS
	84-18-02	INSP RPT (ENF)	R		0	0884	FAILURE TO TAG NONCOMPLIANCE-NONCONTROL OF NONCONFORMING PARTS
	84-21-01	INSP RPT (ENF)	F		0		FAILURE TO ISSUE AN NCR HONEYWELL'S INSTRUMENTS MADE IMPROPER BY OTHERS
	84-25-01	INSP RPT (ENF)	C	8425	0		SEISMIC ANALYSIS OF THE FIRE PROTECTION SYSTEM IS IMPROPER
	84-28-01	INSP RPT (ENF)	R		0	1084	FAILURE TO PROPERLY DISPOSITION AN SFR

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 7

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-02-03	INSP RPT (FOLLOWUP)	C	8317	0		COLD SPRINGING OF ECM PIPE REQUIRES APS ACTION
		INSP RPT (FOLLOWUP)	C	8436	0		
	83-03-05	INSP RPT (FOLLOWUP)	M		0		FUEL BLDG EXHAUST MONITOR RU-145 8146 SAMPLE POINT LESS THAN 5 DUCE DIAM
	83-12-01	INSP RPT (FOLLOWUP)	M		0		FSAR 12.5.2.1.1 ITEM 8-HOODS & AIR SUPPLY RESOLUTION ADD OR DELETE
	83-12-12	INSP RPT (FOLLOWUP)	M	8328	0		0737 IIF1 CALIBRATION RECORDS
		INSP RPT (FOLLOWUP)	M	8330	0		
		INSP RPT (FOLLOWUP)	M	8434	0		
	83-12-14	INSP RPT (FOLLOWUP)	M		0		0737 IIF1 VENDOR CALIBRATION DATA
		INSP RPT (FOLLOWUP)	M	8434	0		NRC RESPONSE ANALYSIS NOT COMPLETE
	83-12-15	INSP RPT (FOLLOWUP)	E	8328	0		0737 IIF1 STEAM LINE MONITOR CASE CONSTRUCTION & SHIELDING
		INSP RPT (FOLLOWUP)	E	8330	0		

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 8

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-12-15	INSP RPT (FOLLOWUP)	E	8434	0		COMPLETE EPIP REVISION AND REVIEW FOR ADEQUACY
	83-12-16	INSP RPT (FOLLOWUP)	M		0		0737 IIF1 ATT2 IODINE & PARTICULATE SAMPLING CONSIDERATIONS
		INSP RPT (FOLLOWUP)	M	8434	0		COMPLETE PROCEDURES FOR HANDLING POST ACCIDENT FILTERS
	83-12-18	INSP RPT (FOLLOWUP)	M	8434	0		0737 IIF1 ATT3 HIGH RANGE CONTAINMENT MONITORS
	83-12-19	INSP RPT (FOLLOWUP)	M	8434	0		0737 IIB3 PASS
	83-12-20	INSP RPT (FOLLOWUP)	M		0		0737 IIB3 CLARIFICATION 8&9 OFFSITE LABORATORY
		INSP RPT (FOLLOWUP)	M	8431	0		CHANGE PASS BACKUP LAB TO UNIT 2 PROPOSED-REQUIREMENTS WOULD INCLUDE WASTE HANDLING, VENT., MONITORING
		INSP RPT (FOLLOWUP)	M	8434	0		
	83-12-21	INSP RPT (FOLLOWUP)	M		0		FSAR 12.5.2.2.5-NO PORTABLE CAMS HAVE BEEN PROCURED
		INSP RPT (FOLLOWUP)	M	8405	0		CAM'S NOT ORDERED-LICENSEE TAKING ACTION TO CORRECT
	83-12-22	INSP RPT (FOLLOWUP)	M		0		FSAR 12.5.2.2.5-EXAMINE FIXED & MOVABLE AIR MONITORS

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 9

DOCKET	ITEM-NUH	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-14-04	INSP RPT (FOLLOWUP)	P	8401	0		EP PLAN & STAFF AUGMENTATION NOT CONSISTENT WITH NUREG-0654
		INSP RPT (FOLLOWUP)	P	8426	0		
	83-14-14	INSP RPT (FOLLOWUP)	P	8401	0		CR, TSC, OSC & EOC NOT COMPLETED
		INSP RPT (FOLLOWUP)	P	8426	0		
	83-14-17	INSP RPT (FOLLOWUP)	P	8401	0		BACKUP LAB NOT FULLY EQUIPPED AND LICENSED
		INSP RPT (FOLLOWUP)	P	8426	0		
	83-14-21	INSP RPT (FOLLOWUP)	M	8401	C		AREA, PROCESS & EFFLUENT MONITORING SYSTEMS NOT INSTALLED
	83-14-22	INSP RPT (FOLLOWUP)	P	8401	0		NONRADIATION MONITORS NOT INSTALLED
		INSP RPT (FOLLOWUP)	P	8426	0		
	83-14-25	INSP RPT (FOLLOWUP)	P	8401	0		ERFDADS NOT INSTALLED
		INSP RPT (FOLLOWUP)	P	8426	0		

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 10

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-14-29	INSP RPT (FOLLOWUP)	M	8401	0		PROCEDURES FOR PAS NOT WRITTEN
	83-14-30	INSP RPT (FOLLOWUP)	M	8401	0		PROCEDURES FOR EFFLUENT MONITORS NOT WRITTEN
	83-14-32	INSP RPT (FOLLOWUP)	P	8401	0		CARD READER SYSTEM NOT OPERATIONAL
		INSP RPT (FOLLOWUP)	P	8426	0		
	83-17-02	INSP RPT (FOLLOWUP)	C		0		SIT SAFEND TO NOZZLE WELD REQUIRES RT
	83-25-01	INSP RPT (FOLLOWUP)	R		0		FOLLOWUP OF RTD THERMOWELL FAILURES
	83-26-02	INSP RPT (FOLLOWUP)	O		0		RG 1.33 ITEMS APPARENTLY NOT COVERED BY PLANT PROCEDURES
	83-30-01	INSP RPT (FOLLOWUP)	M		0		FUEL BLDG 180 PROBE-SAMPLE LINE PARA. 4.A
	83-33-01	INSP RPT (FOLLOWUP)	M		0		CRACKS RMS INTERFACE REVIEW
	83-3A-01	INSP RPT (FOLLOWUP)	R		0		QUALIFICATION OF CONTAINMENT WATER LEVELS
	83-39-03	INSP RPT (FOLLOWUP)	M		0		BREATHING AIR SUPPLY SYSTEM FOR USE WITH AIRLINE-SUPPLIED MASKS & HOODS

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 11

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-39-03	INSP RPT (FOLLOWUP)	M	8405	0		DIESEL POWERED COMPRESSOR BEING CONSIDERED FOR AIR SUPPLY BACKUP
		INSP RPT (FOLLOWUP)	M	8431	0		60 CFM BREATHING AIR COMPRESSOR- PLANS FOR USE? SUPPORT FOR HOODS AND MASKS?
	83-41-03	INSP RPT (FOLLOWUP)	M		0		CONTROL ROOM RMS ANNUNCIATOR CAPABILITIES & PROCEDURES FOR ALARM RES
	83-41-04	INSP RPT (FOLLOWUP)	M		0		REVIEW UNMONITORED EFFLUENT RELEASE PATHWAYS SUCH AS TURBINE BUILDING
	84-01-01	INSP RPT (FOLLOWUP)	P	8426	0		GRAB SAMPLE CROSS REFERENCE TO SAFETY PRECAUTIONS
	84-04-02	INSP RPT (FOLLOWUP)	C		0		EVALUATION OF STANDARD CONDUIT ELLS
	84-07-01	INSP RPT (FOLLOWUP)	O		0		REEXAMINE COLD LICENSEE TRAINING RECORDS
	84-09-01	INSP RPT (FOLLOWUP)	M		0		DEVELOP QC PROCEDURES FOR GAMMA SPECTROSCOPY & LLD CRITERIA
	84-09-02	INSP RPT (FOLLOWUP)	M		0		TRAINING & PROFICIENCY OF GAMMA SPECTROSCOPY ANALYSTS (SFE PG 5)
	84-10-02	INSP RPT (FOLLOWUP)	C	8425	0		ACTIONS ON FP LOOSE BEAM CLAMPS AND WELDED STUDS
	84-10-04	INSP RPT (FOLLOWUP)	C		0		HVAC WALKDOWN - ADEQUATE FOR SEISMIC INPUT?

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 12

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50520	84-13-03	INSP RPT (FOLLOWUP)	M		0		3/1/84 RMS TASK FORCE MEETING & JOHN STEVENS RPT OF PROBLEMS PARA 7
	84-13-04	INSP RPT (FOLLOWUP)	M		0		CONTROL OF ACCESS TO SPENT FUEL TUBE BELLOW
	84-15-02	INSP RPT (FOLLOWUP)	C		0		ALL UNITS-UPDATE DOCUMENTATION TO REFLECT DESIGN CHANGE IN NUMBER OF RV HOLDDOWN BOLTS
	84-18-04	INSP RPT (FOLLOWUP)	R		0	0884	SAFEGUARDS-ANOMALOUS NOISE LPBI PUMP
	84-23-01	INSP RPT (FOLLOWUP)	R		0	1084	THI T.C.S FEEDBACK OF OPS EXPERIENCE-PROCEDURE ISSUANCE
	84-23-02	INSP RPT (FOLLOWUP)	R		0	0984	OPERATOR REQUAL RE-EXAM
	84-28-03	INSP RPT (FOLLOWUP)	R		0	1084	TDAFWP MODIFICATIONS
	84-31-01	INSP RPT (FOLLOWUP)	M		0		VERIFY SAMPLE LINE FLOW RATES IN PRFOP TEST RESULTS-SEE INSPECTION REPORT FOR SAMPLING PROCEDURES

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 13

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50520	IN-83-17	INFO NOTICE	0		0		DIESEL GENERATOR AUTO-START LOGIC
	IN-83-36	INFO NOTICE	8		0		RECOMMENDED REMOVAL OF CERTAIN SECURITY FEATURES FOR SAFETY ASSURANCE
	IN-84-34	INFO NOTICE	M		0		RESPIRATOR USERS WARNING-SCBA 4500 PSI LUXFER CYLINDERS
	IN-84-40	INFO NOTICE	M		0		EMERGENCY WORKER DOSES-VERIFY RECEIPT, PROPER DISTRIBUTION AND UNDERSTANDING
	IN-84-50	INFO NOTICE	M		0		CLARIFICATION OF SCOPE OF QA PROGRAMS F/TRANSPORT PACKAGES PURSUANT TO PT. 50, APPENDIX B
	IN-84-55	INFO NOTICE	M		0		IE IN 84-55 SEAL TABLE LEAKS AT PWR
	IN-84-56	INFO NOTICE	M		0		IE IN-84-56 RESPIRATOR USERS NOTICE FOR CERTAIN 5-MINUTE EMERGENCY ESCAPE SCBA
	IN-84-59	INFO NOTICE	M		0		IN 84-59 DELIBERATE CIRCUMVENTING OF STATION HEALTH PHYSICS PROCEDURES
	IN-84-60	INFO NOTICE	M		0		IN 84-60 FAILURE OF AIR-PURIFYING RESPIRATOR FILTERS TO MEET EFFICIENCY REQUIREMENT
	IN-84-61	INFO NOTICE	M		0		IN 84-61 OVEREXPOSURE OF DIVER IN PRESSURIZED WATER REACTOR (PWR) REFUELING CAVITY

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 14

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	PJ-08-24	OTHER	F	0			DETERMINE WHETHER DUCOMMUN METAL IS ON APPROVED BIDDER'S LIST
	PJ-09-16	OTHER	0	0	REF		CONDUCT NATL CIRCULATION COOLDWN TEST PRIOR TO FIRST REFUELING REF VAN BRUNT LTR 1/27/83
	PJ-82-02	OTHER	R	0			SER SECTION 7.2.3-CPC SOFTWARE PROCEDURES
	PJ-82-03	OTHER	0	0			SER SECTION 7.3.2.1-I&C PROCEDURES AND TESTING (4 ITEMS)
	PJ-82-04	OTHER	0	0			SER SECTION 7.4.3-IE BULLETIN 79-27 PROCEDURES
	PJ-82-05	OTHER	0	0			SER SECTION 9.5.1-FIRE PROTECTION MODIFICATIONS (3 ITEMS)
	PJ-82-06	OTHER	0	0			SER SECTION 9.5.1.7-FIRE PROTECTION ADMIN CONTROLS & PROCEDURES
	PJ-82-07	OTHER	0	0			SER SECTION 13.1.2.3-TRAINING FOR OPS SUPERINTENDENT (ANSI/ANS 3.1)
	PJ-82-08	OTHER	0	0			SER SECTION 13.5.2-TRAINING OF OPERATORS ON OP/MAINT PROCEDURES
	PJ-82-09	OTHER	0	0			SER SECTION 15.3.9-ATWS PROCEDURES
	PJ-82-10	OTHER	0	0			SER APPENDIX C ITEM A-44-STATION BLACKOUT PROCEDURES

10/02/00

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 15

DOCKET ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	84-35-01	OTHER	3	0		VA ACCESS USE OF KEYCARDS
84-35-02	OTHER	3		0		VA ACCESS-USE OF D&R BUTTON TO EXIT VITAL AREAS
84-35-03	OTHER	3		0		INOPERATIVE CCTU CAMERAS
84-35-04	OTHER	3		0		SCITY TERMINAL BECOMES INOPERATIVE DURING CASCADING FIRE ALARMS
84-35-05	OTHER	3		0		FAILURE TO PROVIDE TWO-CHANNELS FOR SECURITY COMMUNICATIONS

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 16

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	TI-12-03	TEMP INSTR (TI)	C	7906	0		VERIFY COMPLIANCE WITH ASME CERTIFICATION SYSTEM REQUIREMENTS
	TI-12-04	TEMP INSTR (TI)	C		0		INTERVIEWS WITH CRAFTSMEN AT CONSTRUCTION SITES
	TI-12-11	TEMP INSTR (TI)	C		0		INCREASE INSPECTION COVERAGE IN AREAS OF CONSTR. FOUND BY PAST EXPERIENCE TO NEED IMPROVEMENT
	TI-15-14	TEMP INSTR (TI)	0		0		SIS RESET PROCEDURES
	TI-15-29	TEMP INSTR (TI)	C		0		INSPECTION REQUIREMENTS FOR IE BULLETIN 79-14
	TI-15-36	TEMP INSTR (TI)	0		0		LICENSEE TRAINING STAFF MEMBERS MUST RECEIVE SRO LICENSES
	TI-15-64	TEMP INSTR (TI)	0		0		FOLLOWUP OF LICENSEE RESPONSE TO -- GL 83-28, REQUIRED ACTIONS BASED ON SALEM ATWS EVENTS
	TI-15-65	TEMP INSTR (TI)	0		0		TMI ACTION PLAN REQUIREMENT FOLLOWUP

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 17

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	81-04-02	INSP RPT (UNR)	C		0		COMPLIANCE W/AWS STRUCTURAL STEEL PREHEAT & RECORDS REQUIREMENTS
		INSP RPT (UNR)	C	8329	0		
		INSP RPT (UNR)	C	8436	0		CLOSE THIS ITEM ON ISSUANCE OF SSER SUPPL 6
	83-36-01	INSP RPT (UNR)	C	8404	0		CORROSION OF BURIED PIPE
		INSP RPT (UNR)	C	8410	0		
	84-10-01	INSP RPT (UNR)	C	8425	0		QUESTIONS ON VIKING SEISMIC ANALYSIS OF FP MGRS
	84-15-04	INSP RPT (UNR)	C		0		CE REVIEW OF TEST PROCEDURES AND CIPS IS NOT DOCUMENTED OR AUDITABLE
	84-15-05	INSP RPT (UNR)	C		0		ACCEPTANCE CRITERIA FOR HFT AT VARIANCE WITH DRWG, SPECIFICATION
	84-15-06	INSP RPT (UNR)	C		0		TECHNICAL CONCERN FOR SIMULTANEOUS SHIM CLEARANCE VERIFICATION
	84-15-07	INSP RPT (UNR)	C		0		LARGE VOID FOUND IN 1B REACTOR VESSEL SUPPORT PAD
	84-15-08	INSP RPT (UNR)	C		0		DISCREPANCY IN REMARK FOUND ON 1A REACTOR VESSEL SUPPORT PAD MOLES

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PAIO VERDE 1

PAGE 18

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	84-15-09	INSP RPT (UNR)	C		0		ERRORS ON CODE DATA SHEETS FOR 1A REACTOR VESSEL SUPPORT PAD REWORK
	84-15-10	INSP RPT (UNR)	C		0		DEBRIS AT BASE OF RV SUPPORT COLUMN BASE
	84-20-01	INSP RPT (UNR)	C		0		RECEIVING INSPECTION DID NOT HAVE CE PD OR SPECS FOR INSPECTION
	84-25-02	INSP RPT (UNR)	C	8425	0		FIRE PROTECTION PIPING IS SUPPORTED BY CABLE TRAY SUPPORTS -VERIFY LOADS WERE INCLUDED
	84-28-02	INSP RPT (UNR)	R		0	1084	FAILURE TO FOLLOW PROCEDURE INVOLVING TRANSFER OF REACTOR COOLANT TO THE RWT

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 19

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	81-12- C	50.55E RPT	F		0	0130	50.55E-DIESEL GEN CONTROL CABINET WIRING-LACK OF REQ SEP BY COOPER ENERGY SERVICES (DER 81-51)
	81-12- D	50.55E RPT	F		0	0130	50.55E-LOOSE ANTI-ROTATION PINS IN CONTAINMENT SPRAY AND LP81 PUMPS (DER 81-52)
	81-12- E	50.55E RPT	F		0	0130	50.55E-MAIN CONTROL PANEL WIRING-LACK OF REQ SEP BY COMSIP CUSTOM LINE (DER 81-53)
	83-04-04	50.55E RPT	0		0	0505	50.55E-APS STARTUP QC NOT QUALIFIED-DER 8320
	84-01-C	50.55E RPT	C		0		50.55(E): CONTROL OF RETESTING ACTIVITIES DETERMINED NOT TO BE REPORTABLE
	84-02-C	50.55E RPT	C		0		50.55(E): EXCESSIVE RUST SI AND CH VALVES (ALL UNITS) FINAL RPT EXPECTED 6/21/84
	84-03-C	50.55E RPT	C		0		50.55(E): FEEDWATER ISOLATION VALVE STUCK DURING TESTING - FINAL RPT EXPECTED 5/31/84
	84-06-C	50.55E RPT	C		0		50.55(E): FOXBORO ALARM MODULE DEFECTS (ALL UNITS) - FINAL RPT EXPECTED 6/12/84
	84-08-C	50.55E RPT	C		0		50.55(E): BARTON MDL 763 TRNSMITRS DO NOT MEET SPECS (ALL UNITS) FINAL RPT EXPECTED 5/18/84
	84-10-C	50.55E RPT	C		0		50.55(E): FAILURE OF SINGLE ELEMENT RTD'S (ALL UNITS) FINAL REPORT EXPECTED 6/1/84
	84-11-C	50.55E RPT	C		0		50.55(E): PUMP INSTRUMENTATION CONDUIT CONTAMINATED WITH CHLORIDES FINAL RPT EXPECTED 5/29/84

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 20

BUCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	84-12-C	50.55E RPT	C		0		50.55(E): ZONE III VIOLATIONS OF RCP 1A AND 8G #1 FINAL RPT EXPECTED 6/1/84
	84-13-C	50.55E RPT	C		0		50.55(E): HVAC ACCEPTANCE CRITERIA (ALL UNITS) - FINAL RPT EXPECTED 12/14/84
	84-15-C	50.55E RPT	C		0		50.55(E): UNDERSIZED PIPE RESTRAINT SUPPORT WELDS (ALL UNITS)-FINAL RPT EXP 8/3/84
	84-16-C	50.55E RPT	C		0		50.55(E): UNDERSIZED ESFAS RELAY CABINET BASEPLATS (ALL UNITS) FINAL RPT EXPECTED 6/29/84
	84-18-C	50.55E RPT	C		0		50.55(E): WIRING ERROR ON LP8I B PUMP SWITCH-FINAL RPT EXPECTED 6/12/84
	84-19-C	50.55E RPT	C		0		50.55(E): BLIND FLANGES IMPROPERLY INSTALLED (ALL UNITS)
	84-20-C	50.55E RPT	C		0		50.55(E): CONNECTING LINE TO 818 380 DAMAGED
	84-21-C	50.55E RPT	C		0		50.55(E): ROSEMONT TRANSMITTERS LOOSE NUTS
	84-22-C	50.55E RPT	C		0		50.55(E): CEA SHROUD CONTAMINATED WITH OIL
	84-23-C	50.55E RPT	C		0		50.55(E): APW VALVE LOOSE SLEEVE PIN
	84-24-C	50.55E RPT	C		0		50.55(E): ALL UNITS - LOOSE BOLTS ON LIMITORQUE OPERATORS (ALL UNITS)

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 21

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	84-25-C	50,55E RPT	C		0		50,55(E): ALL UNITS - CONTAINMENT AIR SUPPLY REGISTERS BY TITUS HAVE FAILED WIRE
	84-26-C	50,55E RPT	C		0		50,55(E): CIRCUIT BRKR INTERLOCK MECHANISM WAS IMPROPERLY ASSEMBLED
	84-27-C	50,55E RPT	C		0		50,55(E): HVAC INSTRUMENTATION WERE MODIFIED AFTER FINAL ACCEPTANCE BY APS MAINTENANCE
	84-28-C	50,55E RPT	C		0		50,55(E): DIESEL FUEL LINES TOUCHING PENETRATION SLEEVE
	84-29-C	50,55E RPT	C		0		50,55(E): DIESEL GENERATOR HEAT EXCHANGERS HAVE SUBSTANCE BUILDUP
	84-30-C	50,55E RPT	C		0		50,55(E): DIESEL GENERATOR COOLERS HAVE PARTS THAT DONT MEET ASME REQUIREMENTS
	84-31-C	50,55E RPT	C		0		50,55(E): UNSEALED PENETRATIONS IN HSSS BUILDING
	84-33-C	50,55E RPT	C		0		50,55(E): UNIT 1 MISSING WELD ON PIPE SUPPORT I81070H011
	84-34-C	50,55E RPT	C		0		50,55(E): 81T BOLTING UNDERTORQUED/ WASHERS TOO SMALL
	84-35-C	50,55E RPT	C		0		50,55(E): POTENTIOMETERS ON PPS ARE DRIFTING-THIS AFFECTS SAFETY ANALYSIS
	84-36-C	50,55E RPT	C		0		50,55(E): TWO INCH WPBI VALVE STALL JUST OFF CLOSED POSITION-GUIDE HAS CHATTER - RELATED TO DER 83-63

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 22

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	84-1/-C	50.55E RPT	C		0		50.55(E)1 UNAUTHORIZED/UNQUALIFIED DUCT SEALANT USED ON HVAC DUCT-NOTE THIS WAS FOUND BY NRC IN 84-10
	84-39-C	50.55E RPT	C		0		50.55E1 LP81 PUMP HAS RUMBLING NOISES
	84-40-C	50.55E RPT	C		0		50.55E1 APW PUMP IMPELLORS HAVE MIC-DISCOVERED IN US-APPLICABLE TO ALL UNITS
	84-41-C	50.55E RPT	C		0		50.55(E)1 REG IV INSPECTION CARDINAL INDUSTRY PRODUCTS HAD INDETERMINATE QUALITY
	84-42-C	50.55E RPT	C		0		50.55E1 MOTOR OPERATOR TORQUE SWITCHES IMPROPERLY REPLACED NOT QUALIFIED
	84-43-C	50.55E RPT	C		0		50.55(E)1A 3 INCH MORG WARNER VALVE SIV MV 609 FAILED TO OPEN
	84-44-C	50.55E RPT	C		0		50.55E1 PART 21 REPORT ISSUED ON GAULIN CHARGING PUMP BLOCKS FATIGUE FAILURE
	84-45-C	50.55E RPT	C		0		50.55E1 KAMAN RADIATION MEASURING INSTRUMENTS ARE IMPROPERLY INSTALLE
	84-46-C	50.55E RPT	C		0		50.55E1 NOZZLE LOADS FROM 20 INCH PIPES IN REFUELING WATER TANK NOT PREVIOUSLY EVALUATED
	84-48-C	50.55E RPT	C		0		50.55E1 GAULING IN MSIV PLUGS DURING INSTALLATION CAUSE OPERATING LEVERS TO VIBRATE LOOSE
	84-49-C	50.55E RPT	C		0		50.55(F)1AFW VIBRATES IN MINICIRC ALSO -REFER TO DEP 84-23 FOR SIMILA PROBLEM IN FULL FLOW RECIRC

10/02/80

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 23

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	84-50-C	50.55E RPT	C		0		50.55E1 TURBINE DRIVEN AUX FEED PUM FAILED TO QUICK START FROM AMBIENT CONDITIONS
	84-51-C	50.55E RPT	C		0		50.55E1 MSIV MADE BY ANCHOR-DARLING FAILED TO CLOSE IN FIVE SECONDS.
	84-52-C	50.55E RPT	C		0		50.55(E)1BASE FLANGE RESISTOR ON ATMOSPHERIC STEAM DUMPS NOT STRONG ENOUGH TO SURVIVE A SEISMIC EVENT
	84-54-C	50.55E RPT	C		0		50.55(E)1BUMP ISOLATION VALVE COULD NOT BE ELECTRICALLY OPENED AFTER BEING MANUALLY CLOSED
	84-55-C	50.55E RPT	C		0		50.55(E)1UNQUALIFIED FOXBORO MODULES HAVE BEEN INSTALLED IN CLASS 1E ELECTRICAL CABINETS
	84-56-C	50.55E RPT	C		0		50.55(E)1HALON & CO2 SYS FIRE DAMPERS DO NOT FULLY CLOSE UNDER NORMAL OPERATING FLOW
	84-57-C	50.55E RPT	C		0		50.55(E)1CONTAINMENT ISOLATION VALVE IN RAD. WASTE DRAIN FAILED TO CLOSE IN 10 SECONDS.
	84-61-C	50.55E RPT	C		0		50.55(E)1POSSIBLE AUXILIARY PRESSURIZER SPRAY FAILURE-IE LOOP CHARGING V-LVE STICKS OPEN
	84-62-C	50.55E RPT	C		0		50.55(E)1SAFEGRD SEQUENCING PRBLMS WITH SIGNALS TO THE MPSI AND 480 VOLT LOAD CTR BREAKERS
	84-63-C	50.55E RPT	C		0		50.55(E)1TARGET ROCK VALVE FAILED TO CLOSE ON SIT WHEN PRESSURE DROPPED TO 200 PSIG DURING A TEST
	84-64-C	50.55E RPT	C		0		50.55(E)1PIPE SUPPORT SNUBBERS FOUND LOCKED UP AFTER HOT PUMP TEST

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 24

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	84-65-C	50.55E RPT	C		0		50.55E INSTRUMENT LEAD OUTER CABING LOCATED ON UPPER GUIDE STRUCTURE SPLIT EXPOSING CERAMIC INSULATOR
	84-66-C	50.55E RPT	C		0		50.55(E) DOWNCOMER FEEDWATER ISO VALVE FAILED TO COMPLETELY CLOSE UNDER DYNAMIC TEST CONDITIONS
	84-67-C	50.55E RPT	C		0		50.55(E) RED POSITION SWITCH FAILED TO CHANGE STATE W/THE VALVE CHANGE STATE USING REDUCED VOLTAGE
	84-68-C	50.55E RPT	C		0		50.55(E) ESSENTIAL CHILLER 'A' TEMP SWITCH TRIPS OFF AFTER BIAS FOL BY LOSS OF POWER-LOCKING RESTART
	84-69-C	50.55E RPT	C		0		50.55(E) IRP8 CHANNEL C, RELAY K-3 FAILED TO CLOSE DURING SAFEGUARDS TESTING

10/02/84

REGION 5
LICENSEE EVENT REPORT

PAGE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	81-08-X1	SPECIAL RPT.	C		0		RY FOLLOWUP-PROBLEMS WITH CRANE TILTING DISC CHECK VALVES
	81-10-21	PART 21	C		0		PART 21-(PARSONS PEBBLES) DIESEL GENERATOR SYSTEM DEFECT

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 3

PAGE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IR-79-14	IE BULLETIN	C	8231	0		SEISMIC ANAL OF AB-BUILT SAFETY RELATED PIPING SYSTEM - LATEST EFFECTIVE REVI 1/8UP1 2 TEMPERATURE EFFECTS ON LEVEL MEASUREMENTS
	IR-79-21	IE BULLETIN	C	8308	0		
	IR-80-06	IE BULLETIN	C		0		ESP RESET CONTROLS - OL'S RESPOND BY JUL 1, 1980 - CP'S FOR INFO ONLY
	IR-80-09	IE BULLETIN	C		0		HYDRAMOTOR ACTUATOR DEFICIENCIES RESPOND BY JUL 6, 1980
	IR-80-12	IE BULLETIN	C	8121	0		DECAY HEAT REMOVAL SYS OPERABILITY
	IR-81-01	IE BULLETIN	C		0		SURVEILLANCE OF MECHANICAL SHUBBERS-INSPECT ACCESSABLE WITHIN 30 DAYS
	IR-81-02	IE BULLETIN	C	8234	0		POV ISULATION OR BLOCK VALVE FAILURES AGAINST DIFF PRESSURE 90 DAYS FOR CONST
		IE BULLETIN	C	8305	0		
	IR-82-02	IE BULLETIN	C	8413	0		DEGRADATION OF THREADED FASTENERS IN PRIMARY PRESSURE BOUNDARIES
	IR-82-04	IE BULLETIN	C		0		DEFICIENCIES IN PRIMARY CONTAINMENT ELECTRICAL PENETRATION ASSEMBLIES
	IR-83-01	IE BULLETIN	C	8413	0		FAILURE OF REACTOR TRIP BREAKERS TO OPEN ON AUTO TRIP SIGNAL

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 3

PAGE 2

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IR-83-03	IE BULLETIN	C	8413	0		CHECK VALVE FAILURES IN RAW WATER COOLING SYSTEMS OF DG
	IR-83-04	IE BULLETIN	C	8413	0		FAILURE OF UV TRIP FUNCTION OF REACTOR TRIP BREAKERS
	IR-83-06	IE BULLETIN	C		0		NC MATERIALS SUPPLIED BY TUBE-LINE CORP OF LONG ISLD CITY HOUSTON
	IR-83-07	IE BULLETIN	C		0		APPARENTLY FRAUDLENT PRODUCTS SOLD BY RAY MILLER, INC
	IR-83-08	IE BULLETIN	C		0		C/P'S WITH UV TRIP ON SAFETY RELATED SYSTEMS OTHER THAN REACTOR TRIP SYSTEM
	IR-84-02	IE BULLETIN	0		0		FAILURE OF GE TYPE HFA RELAYS USED IN CLASS IE SAFETY SYSTEMS

10/02/94

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 3

PAGE 3

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IC-79-21	IE CIRCULAR	C	8231	0		
	IC-80-01	IE CIRCULAR	C	8308	0		GE INDUCTION RELAYS
	IC-80-05	IE CIRCULAR	C	8308	0		EMERG DIESEL GEN LUBE OIL ADDITION AND ONSITE SUPPLY
	IC-80-09	IE CIRCULAR	0	8308	0		PROBLEMS WITH PLANT INTERNAL COMMUNICATIONS SYSTEMS
	IC-80-10	IE CIRCULAR	C	8308	0		FAILURE TO MAINTAIN ENVIRONMENTAL QUALIFICATION OF EQUIPMENT
		IE CIRCULAR	C	8413	0		
	IC-80-14	IE CIRCULAR	C	8311	0		RADIOACTIVE CONTAMINATION OF PLANT DEMIN. WATER SYSTEM
	IC-81-02	IE CIRCULAR	0		0		PERFORMANCE OF NRC LICENSED INDIVIDUALS WHILE ON DUTY
	IC-81-03	IE CIRCULAR	0	8413	0		INOP SEISMIC INSTRUMENTATION
	IC-81-04	IE CIRCULAR	0		0		ROLE OF STA'S & IMPORTANCE OF LER'S
	IC-81-10	IE CIRCULAR	0	8413	0		STEAM VOIDING IN RCS DURING COOLDOWN

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 3

PAGE 4

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IC-01-12	IE CIRCULAR	0		0		INADEQUATE PERIODIC BREAKER TEST PROCEDURES
	IC-01-14	IE CIRCULAR	C	8311	0		EVALUATE MBIV PROGRAMS & PROPOSE CHANGES TO MINIMIZE PROBLEMS
		IE CIRCULAR	C	8413	0		
	83-15-01	IE CIRCULAR	C	8337	0		EXCESSIVE TENSION ON TENDONS

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 3

PAGE 5

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	84-03-01	INSP RPT (ENF)	C		0		STORAGE OF 480 V.MCC IN LEVEL D STORAGE
	84-07-14	INSP RPT (ENF)	C		0		REGEN HEAT EXCHANGER UPPER SUPPORT JAM NUT ADJUSTMENT & TORQUE
	84-07-17	INSP RPT (ENF)	C		0		CABLE REELS NOT TAGGED NONCONFORMING
	84-12-05	INSP RPT (ENF)	C	8425	0		IMPROPER ACCEPTANCE OF HONEYWELL INSTRUMENTS

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 3

PAGE 6

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	83-03-02	INSP RPT (FOLLOWUP)	C	8311	0	0303	WATER USED TO COOL STAINLESS STEEL WELDS
		INSP RPT (FOLLOWUP)	C	8317	0		
		INSP RPT (FOLLOWUP)	C	8329	0		
84-07-16		INSP RPT (FOLLOWUP)	C		0		REINSPECTION OF PIPE HANGERS AND SUPPORTS - UNIT 3

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 3

PAGE 7

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IN-82-05	INFO NOTICE	S		0		DRUG RELATED INCIDENTS
	IN-82-07	INFO NOTICE	S		0		SCREENING OF ONSITE PERSONNEL
	IN-83-27	INFO NOTICE	S		0		OPERATIONAL RESPONSE TO EVENTS CONCERNING DELIBERATE ACTS AGAINST PLANT (COR W/S & O)
	IN-83-28	INFO NOTICE	S		0		CRITERIA FOR GENERAL EMERGENCY PROTECTIVE ACTION RECOMMENDATIONS
	IN-83-36	INFO NOTICE	S		0		RECOMMENDED REMOVAL OF CERTAIN SECURITY FEATURES FOR SAFETY ASSURANCE
	IN-84-07	INFO NOTICE	S		0		DESIGN BASIS THREAT AND REVIEW OF VEHICULAR ACCESS CONTROL
	IN-84-38	INFO NOTICE	M		0		RESPIRATOR USERS WARNING-SCRA 4500 PSI LUXFER CYLINDERS
	IN-84-40	INFO NOTICE	M		0		EMERGENCY WORKER DOSES-VERIFY RECEIPT, PROPER DISTRIBUTION AND UNDERSTANDING
	IN-84-50	INFO NOTICE	M		0		CLARIFICATION OF SCOPE OF QA PROGRAMS F/TRANSPORT PACKAGES PURSUANT TO PT. 50, APPENDIX B

10/02/89

REGION 3

OUTSTANDING ITEMS REPORT

ALL OPEN ITEMS (SORTED BY TYPE)

PALO VERDE 3

PAGE 8

[illegible]

50530 09-03-30 QTYER

9

9

ADDITIONAL 3 WIRES FOUND CUT
(COMPUTER RM) ON 03/30/83
(PNO-V-84-18)

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 3

PAGE 9

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	TI-00-01	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESPONSE TO IE BULLETIN 79-15
	TI-00-05	TEMP INSTR (TI)	C		0		INSTRUCTIONS FOR VERIFICATION OF TMI ACTION PLAN-LICENSEE ACTIONS
	TI-12-03	TEMP INSTR (TI)	C	7906	0		VERIFY COMPLIANCE WITH ASME CERTIFICATION SYSTEM REQUIREMENTS
	TI-15-27	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESPONSE TO IE BULLETIN 79-02 (ANCHOR BOLTS)
	TI-15-28	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESP TO IEB 7902, REV 1
	TI-15-29	TEMP INSTR (TI)	C		0		INSPECTION REQUIREMENTS FOR IE BULLETIN 79-14
	TI-15-44	TEMP INSTR (TI)	C		0		TMI ACTION PLAN INSPECT RQMTS HP & EMERGENCY PLANNING-REV. 2
	TI-15-53	TEMP INSTR (TI)	C		0		NUREG-0737 INSPECTION RQMTS FOR SYSTEM RQMTS
	TI-15-54	TEMP INSTR (TI)	C		0		IEE RESPONSIBILITY FOR REVIEW OF TMI SERIES
	TI-15-57	TEMP INSTR (TI)	C		0		0737 INSPECTION LISTING FOR EMERGENCY PROCEDURES-DUE EARLY R2
	TI-15-59	TEMP INSTR (TI)	C		0		0737 INSPECTION LISTING FOR MODS DUE 1/82

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 3

PAGE 10

DOCKET	ITEM#	NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	TI-15-60		TEMP INSTR (TI)	C		0		0737 INSPECTION LISTING FOR MONS DUE 7/82
	TI-15-64		TEMP INSTR (TI)			0		INSPECTION FOLLOWUP BASED ON SALEM ATMS EVENTS

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 3

PAGE 11

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	82-09-02	INSP RPT (UNR)	C		0		FLARE VEVEL WELDS
	84-07-13	INSP RPT (UNR)	C		0		VALVE 3P81EV235 8YUD THREAD ENGAGEMENT INTO BONNET
	86-09-01	INSP RPT (UNR)	C		0		SEE 50-528/84-20-01

10/02/84

REGION 3
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 3

PAGE 12

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	83-01-28	50.55E RPT	0		0	0228	50.55E-HVAC TEST PROCED DO NOT MEET ANSI N 510 DER 83-4
	83-04-06	50.55E RPT	0		0	0505	50.55E-APS STARTUP QC NOT QUALIFIED-DER 8320
	83-04-07	50.55E RPT	0		0	0505	50.55E-LP81 PUMP OPERATED W/SUCTION VALVE SHUT-DER 8321
	84-07-C	50.55E RPT	C		0		50.55(E)1 BORG WARNER VALVE STEM EXTENSIONS-REFERENCE PREVIOUS DER 80-21-FINL RPT EXP 6/1/84

10/02/80

REGION 5
LICENSEE EVENT REPORT

PAGE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	81-08-X1	SPECIAL RPT.	C		0		RV FOLLOWUP-PROBLEMS WITH CRANE TILTING DISC CHECK VALVES
81-10-21	PART 21		C		0		PART 21-(PARSONS PEEBLES) DIESEL GENERATOR SYSTEM DEFECT

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 2

PAGE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	IB-79-14	IE BULLETIN	C	8231	0		SEISMIC ANAL OF AS-BUILT SAFETY RELATED PIPING SYSTEM - LATEST EFFECTIVE REV 1/SUP 2 TEMPERATURE EFFECTS ON LEVEL MEASUREMENTS
	IB-79-21	IE BULLETIN	C	8308	0		ESP RESET CONTROLS - OL'S RESPOND BY JUL 1, 1980 - CP'S FOR INFO ONLY
	IB-80-06	IE BULLETIN	C		0		HYDRAMOTOR ACTUATOR DEFICIENCIES RESPOND BY JUL 6, 1980
	IB-80-09	IE BULLETIN	C		0		DECAY HEAT REMOVAL SYS OPERABILITY
	IB-80-12	IE BULLETIN	C	8111	0		SURVEILLANCE OF MECHANICAL SNUBBERS-INSPECT ACCESSABLE WITHIN 30 DAYS
	IB-81-01	IE BULLETIN	C		0		PCRV ISULATION OR BLOCK VALVE FAILURES AGAINST DIFF PRESSURE 90 DAYS FOR CONST
	IB-81-02	IE BULLETIN	C	8234	0		DEGRADATION OF THREADED FASTENERS IN PRIMARY PRESSURE BOUNDARIES
		IE BULLETIN	C	8305	0		DEFICIENCIES ON PRIMARY CONTAINMENT ELECTRICAL PENETRATION ASSEMBLIES
	IB-82-02	IE BULLETIN	C	8420	0		FAILURE OF REACTOR TRIP BREAKERS TO OPEN ON AUTO TRIP SIGNAL
	IB-82-04	IE BULLETIN	C		0		
	IB-83-01	IE BULLETIN	0	8420	0		

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 2

PAGE 2

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	IR-83-03	IE BULLETIN	C	8420	0		CHECK VALVE FAILURES IN RAW WATER COOLING SYSTEM OF AG
	IR-83-04	IE BULLETIN	C	8420	0		FAILURE OF UV TRIP FUNCTION OF REACTOR TRIP BREAKERS
	IR-83-06	IE BULLETIN	C		0		NO MATERIALS SUPPLIED BY TUBE-LINE CORP OF LONG ISLAND CITY HOUSTON
	IR-83-07	IE BULLETIN	C		0		APPARENTLY FRAUDULENT PRODUCTS SOLD BY RAY MILLER, INC
	IR-83-08	IE BULLETIN	C		0		C/B'S WITH UV TRIP IN SAFETY RELATED SYSTEMS OTHER THAN REACTOR TRIP SYSTEM
	IR-84-02	IE BULLETIN	0		0		FAILURE OF GE TYPE HPA RELAYS USED IN CLASS 1E SAFETY SYSTEMS

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 2

PAGE 3

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	IC-79-21	IE CIRCULAR	C	R231	0		
	IC-80-01	IE CIRCULAR	C	8308	0		GE INDUCTION RELAYS
	IC-80-05	IE CIRCULAR	C	8308	0		EMERG DIESEL GEN LUBE OIL ADDITION AND ONSITE SUPPLY
	IC-80-09	IE CIRCULAR	0	8308	0		PROBLEMS WITH PLANT INTERNAL COMMUNICATIONS SYSTEMS
	IC-80-10	IE CIRCULAR	C	8308	0		FAILURE TO MAINTAIN ENVIRONMENTAL QUALIFICATION OF EQUIPMENT
		IE CIRCULAR	C	R420	0		
	IC-80-14	IE CIRCULAR	C	R311	0		RADIOACTIVE CONTAMINATION OF PLANT DEMIN. WATER SYSTEM
	IC-81-02	IE CIRCULAR	0		0		PERFORMANCE OF NRC LICENSED INDIVIDUALS WHILE ON DUTY
	IC-81-03	IE CIRCULAR	0	R420	0		INOP SEISMIC INSTRUMENTATION
	IC-81-04	IE CIRCULAR	0		0		ROLE OF STA'S & IMPORTANCE OF LER'S
	IC-81-10	IE CIRCULAR	0	R420	0		STEAM VOIDING IN RCS DURING COOLDOWN

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 2

PAGE 8

DOCKET	ITEM-NU	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	IC-81-14	IE CIRCULAR	C	A311	0		EVALUATE MSIV PROGRAMS & PROPOSE CHANGES TO MINIMIZE PROBLEMS
		IE CIRCULAR	C	8420	0		

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 2

PAGE 5

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	84-08-04	INSP RPT (DEV)	C	0			DUCT SEALANT NOT QUALIFIED

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 2

PAGE 6

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	84-04-01	INSP RPT (ENF)	C		0		CABLE BEND RADIUS WRONG
	84-08-02	INSP RPT (ENF)	C		0		IMPROPER HVAC BOLTING WELDING SHIMMING
	84-16-03	INSP RPT (ENF)	R		0	0884	NONCOMPLIANCE-IMPROPER DRAWING CONTROL IN CONTROL ROOM

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 2

PAGE 7

DOCKET	ITEM#NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	84-04-02	INSP RPT (FOLLOWUP)	C		0		FACTORY EL RADIUS FOR CABLE
	84-08-01	INSP RPT (FOLLOWUP)	C		0		HVAC CRAFT TRAINING REQUIRED?
	84-10-01	INSP RPT (FOLLOWUP)	M		0		CONTROL OF ACCESS TO SPENT FUEL TUBE BELLOWS

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 2

PAGE 8

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	IN-82-05	INFO NOTICE	S		0		DRUG RELATED INCIDENTS
	IN-82-07	INFO NOTICE	S		0		SCREENING OF ONSITE PERSONNEL
	IN-83-27	INFO NOTICE	S		0		OPERATIONAL RESPONSE TO EVENTS CONCERNING DELIBERATE ACTS AGAINST PLANT (COR W/S & O)
	IN-83-28	INFO NOTICE	S		0		CRITERIA FOR GENERAL EMERGENCY PROTECTIVE ACTION RECOMMENDATIONS
	IN-83-36	INFO NOTICE	S		0		RECOMMENDED REMOVAL OF CERTAIN SECURITY FEATURES FOR SAFETY ASSURANCE
	IN-84-07	INFO NOTICE	S		0		DESIGN BASIS THREAT AND REVIEW OF VEHICULAR ACCESS CONTROL
	IN-84-30	INFO NOTICE	M		0		RESPIRATOR USERS WARNING-BCBA 4500 PSI LUXFER CYLINDERS
	IN-84-80	INFO NOTICE	M		0		EMERGENCY WORKER DOSES-VERIFY RECEIPT, PROPER DISTRIBUTION AND UNDERSTANDING
	IN-84-50	INFO NOTICE	M		0		CLARIFICATION OF SCOPE OF QA PROGRAMS F/TRANSPORT PACKAGES PURSUANT TO PT. 50, APPENDIX B

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 2

PAGE 9

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
90529	TI-00-01	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESPONSE TO IE BULLETIN 79-15
	TI-00-05	TEMP INSTR (TI)	C		0		INSTRUCTIONS FOR VERIFICATION OF TMI ACTION PLAN-LICENSEE ACTIONS
	TI-12-03	TEMP INSTR (TI)	C	7906	0		VERIFY COMPLIANCE WITH ASME CERTIFICATION SYSTEM REQUIREMENTS
	TI-13-01	TEMP INSTR (TI)	0		0		TRANSFER OF SRP REVIEW FROM NRR TO IE
	TI-15-27	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESPONSE TO IE BULLETIN 79-02 (ANCHOR BOLTS)
	TI-15-28	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESP TO IEB 7902, REV 1
	TI-15-29	TEMP INSTR (TI)	C		0		INSPECTION REQUIREMENTS FOR IE BULLETIN 79-14
	TI-15-40	TEMP INSTR (TI)	C		0		TMI ACTION PLAN INSPECT RQMTS HP & EMERGENCY PLANNING-REV. 2
	TI-15-53	TEMP INSTR (TI)	C		0		NUREG-0737 INSPECTION RQMTS FOR SYSTEM RQMTS
	TI-15-50	TEMP INSTR (TI)	C		0		IEE RESPONSIBILITY FOR REVIEW OF TMI SERIES
	TI-15-57	TEMP INSTR (TI)	C		0		0737 INSPECTION LISTING FOR EMERGENCY PROCEDURES-DUE EARLY 82

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 2

PAGE 10

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	TI-15-59	TEMP INSTR (TI)	C		0		0737 INSPECTION LISTING FOR MODS DUE 1/82
	TI-15-60	TEMP INSTR (TI)	C		0		0737 INSPECTION LISTING FOR MODS DUE 7/82
	TI-15-64	TEMP INSTR (TI)	0		0		INSPECTION FOLLOWUP BASED ON SALEM ATWS EVENTS

10/02/88

REGION 3
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 2

PAGE 11

DOCKET ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	88-08-03 INSP RPT (UNR)	C		0		DUCT SEALANT ON GASKETED JOINT
88-12-11	INSP RPT (UNR)	C		0		UGS REMORK PROCEDURE CONTAINS DIMENSION INCONSISTENT WITH DRWGS
88-15-01	INSP RPT (UNR)	C		0		SEE 50-528/89-20-01

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 2

PAGE 12

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	83-01-28	50.55E RPT	0		0	0228	50.55E-HVAC TEST PROCED DO NOT MEET ANSI N 510 DER 83-4
	83-04-06	50.55E RPT	0		0	0505	50.55E-APS STARTUP QC NOT QUALIFIED-DER 8320
	83-04-07	50.55E RPT	0		0	0505	50.55E-LPSI PUMP OPERATED W/SUCTION VALVE SHUT-DER 8321
	84-07-C	50.55E RPT	C		0		50.55(E): BORG WARNER VALVE STEM EXTENSIONS-REFERENCE PREVIOUS DER 80-21-FINL RPT EXP 6/1/84
	84-04-C	50.55E RPT	C		0		50.55(E): CAD WELDING FOR CATHODIC PROTECTION SYSTEM NOT DOCUMENTED FINAL RPT EXPECTED 5/4/84
	84-38-C	50.55E RPT	C		0		50.55E: PIPE SUPPORT INSTALLED INCORRECTLY
	84-53-C	50.55E RPT	C		0		50.55(E): MISSING NUTS & LOOSE BOLTS FOUND ON VALVES LOC IN CONTAINMENT & CHARGING SYSTEM
	84-59-C	50.55E RPT	C		0		50.55(E): CABLES ARE IN CONTACT WITH SHARP METAL EDGES OF FIRE STOPS ABOVE THE MCC.
	84-60-C	50.55E RPT	C		0		50.55(E): INCOMPATIBLE LUBRICANTS WERE USED ON 50 LIMITORQUE VALVES

10/02/84

REGION 5
LICENSEE EVENT REPORT

PAGE 1

DOCKET ITEM-NUM	TYPE	FOLLOWUP	FOLLOWUP	STATUS	ACTION DATE	DESCRIPTIVE
		BRANCH	REPORT NO.			TITLE
50328	10-10-83	OTHER		0		INITIAL BOMB THREAT ON SITE TARGET-CONTROL ROOM
11-08-83	OTHER			0		SHERIFF'S DEPT ARRESTS FIVE SUBCONTRACTOR EMPLOYEES FOR MARIJUANA
81-08-X1	SPECIAL RPT.			0		RV FOLLOWUP-PROBLEMS WITH CRANE TILTING DISC CHECK VALVES
81-10-21	PART 21			0		PART 21-(PARSONS PEEBLES) DIESEL GENERATOR SYSTEM DEFECT
88-02-P	PART 21			0		PR 21 BY TERRY/JING-RAND AFM TURBINE VALVES NEED NEW SPRINGS

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50920	18-79-14	IE BULLETIN	C	8231	0		SEISMIC ANAL OF AS-BUILT SAFETY RELATED PIPING SYSTEM - LATEST EFFECTIVE REVI 1/SUPI 2
	18-79-21	IE BULLETIN	C	8308	0		TEMPERATURE EFFECTS ON LEVEL MEASUREMENTS
	18-80-04	IE BULLETIN	C		0		ESF RESET CONTROLS - OL'S RESPOND BY JUL 1, 1980 - CP'S FOR INFO ONLY
	18-80-09	IE BULLETIN	C		0		HYDRAMOTOR ACTUATOR DEFICIENCIES RESPOND BY JUL 6, 1980
	18-80-12	IE BULLETIN	C	8121	0		DECAY HEAT REMOVAL SYS OPERABILITY
	18-80-16	IE BULLETIN	C	8308	0		
	18-81-01	IE BULLETIN	C		0		SURVEILLANCE OF MECHANICAL SNUBBERS-INSPECT ACCESSABLE WITHIN 30 DAYS
	18-81-02	IE BULLETIN	C	8234	0		POW INSULATION OR BLOCK VALVE FAILURES AGAINST DIFF PRESSURE 90 DAYS FOR CONST
		IE BULLETIN	C	8305	0		
	18-82-02	IE BULLETIN	C	8422	0		DEGRADATION OF THREADED FASTENERS IN PRIMARY PRESSURE BOUNDARIES
	18-83-01	IE BULLETIN	C	8422	0		FAILURE OF REACTOR TRIP BREAKERS TO OPEN ON AUTO TRIP SIGNAL

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 2

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
--------	----------	------	--------------------	------------------------	--------	-------------	----------------------

90528	18-83-03	IE BULLETIN	C	8422	0		CHECK VALVE FAILURES IN RAW WATER SYS OF DIESEL GENERATORS
	18-83-04	IE BULLETIN	C	8422	0		FAILURE OF UNDERVOLTAGE TRIP FUNCTION OF REACTOR TRIP BREAKER
	18-83-07	IE BULLETIN	C		0		APPARENTLY FRAUDULENT PRODUCTS SOLD BY RAY MILLER, INC
	18-84-02	IE BULLETIN	0		0		FAILURE OF GE TYPE MFA RELAYS USED IN CLASS 1E SAFETY SYSTEMS

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 3

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
90528	IC-79-21	IE CIRCULAR	C	8231	0		
	IC-80-01	IE CIRCULAR	C	8308	0		GE INDUCTION RELAYS
	IC-80-05	IE CIRCULAR	C	8308	0		EMERG DIESEL GEN LUBE OIL ADDITION AND ONSITE SUPPLY
	IC-80-09	IE CIRCULAR	0		0		PROBLEMS WITH PLANT INTERNAL COMMUNICATIONS SYSTEMS
		IE CIRCULAR	0	8308	0		TRANSFER TO OPS PER PJ/PN DISCUSSION 3/21/83
	IC-80-10	IE CIRCULAR	C	8308	0		FAILURE TO MAINTAIN ENVIRONMENTAL QUALIFICATION OF EQUIPMENT
		IE CIRCULAR	C	8422	0		
	IC-81-03	IE CIRCULAR	C	8422	0		INOP SEISMIC INSTRUMENTATION
	IC-81-10	IE CIRCULAR	0	8422	0		STEAM VOIDING IN RCS DURING COOLDOWN
	IC-81-14	IE CIRCULAR	C	8311	0		EVALUATE MSIV PROGRAMS & PROPOSE CHANGES TO MINIMIZE PROBLEMS
		IE CIRCULAR	C	8422	0		

10/02/80

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 4

DOCKET ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-34-04 INSP RPT (DEV)	C	8406	0		ACCEPTANCE CRITERIA FOR VISUAL INSPECTION OF WELDING
	INSP RPT (DEV)	C	8434	0		TWO F&B CHANGES NEED NRR APPROVAL TO CLOSE THIS ITEM
	84-25-03 INSP RPT (DEV)	C	8425	0		NO AUDITS OF SPRAY ON FIREPROOFING
	84-25-04 INSP RPT (DEV)	C	8425	0		FP MGRS DESIGNED TO SEISMIC IX V8 I

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

DOCKET ITEM#	ITEM#	TYPE	FOLLOWUP BRANCH	REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50520	82-30-01	INSP RPT (ENP)	F		0		NONCOMPLIANCE STEAM GENERATOR CHEMICAL
	83-10-01	INSP RPT (ENP)	C		0		TERMINATION CARDS INACCURATE
	83-34-01	INSP RPT (ENP)	C	8436	0		QC PERSONNEL ACCEPTING CONDITIONS NOT IN DRAWING
	83-34-08	INSP RPT (ENP)	C		0		UNSATISFACTORY BOLTING ACCEPTED BY QC
	83-34-17	INSP RPT (ENP)	C		0		CABLE TRAY CONNECTIONS DISCONNECTED
	83-34-18	INSP RPT (ENP)	C		0		HANGER WELDS NOT IN DRAWING
	83-34-19	INSP RPT (ENP)	C		0		WELD OVERLAP ON INSTRUMENT RACK SUPPORT
	83-34-20	INSP RPT (ENP)	C		0		LUMBER IN CHANNEL C ELECTRICAL RACEWAY
	83-40-01	INSP RPT (ENP)	R		0		FAILURE TO FOLLOW PROCEDURES
	84-15-01	INSP RPT (ENP)	C	8436	0		WELDERS QUALIFIED AFTER THE FACT
	84-15-12	INSP RPT (ENP)	C		0		ALL UNITS MINIMUM THREAD ENGAGEMENT CRITERIA FOR THREADED FASTENERS SEE REPORT 50-530/84-07

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 6

DOCKET ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
58226	84-18-01 INSP RPT (ENF)	R		0	0884	NONCOMPLIANCE-NONCONTROL OF EQUIPMENT AND PARTS
	84-18-02 INSP RPT (ENF)	R		0	0884	FAILURE TO TAG NONCOMPLIANCE-NONCONTROL OF NONCONFORMING PARTS
	84-21-01 INSP RPT (ENF)	P		0		FAILURE TO ISSUE AN NCR MONEYWELL'S INSTRUMENTS MADE IMPROPER BY OTHERS
	84-25-01 INSP RPT (ENF)	C	8425	0		SEISMIC ANALYSIS OF THE FIRE PROTECTION SYSTEM IS IMPROPER
	84-28-01 INSP RPT (ENF)	R		0	1084	FAILURE TO PROPERLY DISPOSITION AN SPR

10/02/86

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 7

DOCKET ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-02-03 INSP RPT (FOLLOWUP)	C	8317	0		COLD SPRING OF ECM PIPE REQUIRES APS ACTION
	INSP RPT (FOLLOWUP)	C	8436	0		
83-03-05	INSP RPT (FOLLOWUP)	M		0		FUEL BLOC EXHAUST MONITOR RU-143 8146 SAMPLE POINT LESS THAN 5 DUCT DIAM
83-12-01	INSP RPT (FOLLOWUP)	M		0		FSAN 12.5.2.1.1 ITEM 8-HOODS & AIR SUPPLY RESOLUTION ADD OR DELETE
83-12-12	INSP RPT (FOLLOWUP)	M	8328	0		0737 IIFI CALIBRATION RECORDS
	INSP RPT (FOLLOWUP)	M	8330	0		
	INSP RPT (FOLLOWUP)	M	8434	0		
83-12-14	INSP RPT (FOLLOWUP)	M		0		0737 IIFI VENDOR CALIBRATION DATA
	INSP RPT (FOLLOWUP)	M	8434	0		NRC RESPONSE ANALYSIS NOT COMPLETE
83-12-15	INSP RPT (FOLLOWUP)	E	8328	0		0737 IIFI STEAM LINE MONITOR CASE CONSTRUCTION & SHIELDING
	INSP RPT (FOLLOWUP)	E	8330	0		

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 6

DOCKET ITEM#	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
80528	83-12-15 INSP RPT (FOLLOWUP)	E	8434	0		COMPLETE EPIP REVISION AND REVIEW FOR ADEQUACY
	83-12-16 INSP RPT (FOLLOWUP)	M		0		0737 IIF1 ATT2 IODINE & PARTICULATE SAMPLING CONSIDERATIONS
	INSP RPT (FOLLOWUP)	M	8434	0		COMPLETE PROCEDURES FOR HANDLING POST ACCIDENT FILTERS
	83-12-18 INSP RPT (FOLLOWUP)	M	8434	0		0737 IIF1 ATT3 HIGH RANGE CONTAINMENT MONITOR
	83-12-19 INSP RPT (FOLLOWUP)	M	8434	0		0737 IIF3 PASS
	83-12-20 INSP RPT (FOLLOWUP)	M		0		0737 IIF3 CLARIFICATION 849 OFFSITE LABORATORY
	INSP RPT (FOLLOWUP)	M	8431	0		CHANGE PASS BACKUP LAB TO UNIT 2 PROPOSED-REQUIREMENTS WOULD INCLUDE WASTE HANDLING, VENT, MONITORING
	INSP RPT (FOLLOWUP)	M	8434	0		
	83-12-21 INSP RPT (FOLLOWUP)	M		0		PSAR 12.5.2.2.5-NO PORTABLE CAMS HAVE BEEN PROCURED
	INSP RPT (FOLLOWUP)	M	8405	0		CAM'S NOT ORDERED-LICENSEE TAKING ACTION TO CORRECT
	83-12-22 INSP RPT (FOLLOWUP)	M		0		PSAR 12.5.2.2.5-EXAMINE FIXED & MOVABLE AIR MONITORS

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 9

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-14-06	INSP RPT (FOLLOWUP)	P	8401	0		EP PLAN & STAFF AUGMENTATION NOT CONSISTENT WITH NUREG-0656
		INSP RPT (FOLLOWUP)	P	8426	0		
	83-14-14	INSP RPT (FOLLOWUP)	P	8401	0		CR, TBC, OSC & EOC NOT COMPLETED
		INSP RPT (FOLLOWUP)	P	8426	0		
	83-14-17	INSP RPT (FOLLOWUP)	P	8401	0		BACKUP LAB NOT FULLY EQUIPPED AND LICENSED
		INSP RPT (FOLLOWUP)	P	8426	0		
	83-14-21	INSP RPT (FOLLOWUP)	M	8401	0		AREA, PROCESS & EFFLUENT MONITORING SYSTEMS NOT INSTALLED
	83-14-22	INSP RPT (FOLLOWUP)	P	8401	0		NONRADIATION MONITORS NOT INSTALLED
		INSP RPT (FOLLOWUP)	P	8426	0		
	83-14-25	INSP RPT (FOLLOWUP)	P	8401	0		ERFDADS NOT INSTALLED
		INSP RPT (FOLLOWUP)	P	8426	0		

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

DOCKET ITEM-NUM	TYPE	FOLLOWUP	STATUS	ACTION DATE	BRANCH	REPORT NO.	DESCRIPTIVE TITLE
50528	83-14-29	INSP RPT (FOLLOWUP)	M	8401	0		PROCEDURES FOR PAS NOT WRITTEN
83-14-30	INSP RPT (FOLLOWUP)	M	8401	0			PROCEDURES FOR EFFLUENT MONITORS NOT WRITTEN
83-14-32	INSP RPT (FOLLOWUP)	P	8401	0			CARD READER SYSTEM NOT OPERATIONAL
	INSP RPT (FOLLOWUP)	P	8426	0			
83-17-02	INSP RPT (FOLLOWUP)	C		0			BIT SAFEND TO NOZZLE WELD REQUIRES RT
83-25-01	INSP RPT (FOLLOWUP)	R		0			FOLLOWUP OF RTD THERMOWELL - FAILURES
83-24-02	INSP RPT (FOLLOWUP)	0		0			PG 1.33 ITEMS APPARENTLY NOT COVERED BY PLANT PROCEDURES
83-30-01	INSP RPT (FOLLOWUP)	M		0			FUEL MLOG ISO PROBE-SAMPLE LINE PARA. 8.4
83-33-01	INSP RPT (FOLLOWUP)	M		0			CRACKS RMS INTERFACE REVIEW
83-34-01	INSP RPT (FOLLOWUP)	R		0			QUALIFICATION OF CONTAINMENT WATER LEVELS
83-34-03	INSP RPT (FOLLOWUP)	M		0			BREATHWING AIR SUPPLY SYSTEM FOR USE WITH AIRLINE-SUPPLIED MASKS & MOODS

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 3

PAGE 11

DOCKET ITEM#	NUM	TYPE	FOLLOWUP	FOLLOWUP	STATUS	ACTION DATE	DESCRIPTIVE TITLE
				REPORT NO.			
50526	83-19-03	INSP RPT (FOLLOWUP)	M	8405	0		DIESEL POWERED COMPRESSOR BEING CONSIDERED FOR AIR SUPPLY JACKUP
		INSP RPT (FOLLOWUP)	M	8431	0		60 CFM BREATHING AIR COMPRESSOR- PLANS FOR USEY SUPPORT FOR MOORS AND MASKS?
	83-41-03	INSP RPT (FOLLOWUP)	M		0		CONTROL ROOM RMS ANNUNCIATOR CAPABILITIES & PROCEDURES FOR ALARM RES
	83-41-04	INSP RPT (FOLLOWUP)	M		0		REVIEW UNMONITORED EFFLUENT RELEASE PATHWAYS SUCH AS TURBINE BUILDING
	84-01-01	INSP RPT (FOLLOWUP)	P	8426	0		GRAB SAMPLE CROSS REFERENCE TO SAFETY PRECAUTIONS
	84-04-02	INSP RPT (FOLLOWUP)	C		0		EVALUATION OF STANDARD CONDUIT ELLS
	84-07-01	INSP RPT (FOLLOWUP)	O		0		REEXAMINE COLD LICENSEE TRAINING RECORDS
	84-09-01	INSP RPT (FOLLOWUP)	M		0		DEVELOP QC PROCEDURES FOR GAMMA SPECTROSCOPY & LLD CRITERIA
	84-09-02	INSP RPT (FOLLOWUP)	M		0		TRAINING & PROFICIENCY OF GAMMA SPECTROSCOPY ANALYSTS (SEE PG 5)
	84-10-02	INSP RPT (FOLLOWUP)	C	8425	0		ACTIONS ON FP LOOSE BEAM CLAMPS AND WELDED STUDS
	84-10-04	INSP RPT (FOLLOWUP)	C		0		HVAC WALKDOWN - ADEQUATE FOR SEISMIC INPUT?

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 12

DOCKET ITEM-NUM	TYPE	FOLLOWUP	BRANCH	FOLLOWUP	STATUS	ACTION DATE	DESCRIPTIVE TITLE
				REPORT NO.			
50528	84-13-03	INSP RPT (FOLLOWUP)	M		0	3/1/84	RMS TASK FORCE MEETING & JOHN STEVENS RPT OF PROBLEMS PARA 7
	84-13-04	INSP RPT (FOLLOWUP)	M		0		CONTROL OF ACCESS TO SPENT FUEL TUBE BELLOW
	84-15-02	INSP RPT (FOLLOWUP)	C		0		ALL UNITS-UPDATE DOCUMENTATION TO REFLECT DESIGN CHANGE IN NUMBER OF RV MOLODOWN BOLTS
	84-18-04	INSP RPT (FOLLOWUP)	R		0	0884	SAFEGUARDS-ANOMALOUS NOISE LPBI PUMP
	84-23-01	INSP RPT (FOLLOWUP)	R		0	1084	THE I.C.S FEEDBACK OF OPR EXPERIENCE-PROCEDURE ISSUANCE
	84-23-02	INSP RPT (FOLLOWUP)	R		0	0884	OPERATOR REGUAL RE-EXAM
	84-28-03	INSP RPT (FOLLOWUP)	R		0	1084	TDAFNP MODIFICATIONS
	84-31-01	INSP RPT (FOLLOWUP)	M		0		VERIFY SAMPLE LINE FLOW RATES IN PREOP TEST RESULTS-SEE INSPECTION REPORT FOR SAMPLING PROCEDURES

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 13

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50520	IN-83-17	INFO NOTICE	0	0			DIESEL GENERATOR AUTO-START LOGIC
	IN-83-36	INFO NOTICE	8	0			RECOMMENDED REMOVAL OF CERTAIN SECURITY FEATURES FOR SAFETY ASSURANCE
	IN-84-34	INFO NOTICE	M	0			RESPIRATOR USERS WARNING-SCBA 4500 PSI LUXFER CYLINDERS
	IN-84-40	INFO NOTICE	M	0			EMERGENCY WORKER DOSES-VERIFY RECEIPT, PROPER DISTRIBUTION AND UNDERSTANDING
	IN-84-50	INFO NOTICE	M	0			CLARIFICATION OF SCOPE OF QA PROGRAMS F/TRANSPORT PACKAGES PURSUANT TO PT. 50, APPENDIX B
	IN-84-55	INFO NOTICE	M	0			IE IN 84-55 SEAL TABLE LEAKS AT PWR
	IN-84-56	INFO NOTICE	M	0			IE IN-84-56 RESPIRATOR USERS NOTICE FOR CERTAIN 5-MINUTE EMERGENCY ESCAPE SCBA
	IN-84-59	INFO NOTICE	M	0			IN 84-59 DELIBERATE CIRCUMVENTING OF STATION HEALTH PHYSICS PROCEDURES
	IN-84-60	INFO NOTICE	M	0			IN 84-60 FAILURE OF AIR-PURIFYING RESPIRATOR FILTERS TO MEET EFFICIENCY REQUIREMENT
	IN-84-61	INFO NOTICE	M	0			IN 84-61 OVEREXPOSURE OF DIVER IN PRESSURIZED WATER REACTOR (PWR) REFUELING CAVITY

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 14

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50526	PJ-08-24	OTHER	F	0			DETERMINE WHETHER DUCCOMMUN METAL IS ON APPROVED BIDDER'S LIST
	PJ-09-16	OTHER	0	0	REF		CONDUCT NATL CIRCULATION COOLDOWN TEST PRIOR TO FIRST REFUELING REF VAN BRUNT LTR 1/27/83
	PJ-82-02	OTHER	R	0			SER SECTION 7.2.3-CPC SOFTWARE PROCEDURES
	PJ-82-03	OTHER	0	0			SER SECTION 7.3.2.1-16C PROCEDURES AND TESTING (4 ITEMS)
	PJ-82-04	OTHER	0	0			SER SECTION 7.4.3-IE BULLETIN 79-27 PROCEDURES
	PJ-82-05	OTHER	0	0			SER SECTION 9.5.1-FIRE PROTECTION MODIFICATIONS (3 ITEMS)
	PJ-82-06	OTHER	0	0			SER SECTION 9.5.1.7-FIRE PROTECTION ADMIN CONTROLS & PROCEDURES
	PJ-82-07	OTHER	0	0			SER SECTION 13.1.2.3-TRAINING FOR OPS SUPERINTENDENT (ANSI/ANS 3.1)
	PJ-82-08	OTHER	0	0			SER SECTION 13.5.2-TRAINING OF OPERATORS ON OP/MAINT PROCEDURES
	PJ-82-09	OTHER	0	0			SER SECTION 15.3.9-ATMS PROCEDURES
	PJ-82-10	OTHER	0	0			SER APPENDIX C ITEM 4-44-STATION BLACKOUT PROCEDURES

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 15

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
--------	----------	------	--------------------	------------------------	--------	-------------	----------------------

50320	84-35-01	OTHER	S		0		VA ACCESS USE OF KEYCARDS
	84-35-02	OTHER	S		0		VA ACCESS-USE OF D&R BUTTON TO EXIT VITAL AREAS
	84-35-03	OTHER	S		0		INOPERATIVE CCTV CAMERAS
	84-35-04	OTHER	S		0		SCITY TERMINAL BECAME INOPERATIVE DURING CASCADING FIRE ALARMS
	84-35-05	OTHER	S		0		FAILURE TO PROVIDE TWO-CHANNELS FOR SECURITY COMMUNICATIONS

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 16

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50526	TI-12-03	TEMP INSTR (TI)	C	7906	0		VERIFY COMPLIANCE WITH ASME CERTIFICATION SYSTEM REQUIREMENTS
	TI-12-04	TEMP INSTR (TI)	C		0		INTERVIEWS WITH CRAFTSMEN AT CONSTRUCTION SITES
	TI-12-11	TEMP INSTR (TI)	C		0		INCREASE INSPECTION COVERAGE IN AREAS OF CONSTR. FOUND BY PAST EXPERIENCE TO NEED IMPROVEMENT
	TI-15-14	TEMP INSTR (TI)	0		0		SIS RESET PROCEDURES
	TI-15-29	TEMP INSTR (TI)	C		0		INSPECTION REQUIREMENTS FOR IE BULLETIN 79-14
	TI-15-36	TEMP INSTR (TI)	0		0		LICENSEE TRAINING STAFF MEMBERS MUST RECEIVE SRO LICENSES
	TI-15-64	TEMP INSTR (TI)	0		0		FOLLOWUP OF LICENSEE RESPONSE TO -- GL 83-28, REQUIRED ACTIONS BASED ON SALEM ATWS EVENTS
	TI-15-65	TEMP INSTR (TI)	0		0		TMI ACTION PLAN REQUIREMENT FOLLOWUP

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 17

DOCKET ITEM#	NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50526	81-04-02	INSP RPT (UNR)	C		0		COMPLIANCE W/ANS STRUCTURAL STEEL PREHEAT & RECORDS REQUIREMENTS
		INSP RPT (UNR)	C	8329	0		
		INSP RPT (UNR)	C	8436	0		CLOSE THIS ITEM ON ISSUANCE OF SSER SUPPL 6
	03-36-61	INSP RPT (UNR)	C	8404	0		CORROSION OF BURIED PIPE
		INSP RPT (UNR)	C	8410	0		
	84-10-01	INSP RPT (UNR)	C	8425	0		QUESTIONS ON VIKING SEISMIC ANALYSIS OF FP MGRS
	84-15-04	INSP RPT (UNR)	C		0		CE REVIEW OF TEST PROCEDURES AND CIPS IS NOT DOCUMENTED OR AUDITABLE
	84-15-05	INSP RPT (UNR)	C		0		ACCEPTANCE CRITERIA FOR RPT AT VARIANCE WITH DRMG, SPECIFICATION
	84-15-06	INSP RPT (UNR)	C		0		TECHNICAL CONCERN FOR SIMULTANEOUS SHIM CLEARANCE VERIFICATION
	84-15-07	INSP RPT (UNR)	C		0		LARGE VOID FOUND IN 18 REACTOR VESSEL SUPPORT PAD
	84-15-08	INSP RPT (UNR)	C		0		DISCREPANCY IN REMARK FOUND ON 1A REACTOR VESSEL SUPPORT PAD HOLES

10/02/80

REGION 3
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 18

DOCKET ITEM-NUM	TYPE	FOLLOWUP BRANCH REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	84-15-09 INSP RPT (UNR)	C	0		ERRORS ON CODE DATA SHEETS FOR 1A REACTOR VESSEL SUPPORT PAD REMORK
84-15-10	INSP RPT (UNR)	C	0		DEBRIS AT BASE OF RV SUPPORT COLUMN BASE
84-20-01	INSP RPT (UNR)	C	0		RECEIVING INSPECTION DID NOT HAVE CE PD OR SPECS FOR INSPECTION
84-25-02	INSP RPT (UNR)	C	8425	0	PIRE PROTECTION PIPING IS SUPPORTED BY CABLE TRAY SUPPORTS -VENIPY LOADS ME-E INC'UDED
84-28-02	INSP RPT (UNR)	R	0	1084	FAILURE TO FOLLOW PROCEDURE INVOLVING TRANSFER OF REACTOR COOLANT TO THE RMT

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 19

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	81-12- C	50.55E RPT	F	0	0130	50.55E-DIESEL GEN CONTROL CABINET WIRING=LACK OF REQ SEP BY COOPER ENERGY SERVICES (DER 81-51)	
	81-12- D	50.55E RPT	F	0	0130	50.55E-LOOSE ANTI-ROTATION PINS IN CONTAINMENT SPRAY AND LPBI PUMPS (DER 81-52)	
	81-12- E	50.55E RPT	F	0	0130	50.55E-MAIN CONTROL PANEL WIRING=LACK OF REQ SEP BY COMBIP CUSTOM LINE (DER 81-53)	
	83-04-06	50.55E RPT	0	0	0505	50.55E-APS STARTUP QC NOT QUALIFIED-DER 8320	
	84-01-C	50.55E RPT	C	0		50.55(E): CONTROL OF RETESTING ACTIVITIES DETERMINED NOT TO BE REPORTABLE	
	84-02-C	50.55E RPT	C	0		50.55(E): EXCESSIVE RUST 81 AND CH VALVES (ALL UNITS) FINAL RPT EXPECTED 6/21/84	
	84-03-C	50.55E RPT	C	0		50.55(E): FEEDWATER ISOLATION VALVE STUCK DURING TESTING - FINAL RPT EXPECTED 5/31/84	
	84-06-C	50.55E RPT	C	0		50.55(E): FOXBORO ALARM MODULE DEFECTS (ALL UNITS) - FINAL RPT EXPECTED 6/12/84	
	84-08-C	50.55E RPT	C	0		50.55(E): BARTON MDL 763 TRANSMITTS DO NOT MEET SPECS (ALL UNITS) FINAL RPT EXPECTED 5/18/84	
	84-10-C	50.55E RPT	C	0		50.55(E): FAILURE OF SINGLE ELEMENT RTD'S (ALL UNITS) FINAL REPORT EXPECTED 6/1/84	
	84-11-C	50.55E RPT	C	0		50.55(E): PUMP INSTRUMENTATION CONDUIT CONTAMINATED WITH CHLORIDES FINAL RPT EXPECTED 5/29/84	

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 20

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50520	84-12-C	50,55E RPT	C		0		50,55(E): ZONE III VIOLATIONS OF RCP 1A AND 8G #1 FINAL RPT EXPECTED 6/1/84
	84-13-C	50,55E RPT	C		0		50,55(E): HVAC ACCEPTANCE CRITERIA (ALL UNITS) - FINAL RPT EXPECTED 12/14/84
	84-15-C	50,55E RPT	C		0		50,55(E): UNDERSIZED PIPE RESTRAINT SUPPORT WELDS (ALL UNITS)-FINAL RPT EXP 8/3/84
	84-16-C	50,55E RPT	C		0		50,55(E): UNDERSIZED ESPAS RELAY CABINET BASEPLATS (ALL UNITS) FINAL RPT EXPECTED 6/29/84
	84-18-C	50,55E RPT	C		0		50,55(E): WIRING ERROR ON LPSI B PUMP SWITCH-FINAL RPT EXPECTED 6/12/84
	84-19-C	50,55E RPT	C		0		50,55(E): BLIND FLANGES IMPROPERLY INSTALLED (ALL UNITS)
	84-20-C	50,55E RPT	C		0		50,55(E): CONNECTING LINE TO 81A 380 DAMAGED
	84-21-C	50,55E RPT	C		0		50,55(E): ROSEMONT TRANSMITTERS LOOSE NUTS
	84-22-C	50,55E RPT	C		0		50,55(E): CEA SHROUD CONTAMINATED WITH OIL
	84-23-C	50,55E RPT	C		0		50,55(E): APW VALVE LOOSE SLEEVE PIN
	84-24-C	50,55E RPT	C		0		50,55(E): ALL UNITS - LOOSE BOLTS ON LIMITORQUE OPERATORS (ALL UNITS)

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 21

DOCKET	ITEM#NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50520	84-25-C	50,55E RPT	C		0		50,55(E): ALL UNITS - CONTAINMENT AIR SUPPLY REGISTERS BY TITUS HAVE FAILED WIRE
	84-26-C	50,55E RPT	C		0		50,55(E): CIRCUIT BRKN INTERLOCK MECHANISM WAS IMPROPERLY ASSEMBLED
	84-27-C	50,55E RPT	C		0		50,55(E): HVAC INSTRUMENTATION WERE MODIFIED AFTER FINAL ACCEPTANCE BY APS MAINTENANCE
	84-28-C	50,55E RPT	C		0		50,55(E): DIESEL FUEL LINES TOUCHING PENETRATION SLEEVE
	84-29-C	50,55E RPT	C		0		50,55(E): DIESEL GENERATOR HEAT EXCHANGERS HAVE SUBSTANCE BUILDUP
	84-30-C	50,55E RPT	C		0		50,55(E): DIESEL GENERATOR COOLERS HAVE PARTS THAT DONT MEET ASME REQUIREMENTS
	84-31-C	50,55E RPT	C		0		50,55(E): UNSEALED PENETRATIONS IN H800 BUILDING
	84-33-C	50,55E RPT	C		0		50,55(E): UNIT 1 MISSING WELD ON PIPE SUPPORT 1810Y0H011
	84-34-C	50,55E RPT	C		0		50,55(E): BIT BOLTING UNDERTORQUED/ WASHERS TOO SMALL
	84-35-C	50,55E RPT	C		0		50,55(E): POTENTIOMETERS ON PPS ARE DRIFTING-THIS AFFECTS SAFETY ANALYSIS
	84-36-C	50,55E RPT	C		0		50,55(E): TWO INCH WP81 VALVE STALL JUST OFF CLOSED POSITION-GUIDE HAS CHATTFR - RELATED TO DER 83-63

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 22

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
5052R	84-37-C	50,55E RPT	C		0		50,55(E)1 UNAUTHORIZED/UNQUALIFIED DUCT SEALANT USED ON HVAC DUCT-NOTE THIS WAS FOUND BY NRC IN 84-10
	84-39-C	50,55E RPT	C		0		50,55E1 LPBI PUMP HAS RUMBLING NOISES
	84-40-C	50,55E RPT	C		0		50,55E1 APF PUMP IMPELLORS HAVE MIC-DISCOVERED IN US-APPLICABLE TO ALL UNITS
	84-41-C	50,55E RPT	C		0		50,55(E)1 REG IV INSPECTION CARDINAL INDUSTRY PRODUCTS HAD INDETERMINATE QUALITY
	84-42-C	50,55E RPT	C		0		50,55E1 MOTOR OPERATOR TORQUE SWITCHES IMPROPERLY REPLACED NOT QUALIFIED
	84-43-C	50,55E RPT	C		0		50,55(E)1A 3 INCH BORG WARNER VALVE BIV MV 609 FAILED TO OPEN
	84-44-C	50,55E RPT	C		0		50,55E1 PART 21 REPORT ISSUED ON GAULIN CHARGING PUMP BLOCKS FATIGUE FAILURE
	84-45-C	50,55E RPT	C		0		50,55E1 KAMAN RADIATION MEASURING INSTRUMENTS ARE IMPROPERLY INSTALLE
	84-46-C	50,55E RPT	C		0		50,55E1 NOZZLE LOADS FROM 20 INCH PIPES IN REFUELING WATER TANK NOT PREVIOUSLY EVALUATED
	84-48-C	50,55E RPT	C		0		50,55E1 GAULING IN MBIV PLUGS DURING INSTALLATION CAUSE OPERATING LEVERS TO VIBRATE LOOSE
	84-49-C	50,55E RPT	C		0		50,55(E)1APF VIBRATES IN MINICIRC ALSO -REFER TO DER 84-23 FOR SIMILA PROBLE IN FULL FLOW RECIRC

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALC VERDE 1

PAGE 23

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	84-50-C	50.55E RPT	C		0		50.55E1 TURBINE DRIVEN AUX FEED PUM FAILED TO QUICK START FROM AMBIENT CONDITIONS
	84-51-C	50.55E RPT	C		0		50.55E2 MBIV MADE BY ANCHOR-DARLING FAILED TO CLOSE IN FIVE SECONDS.
	84-52-C	50.55E RPT	C		0		50.55(E)1BASE FLANGE RESISTOR ON ATMOSPHERIC STEAM DUMPS NOT STRONG ENOUGH TO SURVIVE A SEISMIC EVENT
	84-54-C	50.55E RPT	C		0		50.55(E)1BUMP ISOLATION VALVE COULD NOT BE ELECTRICALLY OPENED AFTER BEING MANUALLY CLOSED
	84-55-C	50.55E RPT	C		0		50.55(E)1UNQUALIFIED FOXBORD MODULES HAVE BEEN INSTALLED IN CLASS 1E ELECTRICAL CABINETS
	84-56-C	50.55E RPT	C		0		50.55(E)1HALON & CO2 SYS FIRE DAMPERS DO NOT FULLY CLOSE UNDER NORMAL OPERATING FLOW
	84-57-C	50.55E RPT	C		0		50.55(E)1CONTAINMENT ISOLATION VALVE IN RAD. WASTE DRAIN FAILED TO CLOSE IN 10 SECONDS.
	84-61-C	50.55E RPT	C		0		50.55(E)1POSSIBLE AUXILIARY PRESSURIZER SPRAY FAILURE-IE LOOP CHARGING VALVE STICKS OPEN
	84-62-C	50.55E RPT	C		0		50.55(E)1SAFEGRD SEQUENCING PRBLMS WITH SIGNALS TO THE HPBI AND 480 VOLT LOAD CTR BREAKERS
	84-63-C	50.55E RPT	C		0		50.55(E)1TARGET ROCK VALVE FAILED TO CLOSE ON SIT WHEN PRESSURE DROPPED TO 200 PSIG DURING A TEST
	84-64-C	50.55E RPT	C		0		50.55(E)1PIPE SUPPORT SNUBBERS FOUND LOCKED UP AFTER HOT PUMP TEST

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 1

PAGE 24

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50520	84-65-C	50.55E RPT	C		0		50.55E INSTRUMENT LEAD OUTER CABING LOCATED ON UPPER GUIDE STRUCTURE SPLIT EXPOSING CERAMIC INSULATOR
	84-66-C	50.55E RPT	C		0		50.55(E) DOWNCOMER FEEDWATER ISO VALVE FAILED TO COMPLETELY CLOSE UNDER DYNAMIC TEST CONDITIONS
	84-67-C	50.55E RPT	C		3		50.55(E) RED POSITION SWITCH FAILED TO CHANGE STATE W/THE VALVE CHANGE STATE USING REDUCED VOLTAGE
	84-68-C	50.55E RPT	C		0		50.55(E) ESSENTIAL CHILLER 'A' TEMP SWITCH TRIPS OFF AFTER 81AS FOL BY LOSS OF POWER-BLOCKING RESTART
	84-69-C	50.55E RPT	C		0		50.55(E) IRPS CHANNEL C, RELAY K-3 FAILED TO CLOSE DURING SAFEGUARDS TESTING

REGION 5
LICENSEE EVENT REPORT

PAGE 1

[illegible][illegible]

30529	61-08-21	SPECIAL RPT.	C	0	RV FOLLOWUP-PROBLEMS WITH CRANE TILTING DISC CHECK VALVES
	61-10-21	PART 21	C	0	PART 21-(PARSONS PEBLES) DIESEL GENERATOR SYSTEM DEFECT

01-10-21 PART 21

2

©

PART 21-(PARSONS PEEBLES)
DIESEL GENERATOR SYSTEM DEFECT

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 2

PAGE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	IS-79-18	IE BULLETIN	C	8231	0		SEISMIC ANAL OF AS-BUILT SAFETY RELATED PIPING SYSTEM - LATEST EFFECTIVE REVI 1/SUPI 2
	IS-79-21	IE BULLETIN	C	8308	0		TEMPERATURE EFFECTS ON LEVEL MEASUREMENTS
	IS-80-06	IE BULLETIN	C		0		ESP RESET CONTROLS - OL'S RESPOND BY JUL 1, 1980 - CP'S FOR INFO ONLY
	IS-80-09	IE BULLETIN	C		0		HYDRAMOTOR ACTUATOR DEFICIENCIES RESPOND BY JUL 8, 1980
	IS-80-12	IE BULLETIN	C	8111	0		DECAY HEAT REMOVAL SYS OPERABILITY
	IS-81-01	IE BULLETIN	C		0		SURVEILLANCE OF MECHANICAL SNUBBERS-INSPECT ACCESSABLE WITHIN 30 DAYS
	IS-81-02	IE BULLETIN	C	8234	0		POW INSULATION OR BLOCK VALVE FAILURES AGAINST DIFF PRESSURE 90 DAYS FOR CONST
		IE BULLETIN	C	8305	0		
	IS-82-02	IE BULLETIN	C	8420	0		DEGREATION OF THREADED FASTENERS IN PRIMARY PRESSURE BOUNDARIES
	IS-82-04	IE BULLETIN	C		0		DEFICIENCIES ON PRIMARY CONTAINMENT ELECTRICAL PENETRATION ASSEMBLIES
	IS-83-01	IE BULLETIN	0	8420	0		FAILURE OF REACTOR TRIP BREAKERS TO OPEN ON AUTO TRIP SIGNAL

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 2

PAGE 2

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	18-83-03	IE BULLETIN	C	8420	0		CHECK VALVE FAILURES IN RAW WATER COOLING SYSTEM OF 4G
	18-83-04	IE BULLETIN	C	8420	0		FAILURE OF UV TRIP FUNCTION OF REACTOR TRIP BREAKERS
	18-83-06	IE BULLETIN	C		0		HC MATERIALS SUPPLIED BY TUBE-LINE CORP OF LONG ISLAND CITY HOUSTON
	18-83-07	IE BULLETIN	C		0		APPARENTLY FRAUDULENT PRODUCTS SOLD BY RAY MILLER, INC
	18-83-08	IE BULLETIN	C		0		C/B'S WITH UV TRIP IN SAFETY RELATED SYSTEMS OTHER THAN REACTOR TRIP SYSTEM
	18-84-02	IE BULLETIN	0		0		FAILURE OF GE TYPE MPA RELAYS USED IN CLASS 1E SAFETY SYSTEMS

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 2

PAGE 3

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	IC-79-21	IE CIRCULAR	C	8231	0		
	IC-80-01	IE CIRCULAR	C	8308	0		GE INDUCTION RELAYS
	IC-80-05	IE CIRCULAR	C	8308	0		EMERG DIESEL GEN LUBE OIL ADDITION AND ONSITE SUPPLY
	IC-80-09	IE CIRCULAR	0	8308	0		PROBLEMS WITH PLANT INTERNAL COMMUNICATIONS SYSTEMS
	IC-80-10	IE CIRCULAR	C	8308	0		FAILURE TO MAINTAIN ENVIRONMENTAL QUALIFICATION OF EQUIPMENT
		IE CIRCULAR	C	8420	0		
	IC-80-14	IE CIRCULAR	C	8311	0		RADIOACTIVE CONTAMINATION OF PLANT DEMIN. WATER SYSTEM
	IC-81-02	IE CIRCULAR	0		0		PERFORMANCE OF NRC LICENSED INDIVIDUALS WHILE ON DUTY
	IC-81-03	IE CIRCULAR	0	8420	0		INOP SEISMIC INSTRUMENTATION
	IC-81-04	IE CIRCULAR	0		0		ROLE OF STA'S & IMPORTANCE OF LER'S
	IC-81-10	IE CIRCULAR	0	8420	0		STEAM VOIDING IN RCS DURING COOLDOWN

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 2

PAGE 4

[illegible]

TYPE

50829 IC-01-14 IE CIRCULAR C 0311 0
EVALUATE MSIV PROGRAMS &
PROPOSE CHANGES TO MINIMIZE
PROBLEMS

EVALUATE MSIV PROGRAMS &

PROPOSE CHANGES TO MINIMIZE PROBLEMS

PROBLEMS

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 2

DOCKET ITEM#	NUM	TYPE	FOLLOWUP	STATUS	ACTION DATE	REPORT NO.	BRANCH	REPORT NO.	DESCRIPTIVE	TITLE
--------------	-----	------	----------	--------	-------------	------------	--------	------------	-------------	-------

50529	84-08-04	INSP RPT (DEV)	C	0					DUCT SEALANT NOT QUALIFIED	
-------	----------	----------------	---	---	--	--	--	--	----------------------------	--

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 2

PAGE 6

DO-KEY	ITEM-NUM	TYPE	FOLLOWUP	BRANCH	REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE	TITLE
50529	64-04-01	INSP RPT (ENF)	C			0		CABLE BEND RADIUS WRONG	
	64-08-02	INSP RPT (ENF)	C			0		IMPROPER HVAC BOLTING WELDING SHIMMING	
	64-18-03	INSP RPT (ENF)	R			0	0884	NONCOMPLIANCE-IMPROPER DRAWING CONTROL IN CONTROL ROOM	

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 2

PAGE 7

DOCKET ITEM#	NUM	TYPE	FOLLOWUP	BRANCH	FOLLOWUP	REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE	TITLE
50529	84-04-02	INSP RPT (FOLLOWUP)	C				0		FACTORY EL RADIUS FOR CABLE	
84-06-01	INSP RPT (FOLLOWUP)	C					0		MVAC CRAFT TRAINING REQUIRED?	
84-10-01	INSP RPT (FOLLOWUP)	M					0		CONTROL OF ACCESS TO SPENT FUEL TUBE BELLOMS	

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 2

DOCKET	ITEM-NUM	TYPE	FOLLOWUP	FOLLOWUP	STATUS	ACTION DATE	DESCRIPTIVE
			BRANCH	REPORT NO.			TITLE
50529	IN-92-05	INFO NOTICE	S		0		DRUG RELATED INCIDENTS
	IN-82-07	INFO NOTICE	S		0		SCREENING OF ONSITE PERSONNEL
	IN-83-27	INFO NOTICE	S		0		OPERATIONAL RESPONSE TO EVENTS CONCERNING DELIBERATE ACTS AGAINST PLANT (COR W/S & O)
	IN-83-28	INFO NOTICE	S		0		CRITERIA FOR GENERAL EMERGENCY PROTECTIVE ACTION RECOMMENDATIONS
	IN-83-36	INFO NOTICE	S		0		RECOMMENDED REMOVAL OF CERTAIN SECURITY FEATURES FOR SAFETY ASSURANCE
	IN-84-07	INFO NOTICE	S		0		DESIGN BASIS THREAT AND REVIEW OF VEHICULAR ACCESS CONTROL
	IN-84-34	INFO NOTICE	M		0		RESPIRATOR USERS WARNING-SCBA 4500 PSI LUXFER CYLINDERS
	IN-84-40	INFO NOTICE	M		0		EMERGENCY WORKER D0828-VERIFY RECEIPT, PROPER DISTRIBUTION AND UNDERSTANDING
	IN-84-50	INFO NOTICE	M		0		CLARIFICATION OF SCOPE OF QA PROGRAMS P/TRANSPORT PACKAGES PURSUANT TO PT. 50, APPENDIX 8

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 2

PAGE 9

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
90929	TI-00-01	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESPONSE TO IE BULLETIN 79-15
	TI-00-05	TEMP INSTR (TI)	C		0		INSTRUCTIONS FOR VERIFICATION OF TMI ACTION PLAN=LICENSEE ACTIONS
	TI-12-03	TEMP INSTR (TI)	C	7906	0		VERIFY COMPLIANCE WITH ASME CERTIFICATION SYSTEM REQUIREMENTS
	TI-13-01	TEMP INSTR (TI)	0		0		TRANSFER OF SRP REVIEW FROM NRR TO IE
	TI-15-27	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESPONSE TO IE BULLETIN 79-02 (ANCHOR BOLTS)
	TI-15-28	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESP TO IES 7902, REV 1
	TI-15-29	TEMP INSTR (TI)	C		0		INSPECTION REQUIREMENTS FOR IE BULLETIN 79-14
	TI-15-44	TEMP INSTR (TI)	C		0		TMI ACTION PLAN INSPECT RGHTS HP & EMERGENCY PLANNING-REV, 2
	TI-15-53	TEMP INSTR (TI)	C		0		NUREG-0737 INSPECTION RGHTS FOR SYSTEM RGHTS
	TI-15-54	TEMP INSTR (TI)	C		0		I&E RESPONSIBILITY FOR REVIEW OF TMI SERIES
	TI-15-57	TEMP INSTR (TI)	C		0		0737 INSPECTION LISTING FOR EMERGENCY PROCEDURES=DUE EARLY 82

PAGE 10

TI-15-64	TEMP INSTR (VI)	0	0	INSPECTION FOLLOWUP BASED ON SALEM ATMB EVENTS

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 2

PAGE 11

DOCKET ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
-----------------	------	--------------------	------------------------	--------	-------------	----------------------

50529	84-08-03 INSP RPT (UNR)	C		0		DUCT SEALANT ON GASKETED JOINT
84-12-11	INSP RPT (UNR)	C		0		UGS REWORK PROCEDURE CONTAINS DIMENSION INCONSISTENT WITH DRUGS
84-12-01	INSP RPT (UNR)	C		0		SEE 50-528/84-20-01

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 2

PAGE 12

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	83-01-28	50.55E RPT	0	0	0228		50.55E-MVAC TEST PROCED DO NOT MEET ANSI N 510 DER 83-4
	83-04-06	50.55E RPT	0	0	0505		50.55E-AP8 STARTUP QC NOT QUALIFIED-DER 9320
	83-04-07	50.55E RPT	0	0	0505		50.55E-LP81 PUMP OPERATED W/SUCTION VALVE SHUT-DER 8321
	84-07-C	50.55E RPT	C	0			50.55(E): BORG WARNER VALVE STEM EXTENSIONS-REFERENCE PREVIOUS DER 80-21-FINL RPT EXP 6/1/84
	84-09-C	50.55E RPT	C	0			50.55(E): CAD WELDING FOR CATHODIC PROTECTION SYSTEM NOT DOCUMENTED FINAL RPT EXPECTED 5/4/84
	84-38-C	50.55E RPT	C	0			50.55E: PIPE SUPPORT INSTALLED INCORRECTLY
	84-53-C	50.55E RPT	C	0			50.55(E): MISSING NUTS & LOOSE BOLTS FOUND ON VALVES LOC IN CONTAINMENT & CHARGING SYSTEM
	84-59-C	50.55E RPT	C	0			50.55(E): CABLES ARE IN CONTACT WITH SHARP METAL EDGES OF FIRE STOPS ABOVE THE MCC.
	84-60-C	50.55E RPT	C	0			50.55(E): INCOMPATIBLE LUBRICANTS WERE USED ON 50 LIMITORQUE VALVES

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 3

PAGE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IB-79-14	IE BULLETIN	C	8231	0		SEISMIC ANAL OF AS-BUILT SAFETY RELATED PIPING SYSTEM - LATEST EFFECTIVE REV: 1/BUPI 2 TEMPERATURE EFFECTS ON LEVEL MEASUREMENTS
	IB-79-21	IE BULLETIN	C	8308	0		
	IB-80-06	IE BULLETIN	C		0		ESP RESET CONTROLS - OL'S RESPOND BY JUL 1, 1980 - CP'S FOR INFO ONLY
	IB-80-09	IE BULLETIN	C		0		HYDRAMOTOR ACTUATOR DEFICIENCIES RESPOND BY JUL 6, 1980
	IB-80-12	IE BULLETIN	C	8121	0		DECAY HEAT REMOVAL SYS OPERABILITY
	IB-81-01	IE BULLETIN	C		0		SURVEILLANCE OF MECHANICAL SHUBBERS-INSPECT ACCESSABLE WITHIN 30 DAYS
	IB-81-02	IE BULLETIN	C	8234	0		POW ISULATION OR BLOCK VALVE FAILURES AGAINST DIFF PRESSURE 90 DAYS FOR CONST
		IE BULLETIN	C	8305	0		
	IB-82-02	IE BULLETIN	C	8413	0		DEGRADATION OF THREADED FASTENERS IN PRIMARY PRESSURE BOUNDARIES
	IB-82-04	IE BULLETIN	C		0		DEFICIENCIES IN PRIMARY CONTAINMENT ELECTRICAL PENETRATION ASSEMBLIES
	IB-83-01	IE BULLETIN	0	8413	0		FAILURE OF REACTOR TRIP BREAKERS TO OPEN ON AUTO TRIP SIGNAL

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 3

PAGE 2

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	18-83-03	IE BULLETIN	C	8413	0		CHECK VALVE FAILURES IN RAW WATER COOLING SYSTEMS OF DG
	18-83-04	IE BULLETIN	C	8413	0		FAILURE OF UV TRIP FUNCTION OF REACTOR TRIP BREAKERS
	18-83-06	IE BULLETIN	C		0		HC MATERIALS SUPPLIED BY TUBE-LINE CORP OF LONG ISLAND CITY HOUSTON
	18-83-07	IE BULLETIN	C		0		APPARENTLY FRAUDULENT PRODUCTS SOLD BY RAY MILLER, INC
	18-83-08	IE BULLETIN	C		0		C/B'S WITH UV TRIP ON SAFETY RELATED SYSTEMS OTHER THAN REACTOR TRIP SYSTEM
	18-84-02	IE BULLETIN	0		0		FAILURE OF GE TYPE MFA RELAYS USED IN CLASS 1E SAFETY SYSTEMS

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 3

PAGE 3

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IC-79-21	IE CIRCULAR	C	8231	0		
	IC-80-01	IE CIRCULAR	C	8308	0		GE INDUCTION RELAYS
	IC-80-05	IE CIRCULAR	C	8308	0		EMERG DIESEL GEN LUBE OIL ADDITION AND ONSITE SUPPLY
	IC-80-09	IE CIRCULAR	0	8308	0		PROBLEMS WITH PLANT INTERNAL COMMUNICATIONS SYSTEMS
	IC-80-10	IE CIRCULAR	C	8308	0		FAILURE TO MAINTAIN ENVIRONMENTAL QUALIFICATION OF EQUIPMENT
		IE CIRCULAR	C	8413	0		
	IC-80-14	IE CIRCULAR	C	8311	0		RADIOACTIVE CONTAMINATION OF PLANT DEMIN. WATER SYSTEM
	IC-81-02	IE CIRCULAR	0		0		PERFORMANCE OF NRC LICENSED INDIVIDUALS WHILE ON DUTY
	IC-81-03	IE CIRCULAR	0	8413	0		INOP SEISMIC INSTRUMENTATION
	IC-81-04	IE CIRCULAR	0		0		ROLE OF STA'S & IMPORTANCE OF LER'S
	IC-81-10	IE CIRCULAR	0	8413	0		STEAM VOIDING IN RCS DURING COOLDOWN

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 3

PAGE 4

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IC-81-12	IE CIRCULAR	0		0		INADEQUATE PERIODIC BREAKER TEST PROCEDURES
	IC-81-14	IE CIRCULAR	C	8311	0		EVALUATE MSIV PROGRAMS & PROPOSE CHANGES TO MINIMIZE PROBLEMS
		IE CIRCULAR	C	8413	0		
	83-15-01	IE CIRCULAR	C	8337	0		EXCESSIVE TENSION ON TENDONS

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 3

PAGE 5

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
--------	----------	------	--------------------	------------------------	--------	-------------	----------------------

50530	84-03-01	INSP RPT (ENF)	C		0		STORAGE OF 480 V. MCC IN LEVEL D STORAGE
	84-07-14	INSP RPT (ENF)	C		0		REGEN HEAT EXCHANGER UPPER SUPPORT JAM NUT ADJUSTMENT & TORQUE
	84-07-17	INSP RPT (ENF)	C		0		CABLE REELS NOT TAGGED NONCONFORMING
	84-12-05	INSP RPT (ENF)	C	8425	0		IMPROPER ACCEPTANCE OF HONEYWELL INSTRUMENTS

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 3

PAGE 6

DOCKET ITEM#	NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	83-03-02	INSP RPT (FOLLOWUP)	C	8311	0	0303	WATER USED TO COOL STAINLESS STEEL MELOS
		INSP RPT (FOLLOWUP)	C	8317	0		
		INSP RPT (FOLLOWUP)	C	8329	0		
84-07-16	INSP RPT (FOLLOWUP)	C			0		REINSPECTION OF PIPE HANGERS AND SUPPORTS - UNIT 3

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 3

PAGE 7

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IN-82-05	INFO NOTICE	S		0		DRUG RELATED INCIDENTS
	IN-82-07	INFO NOTICE	S		0		SCREENING OF ONSITE PERSONNEL
	IN-83-27	INFO NOTICE	S		0		OPERATIONAL RESPONSE TO EVENTS CONCERNING DELIBERATE ACTS AGAINST PLANT (COR M/S & O)
	IN-83-28	INFO NOTICE	S		0		CRITERIA FOR GENERAL EMERGENCY PROTECTIVE ACTION RECOMMENDATIONS
	IN-83-36	INFO NOTICE	S		0		RECOMMENDED REMOVAL OF CERTAIN SECURITY FEATURES FOR SAFETY ASSURANCE
	IN-84-07	INFO NOTICE	S		0		DESIGN BASIS THREAT AND REVIEW OF VEHICULAR ACCESS CONTROL
	IN-84-34	INFO NOTICE	M		0		RESPIRATOR USERS WARNING-SCBA 4500 PSI LUXFER CYLINDERS
	IN-84-40	INFO NOTICE	M		0		EMERGENCY WORKER DOSES-VERIFY RECEIPT, PROPER DISTRIBUTION AND UNDERSTANDING
	IN-84-50	INFO NOTICE	M		0		CLARIFICATION OF SCOPE OF QA PROGRAMS F/TRANSPORT PACKAGES PURSUANT TO PT. 50, APPENDIX B

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 3

PAGE 6

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50550	08-03-10	OTHER	3		0		ADDITIONAL 3 MINES FOUND CUT (COMPUTER RM) ON 03/30/83 (PNC-V-88-18)

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 3

PAGE 4

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
5053Q	TI-00-01	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESPONSE TO IE BULLETIN 79-15
	TI-00-05	TEMP INSTR (TI)	C		0		INSTRUCTIONS FOR VERIFICATION OF TMI ACTION PLAN=LICENSEE ACTIONS
	TI-12-03	TEMP INSTR (TI)	C	7906	0		VERIFY COMPLIANCE WITH ASME CERTIFICATION SYSTEM REQUIREMENTS
	TI-15-27	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESPONSE TO IE BULLETIN 79-02 (ANCHOR BOLTS)
	TI-15-28	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESP TO IEB 7902, REV 1
	TI-15-29	TEMP INSTR (TI)	C		0		INSPECTION REQUIREMENTS FOR IE BULLETIN 79-14
	TI-15-44	TEMP INSTR (TI)	C		0		TMI ACTION PLAN INSPECT RQMTS HP & EMERGENCY PLANNING=REV. 2
	TI-15-53	TEMP INSTR (TI)	C		0		NUREG-0737 INSPECTION RQMTS FOR SYSTEM RQMTS
	TI-15-54	TEMP INSTR (TI)	C		0		ISE RESPONSIBILITY FOR REVIEW OF TMI SERIES
	TI-15-57	TEMP INSTR (TI)	C		0		0737 INSPECTION LISTING FOR EMERGENCY PROCEDURES=DUE EARLY 82
	TI-15-59	TEMP INSTR (TI)	C		0		0737 INSPECTION LISTING FOR MODS DUE 1/82

[illegible]

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

037 INSPECTION LISTING FOR
MODES DUE 7/62

YI-15-64	YRBD INSTR (Y)	0	0	INSPECTION FOLLOWUP BASED ON SALEM ATMS EVENTS

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 3

PAGE 11

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50830	82-09-02	INSP RPT (UNR)	C		0		FLARE LEVEL WELD
	84-07-13	INSP RPT (UNR)	C		0		VALVE SP81EV235 STUD THREAD ENGAGEMENT INTO BONNET
	84-09-01	INSP RPT (UNR)	C		0		SEE 30-320/84-20-01

10/02/84

REGION 5
OUTSTANDING ITEMS REPORT
ALL OPEN ITEMS (SORTED BY TYPE)
PALO VERDE 3

PAGE 12

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	83-01-28	50,55E RPT	0		0	0228	50,55E-HVAC TEST PROCED DO NOT MFCT ANSI N 510 DER 83-4
	83-04-06	50,55E RPT	0		0	0505	50,55E-APS STARTUP QC NOT QUALIFIED-DER 8320
	83-04-07	50,55E RPT	0		0	0505	50,55E-LPBI PUMP OPERATED W/SUCTION VALVE SHUT-DER 8321
	84-07-C	50,55E RPT	C		0		50,55(E)1 BORG WARNER VALVE STEM EXTENSIONS-REFERENCE PREVIOUS DER 80-21-FINL RPT EXP 6/1/84