

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)
SAN ONOFRE NUCLEAR GENERATING STATION, UNIT 2

DOCKET NUMBER (2)

0 5 0 0 0 B 16 11 1 OF 0 11

PAGE 13

TITLE (4)

FIRE PROTECTION PROGRAM DISCREPANCIES

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)	
07	24	84	84	041	00	07	25	84	UNIT 3	0 5 0 0 0 13 16 P	
THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 8: (Check one or more of the following) (11)											
OPERATING MODE (9)		20.402(a)			20.406(c)			50.73(a)(2)(iv)			73.71(b)
POWER LEVEL (10)		20.405(a)(1)(i)			50.36(e)(1)			50.73(a)(2)(v)			73.71(e)
0 10 0		20.405(a)(1)(ii)			50.36(e)(2)			50.73(a)(2)(vii)			Y OTHER (Specify in Abstract below and in Text, NRC Form 366A)
		20.405(a)(1)(iii)			50.73(a)(2)(i)			50.73(a)(2)(viii)(A)			LICENSE
		20.405(a)(1)(iv)			50.73(a)(2)(ii)			50.73(a)(2)(viii)(B)			CONDITION 2.G
		20.405(a)(1)(v)			50.73(a)(2)(iii)			50.73(a)(2)(ix)			

LICENSEE CONTACT FOR THIS LER (12)

NAME
J. G. HAYNES, STATION MANAGER

TELEPHONE NUMBER

AREA CODE

7 14 4 P 12 L 7 17 10 11

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFAC- Turer	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFAC- Turer	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

EXPECTED
SUBMISSION
DATE (15)MONTH DAY YEAR
| | |

YES (If yes, complete EXPECTED SUBMISSION DATE)

Y NO

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

As reported on July 24, 1984, pursuant to License Condition 2.G, our review associated with the updated Fire Hazards Analysis (FHA) resulted in the issuance of two Nonconformance Reports (NCRs) identifying discrepancies involving cable separation and fire wraps.

The conditions identified in these two NCRs constitute additional examples of deficiencies reported previously in LERs 84-001, 84-015, 84-024 and 84-030. Corrective actions described in LER 84-024 will be implemented. Compensatory fire watches have been established in the affected areas.

This report is also submitted to fulfill the requirements of License Condition 2.G relating to License Condition 2.C(14)a and 2.C.(12)a of Operating Licenses NPF-10 and NPF-15 for Units 2 and 3, respectively.

8408060039 840725
PDR ADDCK 05000361
S PDR