

Commonwealth Edison Company
Braidwood Generating Station
Route #1, Box 84
Braceville, IL 60407-9619
Tel 815-458-2801



November 27, 1995
BW/95-0115

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: ComEd Braidwood Station Unit 1 Fifth Refuel Outage
Steam Generator Inservice Inspection Report
Docket No. STN 50-456


References: (1) Letter BW/95-0110 from ComEd's Braidwood Station to
U.S. Nuclear Regulatory Commission, Category C-3 Report per
Specification 4.4.5.5.c dated November 13, 1995

Gentlemen:

In the "Corrective Measures to Prevent Recurrence" section of the referenced letter, ComEd indicated it will not continue the Secondary Side Boric Acid program for Braidwood Unit 1 Cycle 6. Since this time, ComEd has reversed this decision. Braidwood Unit 1 will continue the Secondary Side Boric Acid program at least until its mid-cycle outage. This program will include boric acid soaks during unit startup along with on-line addition during normal power operation. ComEd's evaluation of the Secondary Side Boric Acid program during Unit 1 Cycle 5 determined that the program is not detrimental to the Steam Generator tubes.

Please direct any questions regarding this decision to Doug Huston, Braidwood Licensing Supervisor, (815) 458-2801, extension 2511.

Very truly yours,


T. J. Tulon
Station Manager
Braidwood Nuclear Station

TJT/DG/dla

c:\corresp\zcsteno\bwdlettrs.doc

cc: Sr. Resident Inspector - Braidwood
Braidwood Project Manager, NRR
Regional Administrator, Region III

010113

9512010256 951127
PDR ADDCK 05000456
PDR

A Unicom Company

A047
1/0