

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Callaway Plant Unit 1										DOCKET NUMBER (2) 0 5 0 0 0 4 8 3 1										PAGE (3) 1 OF 02	
TITLE (4) Inadvertent Engineered Safety Features Actuation																					
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)											
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES			DOCKET NUMBER(S)									
0	8	2	0	8	4	8	4	0	3	2	0	0	0	9	1	9	8	4	0 5 0 0 0		
OPERATING MODE (9) 4		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)																			
POWER LEVEL (10) 0 0 0		20.402(b)				20.405(c)				<input checked="" type="checkbox"/> 50.73(a)(2)(iv)				73.71(b)							
		20.405(a)(1)(i)				50.36(c)(1)				50.73(a)(2)(v)				73.71(c)							
		20.405(a)(1)(ii)				50.36(c)(2)				50.73(a)(2)(vi)				OTHER (Specify in Abstract below and in Text, NRC Form 366A)							
		20.405(a)(1)(iii)				50.73(a)(2)(i)				50.73(a)(2)(viii)(A)											
		20.405(a)(1)(iv)				50.73(a)(2)(ii)				50.73(a)(2)(viii)(B)											
		20.405(a)(1)(v)				50.73(a)(2)(iii)				50.73(a)(2)(ix)											
LICENSEE CONTACT FOR THIS LER (12)																					
NAME Charles D. Naslund - Superintendent, I&C										TELEPHONE NUMBER AREA CODE 3 1 4 6 7 1 6 - 1 8 5 1 0 0											
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																					
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC											
X	J E R I J X	C 1 5 6 1 0	N																		
SUPPLEMENTAL REPORT EXPECTED (14)																					
YES (If yes, complete EXPECTED SUBMISSION DATE)										<input checked="" type="checkbox"/> NO		EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR					

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

At 0246 CDT on 8/20/84, the following Engineered Safety Features (ESF) were actuated while the plant was in Mode 4: Control Room Ventilation Isolation Actuation, Containment Purge Isolation Actuation, and Fuel Building Ventilation Isolation Actuation. Upon investigation it was determined that a 15V DC power supply in an ESFAS cabinet had failed. This power supply provides power to ESFAS Cabinet Channel 1 logic circuits and its failure resulted in a fail safe actuation of the Engineered Safety Features mentioned above.

The defective power supply was replaced and the ESFAS train was returned to normal at 1020. The cause of the power supply failure is unknown. No previous failures of this power supply have been recorded; therefore, this incident is considered an isolated case.

There was no damage to plant equipment or release of radioactivity as a result of this incident. At no time did this event pose a threat to the public health or safety.

8409280268 840919
PDR ADDOCK 05000483
S PDR

IE22
1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1) Callaway Plant Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 4 8 3 8 4 —	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		0 3	2	— 0 0	0	2	OF 0 2

TEXT (If more space is required, use additional NRC Form 365A's) (17)

At 0246 CDT on 8/20/84, a Control Room Ventilation Isolation Signal (CRVIS), Containment Purge Isolation Signal (CPIS), and Fuel Building Ventilation Isolation Signal (FBVIS) were received and actuations initiated while the plant was in Mode 4. The Engineered Safety Features Actuation System (ESFAS) panel indicated a loss of 15V DC power. Upon investigation it was determined that a 15V DC power supply in ESFAS cabinet SA-036D had failed. This power supply provides power to ESFAS Cabinet Channel 1 logic circuits and its failure resulted in a fail safe actuation of the above mentioned safeguards. The only ESF actuations affected by the loss of this power supply are those mentioned above and the ESF equipment functioned properly upon actuation.

The defective power supply was replaced with an identical power supply and the ESFAS train was returned to normal at 1020. The cause of the failure is unknown. The 15V DC power supply (Part No. KYE-1900-1) was supplied by Consolidated Controls Corporation. No previous failures of this power supply have been recorded so this incident is therefore considered an isolated case.

There was no damage to plant equipment or release of radioactivity as a result of this incident. At no time did this event pose a threat to the public health or safety.

Previous occurrences: none

UNION ELECTRIC COMPANY
CALLAWAY PLANT

MAILING ADDRESS:
P. O. BOX 620
FULTON, MO. 65251

September 19, 1984


U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

ULNRC-930

DOCKET NUMBER 50-483
CALLAWAY PLANT UNIT 1
FACILITY OPERATING LICENSE NPF-25
LICENSEE EVENT REPORT 84-032-00
INADVERTENT ENGINEERED SAFETY FEATURES ACTUATION

Gentlemen:

The enclosed Licensee Event Report is submitted pursuant
to 10 CFR 50.73(a)(2)(iv) concerning an inadvertent Engineered Safety
Feature actuation.



S. E. Miltenberger
Manager, Callaway Plant

CDN *San* *guk*
CDN/WRR/JWK/drs
Enclosure

cc: Distribution attached

IE22
1/1

cc distribution for ULNRC-930

Mr. James G. Keppler
Regional Administrator
Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

American Nuclear Insurers
c/o Dottie Sherman, Library
The Exchange Suite 245
270 Farmington Avenue
Farmington, CT 06032

Records Center
Institute of Nuclear Power Operations
Suite 1500
1100 Circle 75 Parkway
Atlanta, GA 30339

NRC Resident Inspector
Missouri Public Service Commission
D. F. Schnell
J. F. McLaughlin
J. E. Davis (Z40LER)
D. W. Capone
F. D. Field
R. L. Powers
A. C. Passwater/D. E. Shafer/D. J. Walker
G. A. Hughes
W. R. Robinson (QA Record)
C. D. Naslund
A. P. Neuhalphen
R. A. McAleenan
L. K. Robertson (470)(NSRB)
Merlin Williams, Wolf Creek
SEM Chrono
3456-0021.6
3456-0260
Z40ULNRC
G56.37
N. Date