

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401  
400 Chestnut Street Tower II

34 SEP 17 1984  
September 12, 1984  
11:09

BLRD-50-438/84-29

U.S. Nuclear Regulatory Commission  
Region II  
Attn: Mr. James P. O'Reilly, Regional Administrator  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30323

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNIT 1 - REQUIRED 1-INCH SEPARATION OF  
FLEX CONDUIT NOT MAINTAINED BLRD-50-438/84-29 - SECOND INTERIM REPORT


The subject deficiency was initially reported to NRC-OIE Inspector Ross Butcher on April 3, 1984 in accordance with 10 CFR 50.55(e) as NCR 2995. This was followed by our interim report dated April 30, 1984. Please note that in our first interim report TVA indicated that this condition applied to both units 1 and 2. Upon further investigation it has been determined that only unit 1 is affected. Please revise your records accordingly. Below is our second interim report. We expect to submit our next report on or about December 7, 1984.

TVA is still in the process of determining corrective action and action required to prevent recurrence of this deficiency.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

  
L. M. Mills, Manager  
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

8409280479 840912  
PDR ADOCK 05000438  
S PDR

An Equal Opportunity Employer

OFFICIAL COPY

1227  
1/0