

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) BYRON, UNIT 1										DOCKET NUMBER (2) 0 5 0 0 0 4 5 4										PAGE 3 1 OF 0 2	
TITLE (4) MISSED SURVEILLANCE																					
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)											
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES			DOCKET NUMBER(S)									
0 1	2 8	8 5	8 5	0 1 9	0 1	0 2	2 7	8 5				0 5 0 0 0									
THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § Check one or more of the following: (11)																					
OPERATING MODE (9)		3		26.405a(1)(b)		26.405a(1)(c)		26.405a(1)(d)		26.405a(1)(e)		26.405a(1)(f)		26.405a(1)(g)							
POWER LEVEL (10)		0 10 0		26.405a(1)(b)		26.405a(1)(c)		26.405a(1)(d)		26.405a(1)(e)		26.405a(1)(f)		26.405a(1)(g)							
				26.405a(1)(b)		26.405a(1)(c)		26.405a(1)(d)		26.405a(1)(e)		26.405a(1)(f)		26.405a(1)(g)							
				26.405a(1)(b)		26.405a(1)(c)		26.405a(1)(d)		26.405a(1)(e)		26.405a(1)(f)		26.405a(1)(g)							
				26.405a(1)(b)		26.405a(1)(c)		26.405a(1)(d)		26.405a(1)(e)		26.405a(1)(f)		26.405a(1)(g)							
LICENSEE CONTACT FOR THIS LER (12)												TELEPHONE NUMBER									
NAME Raymond Choinard										(Ext. 249)		AREA CODE		8 1 5		2 3 4 1 - 1 5 4 1 4 1					
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																					
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE						
A	I L	M O N	G 2 9 0	N																	
SUPPLEMENTAL REPORT EXPECTED (14)												EXPECTED SUBMISSION DATE (15)		MONTH		DAY		YEAR			
YES IF THE COMPANY EXPECTED SUBMISSION DATE: X NO																					
ABSTRACT (Limit to 1000 words. If approximately 1000 words, please indicate "see 15")																					

The monthly surveillance of the Containment Isolation - Containment Radioactivity - High Radiation Monitors was not performed within the required interval per Technical Specifications. Corrective action was taken by entering the Action Statement of the Limiting Condition for Operation. No operator error was involved.

8503140122 850227
PDR ADOCK 05000454
S PDR

EE22
111

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVAL ONE NO 3180-0104

EXPIRES 8/31/95

FACILITY NAME (1)

BYRON, UNIT 1

DOCKET NUMBER (2)

0 5 0 0 0 4 5 4

LER NUMBER (8)

PAGE (3)

YEAR

SEQUENTIAL

REVISION

NUMBER

NUMBER

8 5

-

0 1 9

-

0 1

d

2

OF

0

2

TEXT (If more space is required, use additional NRC Form 206A-1/17)

While in Mode 3 prior to initial criticality, the monthly surveillance of the Containment Isolation - Containment Radioactivity - High Radiation Monitors was not performed within the required interval per Technical Specifications. The surveillance fell outside the required interval at 0000 hours on January 28, 1985. The Action Statement of the Limiting Condition for Operation was entered into on January 28, 1985. Later that day the Action Statement was exited when the surveillance had been successfully completed. The Action Statement required the containment purge valves to be maintained closed. There was no effect to plant or public safety since the reactor was shutdown with a boron concentration of greater than 2000 ppm and since the reactor had not achieved initial criticality.

The Technical Staff engineer responsible for performance of the surveillance failed to follow established administrative procedures. Disciplinary action was taken with the individual. Also technical staff group leaders were reminded of their responsibility to ensure surveillances are completed within the required time interval.

There have been three other similar occurrences of exceeded surveillance intervals.

Refer to LERS:

85-003-00

85-005-00, and

85-012-00

This revision is being provided to correct a typographical error in the stated mode shown in the text of the original LER.



Commonwealth Edison
Byron Nuclear Station
4450 North German Church Road
Byron, Illinois 61010

February 27, 1985

LTR: BYRON 85-0308

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Dear Sir:

The enclosed Licensee Event Report from Byron Generating Station is being transmitted to you as a Supplemental Report to LER 85-019-00.

This report is number 85-019-01, Docket No. 50-454.

Very truly yours,

R. E. Querio
Station Superintendent
Byron Nuclear Power Station

REQ/vda

Enclosure: Licensee Event Report No. 85-019-01

cc: J. G. Koppler, NRC Region III Administrator
J. Hinc., NRC Resident Inspector
INPO Record Center
CFEO Distribution List

IE22
11