

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Dresden Nuclear Power Station										DOCKET NUMBER (2) 0 5 0 0 0 2 3 7 1					PAGE (3) OF 0 2	
TITLE (4) Missed Refueling Surveillances																
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)						
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES				DOCKET NUMBER(S)			
0 2	1 5	8 5	8 5	0 0 7	0 0	0 3	1 4	8 5	N/A				0 5 0 0 0			
OPERATING MODE (9) N			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 8: (Check one or more of the following) (11)													
POWER LEVEL (10) 0 0 0		20.402(b)				20.406(e)				80.73(a)(2)(iv)				73.71(b)		
		20.406(a)(1)(i)				80.38(e)(1)				80.73(a)(2)(v)				73.71(e)		
		20.406(a)(1)(ii)				80.38(e)(2)				80.73(a)(2)(vii)				OTHER (Specify in Abstract below and in Text, NRC Form 366A)		
		20.406(a)(1)(iii)				80.73(a)(2)(i)				80.73(a)(2)(viii)(A)						
		20.406(a)(1)(iv)				80.73(a)(2)(ii)				80.73(a)(2)(viii)(B)						
		20.406(a)(1)(v)				80.73(a)(2)(iii)				80.73(a)(2)(ix)						
LICENSEE CONTACT FOR THIS LER (12)																
NAME Kevin Sykes										TELEPHONE NUMBER (X-523) 8 1 5 9 4 2 7 2 9 2 0						
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																
CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPROS		CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPROS						
A				N												
SUPPLEMENTAL REPORT EXPECTED (14)												EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR
YES (If yes, complete EXPECTED SUBMISSION DATE)												X NO				

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

During normal refueling outage routine weekly Operating Surveillances DOS 700-1, 2, 3 and 4 were not completed on a weekly basis as required by Technical Specifications. The surveillances were not completed for one weekly period. The safety significance was minimal as the reactor was in refueling and the surveillances missed were SRM/IRM rod blocks. With the reactor in refuel only one rod can be out of the core at any given period. The event was caused by Operator error as the surveillances were overlooked on the weekly schedule.

8503250384 850314  
PDR ADOCK 05000237  
S PDR

IE22, 11

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
Dresden Nuclear Power Station, Unit 2	0 5 0 0 0 2 3 7 8 5	—	0 0 7	—	0 0	0 2 OF 0 2

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Weekly Operating Surveillances 700-1, SRM Inoperable Rod Block Test, 700-2, IRM Downscale Rod Block Functional Test, 700-3, SRM Detector Position Rod Block Functional Test, and 700-4, IRM Detector Position Rod Block Functional Test, were not completed the week of 2/3/85.

Surveillances 700-2, 3 and 4 fulfill rod block test requirements 5, 10 and 6 listed in Table 4.2.1 of the Technical Specifications. The required frequency for these tests is once every 7 days. These surveillances were previously conducted on 2/1/85 and were not completed again until 2/15/85, which constitutes a Technical Specification violation.

This error is attributable to miscommunication. The surveillances which were done 2/1/85 were mistakenly reported to have been done 2/5/85. Under Technical Specification guidelines, the surveillances were then due for next completion the week of 2/10/85. Therefore they were not done the week of 2/3/85.

As a corrective action, the individual responsible for the recording error was made aware of his mistake. In addition, a module on adherence to surveillance schedules will be added to the Operator training program. The safety significance is minimal because the reactor was in the refuel mode, obviating the need for IRM and SRM rod blocks.

At Dresden, surveillance intervals have been exceeded infrequently in past years; however this is a first reported occurrence for missed refueling surveillances.



**Commonwealth Edison**  
Dresden Nuclear Power Station  
R.R. #1  
Morris, Illinois 60450  
Telephone 815/942-2920

March 14, 1985

DJS Ltr #85-295

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Licensee Event Report #85-007-0, Docket #050237 is being submitted as required by Technical Specification 6.6, NUREG 1022 and 10 CFR 50.73 (a)(2)(i)(B).

D.C. Scott  
Station Superintendent  
Dresden Nuclear Power Station

DJS/kjl

Enclosure

cc: J.G. Keppler, Regional Administrator, Region III  
File/NRC  
File/Numerical

IE22  
1/1