

EXHIBIT A

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

FACILITY

ACTIVITY

PERSONNEL EXPOSURES

PERSONNEL INJURIES

LOSS OF OR DAMAGE TO FACILITY

PUBLICITY

NAME OF PREPARER: Don Lomax, Plant Licensing Supervisor

PHONE: (501) 964-3100

8412060705 841123
PDR ADOCK 05000368
S PDR

IE22
11

LICENSEE EVENT REPORT

EXHIBIT A

LER No. 50-368/83-041/03X-1

Occurrence Date: 08/31/83

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (Continued)

This investigation yielded no concrete conclusions as to the cause of the sensor drift. It is suspected that high connector resistance and/or signal shield grounding was related to the cause. No further corrective action is warranted at this time as no subsequent sensor drift has occurred.



ARKANSAS POWER & LIGHT COMPANY

POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

November 23, 1984

2CAN118409


U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Licensee Event Report
No. 83-041/03X-1

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9.b, attached is the subject report concerning problems with the Core Protection Calculator Channel 'D'. This is a revision to a previous submittal dated October 3, 1983.

Very truly yours,



J. Ted Enos
Manager, Licensing

JTE:R13:ac

Attachment

cc: Mr. Norman M. Haller, Director
Office of Management & Program Analysis
U. S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. Richard C. DeYoung
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, DC 20555

IE22
1/1