

WOLF CREEK

NUCLEAR OPERATING CORPORATION

Otto L. Maynard
Vice President Plant Operations

February 29, 1996

WO 96-0032

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-137
Washington, D. C. 20555


Subject: Docket No. 50-482: Licensee Event Report 96-002-00

Gentlemen:

The attached Licensee Event Report is being submitted pursuant to 10 CFR 50.73 (a)(2)(vi) concerning the inoperability of the Essential Service Water System (ESWS) A train due to the inability of the existing ESWS design to meet the original plant design basis for the environmental conditions which existed on January 30, 1996. The accumulation of frazil ice on the Wolf Creek Generating Station ESWS trash racks rendered the A ESWS train inoperable on January 30, 1996. The original ESWS design did not contain sufficient warming line flow to prevent the accumulation of frazil ice.

If you should have any questions regarding this submittal, please contact me at (316) 364-8831 extension 4450, or William M. Lindsay at extension 8760.

Very truly yours,


Otto L. Maynard

OLM/jad

Attachment

cc: L. J. Callan (NRC), w/a
W. D. Johnson (NRC), w/a
J. F. Ringwald (NRC), w/a
J. C. Stone (NRC), w/a

9603110619 960229
PDR ADOCK 05000482
S PDR

JE32.1