



Nebraska Public Power District

GENERAL OFFICE
P.O. BOX 499, COLUMBUS, NEBRASKA 68602-0499
TELEPHONE (402) 564-8561
FAX (402) 563-5551

NSD920305
March 16, 1992

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

Subject: Section XI Code Reports
Cooper Nuclear Station
NRC Docket No. 50-298, DPR-46

Reference: ASME Section XI, 1980 Edition, Winter 1981 Addenda,
Article IWA-6000

Gentlemen:

Pursuant to the reporting requirements of the above reference, the subject code reports are submitted as enclosures to this letter for review by your office.

Enclosure 1, "Owner's Data Report for Inservice Inspections" (Form NIS-1), documents Inservice Inspection activities conducted at Cooper Nuclear Station during refueling outage number fourteen (Fall 1991 Refueling Outage). Enclosure 2, "Owner's Report for Repairs and Replacements" (Form NIS-2), documents repair and replacement activities conducted during operating cycle number fourteen and refueling outage number fourteen.

This letter also serves to report an inadvertent omission on the NIS-2 report which was submitted via letter CNSS897475, from G. A. Trevors to U.S. NRC, dated September 13, 1989. Code Case N-416 was invoked during replacement activities implemented via Design Change 89-023 (Maintenance Work Request 89-1688). Reference to Code Case N-416 was inadvertently omitted from the NIS-2 form which documented this replacement activity (sheet 39 - replacement of orifices HPCI-RO-132, HPCI-RO-133, and HPCI-RO134).

Please contact J. R. Flaherty, Engineering Manager at Cooper Nuclear Station, if you should require additional information regarding this matter.

Sincerely,

G. R. Horn
Nuclear Power Group Manager

GRH/dnm
Enclosures

cc: Regional Administrator
NRC Region IV
Arlington, TX

NRC Resident Inspector
Cooper Nuclear Station

9203230267 920316
PDR ADDCK 05000298
Q PDR

A047
1/1