

GULF STATES UTILITIES COMPANY

RIVER BEND STATION

POST OFFICE BOX 220

ST. FRANCISVILLE, LOUISIANA 70775

AREA CODE 504

635-6094

346-8651




December 3, 1984

RBG-19637

File Nos. G9.5, G9.25.1.1

Mr. Robert D. Martin, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Dear Mr. Martin:



River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-260

On November 1, 1984, GSU notified Region IV by telephone of DR-260 concerning the piping configuration of the control rod drive scram discharge volume vent and drain lines, GSU determined this deficiency was reportable under 10CFR50.55(e). The attachment to this letter is GSU's interim 30-day written report pursuant to 10CFR50-55(e) with regard to this deficiency.

An interim or final status report will be provided by February 5, 1985.

Sincerely,

L. A. England

for J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

PJD
JEB/PJD/trp

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector-Site

INPO

8412210319 841203
PDR ADOCK 05000458
S PDR

IE-27

1/0