

50-322 04-3

SCEP 70

I-SC-70
1/24/84



DOCKET NUMBER
PROD. & UTIL. FAC. 50-322(4-3)

JANUARY 24, 1984

NUCLEAR REGULATORY COMMISSION

Docket No. 50-322-04 Official Exh. No. SCEP 70
In the matter of Shoreham - Emergency Planning
Staff _____ IDENTIFIED _____
Applicant _____ RECEIVED _____
Intervenor / _____ REJECTED _____
Com'g Offr. _____
Contractor _____ DATE 6/15/84
Other _____ Witness _____
Reporter R. Eyster

8408170245 840615
PDR ADOCK 05000322
PDR
6

GENERAL COMMENTS ON 1/28/89

Overall, events at the EOC went smoothly. The Communications group was disorganized as were messages handled by this group. This was largely due to the group being re-organized with five communicators rather than 3 as before. The group will function better after a few more drills.

For future drills, controllers will need to be better briefed. To prevent ^{the} miscommunications which occurred early at the EOC. It is unacceptable to ~~contact~~ brief fellow controllers at different locations on how the events are to occur ~~15~~ 15 minutes or the day before the drill. This unfamiliarity caused confusion amongst the participants and also created inconsistencies in procedural usage.

FEBRUARY 8, 1984

VI. Scenario

Summary

Comment on the adequacy of the scenario. Did it provide enough activity? Was it realistic? Did it test areas of earlier deficiency?

Input OBSERVERS. NOT BRIEFED ON KNOWLEDGE

ENOUGH ON PROCEDURES.

Summary

In your own words, describe and evaluate the demonstrated activities, capabilities and resources, or lack thereof, covered by this section. Put the facts recorded in the "yes/no" questions in perspective. Explain the deficiencies, and also note the exceptionally good performance.

1. OF THE 3 DOWIMETRY PERSONNEL AT DRILL ONLY ONE PARTICIPATED IN PREVIOUS DRILL. HE WAS AT ONE TIME UNFAMILIAR OF SEQUENCE IN EMERGENCY CLASSIFICATIONS. 400 DOWIMETERS WERE ZEROED IN $1\frac{1}{2}$ HOURS AND DISTRIBUTED IN 45 MINUTES. THIS VERY QUICK AND SATISFACTORY DISTRIBUTION TIME IS DUE TO THE DOWIMETRY GROUP TRAVELING TO EACH ROOM OF SEATED PERSONNEL. EXPECT EVEN BETTER TIMES WHEN ALL THREE RECORD KEEPERS ARE FULL DRILL EXPERIENCED AND INDEPENDENT.
2. RECORDS, COPIES AND THEIR HANDLING AND DELIVERY TO THE EOC WAS VERY EFFICIENT.
3. NOT SUFFICIENT OBSERVERS
4. SCENARIO CALLED FOR PEGGING ONE TRAFFIC GUIDES 0-200 MR DOWIMETER. WHEN RELATED TO THE LEAD TRAFFIC GUIDES HE TOOK NO ACTION. FINALLY A PROMPT WAS GIVEN TO NOTIFY THE EOC. REASSIGNMENT OF WOMEN WAS NOT OBSERVED. NOTE OPIT 363 DOES NOT SAY TO CALL EOC WHEN FIELD MEMBER REPORTS HIGH READING > 200 MA ON DOWIMETER (0-200). ROUTE ALERT DRIVERS WERE SENT OUT WITHOUT KI BECAUSE IT HAD NOT BEEN ANNOUNCED UNTIL 12:45 - WELL AFTER THE SIRENS SOUNDED FOR THE SITE AREA EMERGENCY.

Rad. Health

- DOE observer created a lot of confusion in EOC. Took away from E-H's time and placed doubt in the mind of some of the people as to how DOE/RAP would function.
- Communicators in Rad Health are very fast. None picked up the telephone when I was ringing, no messages taken. [General Comment on communications in EOC]
- EHC should tell communicator of he is going out of the room.

General

- Used framing in "showman ship".