

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

November 20, 1984
85 JAN 31 P 1:18

BLRD-50-438/83-61
BLRD-50-439/83-54

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - OVERTORQUED STUDS
ON BORG-WARNER GATE VALVE MOTOR OPERATORS - BLRD-50-438/83-61,
BLRD-50-439/83-54 - SUPPLEMENTAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector P. E. Fredrickson on November 21, 1983 in accordance with 10 CFR 50.55(e) as NCR 2390. This was followed by our interim reports dated December 19, 1983 and March 23, 1984 and our final report dated July 10, 1984. Below is our supplemental report. We consider 10 CFR Part 21 applicable to this deficiency.

As discussed with NRC-OIE Inspector P. E. Fredrickson on October 31, 1984, the date of October 31, 1984 for completion of corrective actions indicated in our final report on this matter was not met. The damaged operator studs have been replaced and retorqued, but the review of the remaining Borg-Warner valves affected by the torque change is continuing. The corrective action on this matter will be completed by February 1, 1985.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Dorn
for J. W. Hufham, Manager
Licensing and Regulations

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8502210375 841120
PDR ADOCK 05000438
S PDR

An Equal Opportunity Employer

OFFICIAL COPY

IE 27 10