



10 CFR 50.73

Pilgrim Nuclear Power Station
Rocky Hill Road
Plymouth, Massachusetts 02360

E. T. Boulette, PhD
Senior Vice President — Nuclear

April 29, 1996
BECo Ltr. #96-041

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555

Docket No. 50-293
License No. DPR-35

The enclosed Licensee Event Report (LER) 96-003-00, "Reactor Core Isolation Cooling System Made Inoperable due to Anomalies during Testing," is submitted in accordance with 10 CFR Part 50.73.

In this letter, the following commitment is made:

- Evaluate the failed speed control system hydraulic actuator which was replaced to determine the root cause and take additional action as necessary.

Please do not hesitate to contact me if there are any questions regarding this report.


E. T. Boulette, PhD

JPC/dmc/9600300

cc: Mr. Thomas T. Martin
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Sr. NRC Resident Inspector - Pilgrim Station

Standard BECo LER Distribution

060131

9605060338 960429
PDR ADOCK 05000293
S PDR

IF22
11