



Carolina Power & Light Company

Brunswick Steam Electric Plant  
P. O. Box 10429  
Southport, NC 28461-0429  
June 3, 1985

FILE: B09-13510C  
SERIAL: BSEF/85-0973

NRC Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555

BRUNSWICK STEAM ELECTRIC PLANT UNIT 1  
DOCKET NO. 50-325  
LICENSE NO. DPR-71  
IDENTIFICATION OF LICENSEE EVENT REPORT 1-85-026

Gentlemen:

On May 10, 1985, while performing Induction Heat Stress Improvement (IHSI) of Unit 1 reactor recirculation piping, in accordance with IE Bulletins 82-03, 83-02, and Generic Letter 84-11, posttesting inspections revealed five pin-hole leaks on the riser piping of the A and B recirculating loop piping. The required Licensee Event Report for these and any other reportable findings found during this testing will be submitted within 30 days following completion of the IHSI process and subsequent inspections.

Very truly yours,

C. R. Dietz, General Manager  
Brunswick Steam Electric Plant

MJP/jfm/LETJA

Enclosure

cc: Dr. J. N Grace

IE22  
1/0

8506060471 850603  
PDR ADOCK 05000325  
S PDR