



NARRATIVE REPORT LER #70-56

During the performance of a hanger rework project it was discovered that a section of Radwaste piping crosstied with the Core Spray Div. "B" test line was not supported per Seismic Class I requirements.

The cause of this was due to a design error as all loads were not accounted for in the original design.

To resolve this problem, action has been taken to upgrade this piping to Seismic Class I requirements. A review was made to determine if HNP-2 had a similar problem. The review revealed that a similar intertie did not exist on HNP-2; hence, the supports were not applicable.