

APPENDIX A

NOTICE OF VIOLATION

Based on the results of the NRC inspection conducted on November 10-19, 1975, it appears that one of your activities was not conducted in full compliance with conditions of your license as indicated below:

A. Contrary to Technical Specification 6.2.3 requirements for adherence to procedures, the following examples of noncompliance with procedures were identified.

1. Data recording requirements of SP1303-4.1 were not met for tests performed on July 22, 1975 and September 24, 1975; in that High Flux bistable input voltage at the trip point was not recorded required by the procedure. Actual system settings did not exceed Limiting Safety System Settings in this case.
2. The power range amplifier resetting administratively required by SP1302-1.1 to assure setpoint maintenance within the appropriate range was not accomplished on August 7, 1975. Actual system settings did not exceed Limiting Safety System Settings in this case.

This item is a Deficiency.

90012621

7910190

524