

CONNECTICUT YANKEE ATOMIC POWER COMPANY

HADDAM NECK PLANT

RR #1, BOX 127E, EAST HAMPTON, CONN. 06424

November 25, 1974
CYH-2818

Mr. James P. O'Reilly, Director
Region I
Directorate of Regulatory Operations
U. S. Atomic Energy Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

50-213


Dear Mr. O'Reilly:

We have completed the investigation involving the failure of #3 main steam line isolation valve reported to you on November 15, 1974. As a result of our investigation, this item is no longer considered "reportable" as defined in Connecticut Yankee Technical Specifications Section 5.3.

Our investigation indicated the failure of the #3 steam line trip valve to move during its weekly motion check (reference Section 4.9, Connecticut Yankee Technical Specifications) was due to a failure in the test system and not of the valve or its associated trip system. The test system has no effect on the valve in a trip situation.

These findings conclude, therefore, that at no time was the steam line trip valve unable to perform its intended safety function.

Very truly yours,


F. W. Hartley
Plant Superintendent

JHF/bn
cc: DOL, Washington, D. C.



12120

8103090041