

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONT  
7 8

REPORT SOURCE 1 5 0 5 0 0 0 3 3 4 7 0 2 1 0 8 1 3 0 3 1 2 8 1 9

60 61 DOCKET NUMBER 62 63 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES	(10)

1 At 1050 hours while at 97 percent power, the 1B Safety Injection Accumulator

[SI-TK-1B] low level alarm was received. Makeup to [SI-TK-1B] was begun at 1054

hours and level was restored at 1116 hours. The health and safety of the public was

not placed in jeopardy by this incident since all three accumulators remained

Examples of supplies located water to the core with only a slightly degraded level

In [SI-TK-1B]. Only two accumulators are required in the safety analysis.

SYSTEM CODE S F (11)		CAUSE CODE A (12)		CAUSE SUBCODE K (12)		COMPONENT CODE Z Z Z Z Z Z (14)				COMP SUBCODE Z (15)		VALVE SUBCODE Z (16)	
EVENT YEAR K 1 (12)		SEQUENTIAL REPORT NO. 0 2 1 (10)		OCCURRENCE CODE 0 3 (10)				REPORT TYPE L (10)		REVISION NO. 0 (10)			
ACTION TAKEN 1 (18)		FUTURE ACTION 1 (19)		EFFECT ON PLANT 2 (20)		SHUTDOWN METHOD 2 (21)		HOURS 0 0 0 0 (22)		ATTACHMENT SUBMITTED 1 (22)		NPROA FORM 108 1 (24)	
PRIME COMP. SUPPLIER 1 (25)		COMPONENT MANUFACTURER 2 0 0 0 (27)											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1. Chemist had been sampling the accumulators earlier in the day and inadvertently

I left open the sample valve for [SI-TK-13]. The tank had been draining down for

approximately 100 minutes prior to obtaining the alarm. At 1054 hours, after

Learning of the problem with [SI-TN-IB], the chemist returned to the sampling panel

and shut the valve.

FACTORY STREET	ADDRESS	OTHER STATUS	METHOD OF DISCOVERY	RECOVERY OR DISTRIBUTION
100	100	N/A	100	Control from manufacturer
ACTIVITY	AMOUNT OF ACTIVITY	LOCATION OF RELEASE		
100	N/A			
PERSONAL EXPENDITURES	DESCRIPTION			
100	N/A			
PERSONAL EXPENDITURES	DESCRIPTION			
100	N/A			
PERSONAL EXPENDITURES	DESCRIPTION			
100	N/A			

8108260 686

Attachment To LER 81-21/03L  
Beaver Valley Power Station  
Duquesne Light Company  
Docket No. 50-334

No further information is available or needed to satisfy the reporting requirement.