

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONT

REPORT SOURCE L A G O S O O O 3 3 4 7 0 2 1 1 8 1 6 0 3 1 2 8 1 2

40 61 DOCKET NUMBER 69 80 EVENT DATE 14 15 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

012 | At 1930 hours while performing a surveillance test on the control room chlorine

013 | detection system, it was discovered that the 1018 detector's electrolyte was not

014 | dripping. The detector was placed in the tripped condition as per Technical

015 | Specification 3.3.3.7. This is the fourteenth reported event involving the

016 | chlorine detectors.

017 |

018 |

SYSTEM CODE S 9		CAUSE CODE D 11		CAUSE SUBCODE B 12		COMPONENT CODE I N S T R U 14		COMP SUBCODE V 15		VALVE SUBCODE 7 16	
EVENT YEAR 9 10		SEQUENTIAL REPORT NO. 0 2 2 13		OCCURRENCE CODE 0 3 17		REPORT TYPE L 18		REVISION NO. 0 19		ACTION TAKEN A 20	
EFFECT ON PLANT 21		SHUTDOWN METHOD 22		HOURS 0 10 10 23		ATTACHMENT SUBMITTED V 24		WROTE FORMULA N 25		PRIME COMP SUPPLIER A 26	
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27		COMPONENT MANUFACTURER W O 2 3 28									

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (37)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (10)

The ICIB detector was returned to service on 2/14/81 after cleaning its flow orifice and replacing its wick. This problem is still under investigation by the Engineering department.

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
										A DRIVER										OTHER STATUS										REASON FOR DISCOVERY										DISCOVERY DESCRIPTION																																																											
										N/A										N/A										N/A										N/A																																																											
ACTIVITY										RELATES TO CHARGE										AMOUNT OF ACTIVITY										LOCAL VS. RELEASE																																																																					
										N/A										N/A										N/A																																																																					
PERMANENCE OF CHARGE										DESCRIPTION																																																																																									
										N/A																																																																																									
FEDERAL NUMBER										REGISTRATION																																																																																									
										N/A																																																																																									
SALES FACILITY																																																																																																			
										N/A																																																																																									
DATE																																																																																																			
										N/A																																																																																									

810326 0691

Attachment To LER 81-22/03L
Beaver Valley Power Station
Duquesne Light Company
Docket No. 50-334

No further information is available or needed to satisfy the reporting requirement.