

APPENDIX A

NOTICE OF VIOLATION

ABC Testing  
Bridgewater, Massachusetts 02324

Docket No. 030-19223  
License No. 20-19778-01

As a result of the inspection conducted on April 23-24, 1985, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violations were identified:

- A. 10 CFR 34.24 requires that each survey instrument used to conduct physical radiation surveys be calibrated at intervals not to exceed three months and after each instrument servicing.

Contrary to the above, during the period from November 7, 1984 to March 14, 1985, physical radiation surveys were conducted with a survey instrument which was last calibrated on August 6, 1984, an interval of more than three months prior to the date of use.

This is a Severity Level IV violation. (Supplement VI)

- B. 10 CFR 34.31(a)(2) requires that no licensee permit any person to act as a radiographer until that person has received copies of Title 10 Code of Regulations, Part 34 and the applicable sections of Parts 19 and 20, NRC license(s) under which the radiographer will perform radiography, and the licensee's operating and emergency procedures.

Contrary to the above, as of April 24, 1985, individuals were permitted to act as radiographers that had not received copies of the required Parts of Title Ten Code of Regulations, your NRC license, and your operating and emergency procedures.

This is a Severity Level IV violation (Supplement VI).

- C. 10 CFR 34.11 requires that licensees have an internal inspection system to assure operating and emergency procedures are followed by radiographers and radiographer's assistants and the performance of inspections at intervals not to exceed three months and retention of records of the inspections for two years.

Contrary to the above, as of April 24, 1985, no inspections of your radiographers had been performed during calendar years 1984 and 1985.

This is a Severity Level IV violation (Supplement VI).

- D. 10 CFR 34.33(a) requires that all radiographers and radiographer's assistants wear pocket dosimeters during all radiographic operations and that the pocket dosimeters be recharged at the beginning of each shift.

Contrary to the above, as of April 24, 1985, radiographers routinely failed to recharge their pocket dosimeters at the beginning of each shift during 1984 and 1985.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, ABC Testing is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.