

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

7 8 9 80

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

7 8 9 80

NRC USE ONLY

746-2084 Y32A

070-610-0



Commonwealth Edison
Zion Generating Station
Shiloh Blvd. & Lake Michigan
Zion, Illinois 60099
Telephone 312/746-2084

COPY

September 16, 1983

Mr. James G. Keppler
Regional Administrator
Directorate of Inspection and Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Rd.
Glen Ellyn, IL 60137

Reference: Zion Generating Station
Docket No. 50-295/DPR-39
Technical Specification, Section 6.6.2

Dear Mr. Keppler

The enclosed Licensee Event Report from Zion Generating Station is being transmitted to you in accordance with the requirements of Technical Specifications, Section 6.6.2.b (3). This section states a thirty day report is required when observed inadequacies in the implementation of administration or procedural controls threaten to cause reduction of degree of redundancy provided in reactor protection systems or engineered safety feature systems.

This report is number 83-031/03 L-0, Docket No. 50-295/DPR-39.

Very truly yours,

K. L. Graesser
Superintendent
Zion Generating Station

KLK/gm

Enclosure: Reportable Occurrence Report No. 83-031/03 L-0

Attachment

cc: J. Waters, NRC Resident Inspector

1E22
11
83 RETROFIT

SEP 19 1983