

# UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO: 50-423  
 UNIT: MILLSTONE UNIT 3  
 DATE: January 7, 1993  
 COMPLETED BY: A. L. Elms  
 TELEPHONE: 203-444-5388

Number	Date	Type (1)	Duration (Hours)	Reason (2)	Method of Shutting Down the Reactor (3)	Licensee Event Report Number	System Code	Component Code	Cause and Corrective Action to Prevent Recurrence
92-10	12/10/92	F	0	F	5	N/A	KE	SCN	Decreased power due to storm conditions. This was an administrative power reduction in accordance with plant procedures.
92-11	12/18/92	F	0	G	5	N/A	SL	TK	Decreased power due to loss of motor driven feedwater pump. The feedwater pump was removed from service due to loss of oil caused by overfilling the pump oil sump. Procedures are being modified to prevent overfilling of the sump.

1: F: Forced  
 S: Scheduled

2: Reasons:  
 A Equipment Failure (Explain)  
 B Maintenance or Test  
 C Refueling  
 D Regulatory Restriction  
 E Operator Training & License Exam  
 F Administrative  
 G Operational Error (Explain)  
 H Other

3: Method  
 1 Manual  
 2 Manual Scram  
 3 Automatic Scram  
 4 Continued from Previous Month  
 5 Power Reduction (Duration = 0)  
 9 Other (Explain)

4: Exhibit G - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG-0161)  
 5: Exhibit I - Same Source

9302110336 930205  
 PDR ADDCK 05000423  
 PDR