

U. S. NUCLEAR REGULATORY COMMISSION

REGION III

Report No. 50-087/85001(DRSS)

Docket No. 50-087

License No. R-119

Safeguards Group II

Licensee: Westinghouse Electric Corporation  
Westinghouse Nuclear Training Center  
505 Shiloh Boulevard  
Zion, IL 60099

Facility Name: Westinghouse Nuclear Training Center

Inspection At: Westinghouse Nuclear Training Center, Zion, IL

Inspection Conducted: April 8-11, 1985 onsite  
April 15, 1985 in Region III Office

Type of Inspection: Unannounced Physical Security

Date of Previous Physical Security Inspection: February 14-15, 1983

Inspectors: G. L. Pirtle  
G. L. Pirtle  
Physical Security Inspector

5/21/85  
Date

G. L. Pirtle  
for B. Drouin  
Physical Security Inspector

5/21/85  
Date

Approved By: R. Creed  
R. Creed, Chief  
Safeguards Section

5/21/85  
Date

Inspection Summary

Inspection on April 8-15, 1985 (Report No. 50-087/85001(DRSS))

Areas Inspected: Included Security Organization; Use and Storage Area for SNM; Detection Devices and Procedures; Access Controls; Communications; Response Procedures; and Lost Material Notification. The inspection involved 55 inspector-hours by two NRC inspectors. The inspection was begun during normal working hours. Five of the fifty-five inspector-hours were completed during off-shift periods.

Results: Four possible violations were noted in the areas inspected as listed below:

8505310305 850521  
PDR ADOCK 05000087  
Q PDR

ATTACHMENT CONTAINS  
10 CFR 2.790(d) INFO

- a. Detection Devices and Procedures: Some alarm monitoring requirements were not being performed.
- b. Access Control: Required personnel screening was not completed for one individual.
- c. Access Control: Two security-related keys, when not in use, were not controlled in accordance with Security Plan criteria.
- d. Access Control: Required combination changes for certain security-related locks were not made in a timely manner.

An unresolved item pertaining to compensatory measures for certain alarm equipment outages was noted and will be sent to NRC, HQ for resolution. Additionally, a concern was noted pertaining to the detection capability for an alarm system.

The licensee's initial immediate corrective actions for the apparent violations and area of concern appeared adequate.

(Details - 10 CFR 2.790(d) Information)