

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

June 11, 1985

BLRD-50-438/85-07
BLRD-50-439/85-07

U.S. Nuclear Regulatory Commission
Region II
Attn: Dr. J. Nelson Grace, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Dr. Grace:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - INADEQUATE GROUTED ANCHOR INSPECTION
RECORDS - BLRD-50-438/85-07 AND BLRD-50-439/85-07 - SECOND INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector Al Ignatonis on January 18, 1985 in accordance with 10 CFR 50.55(e) as NCR 3714. Our first interim report was submitted on February 19, 1985. Below is our second interim report. We expect to submit our next report on or about September 3, 1985.

Interim Progress

TVA's Office of Engineering (OE) has evaluated all of the grouted anchor installations identified by the Office of Construction (OC) personnel and dispositioned the deficient installations. OC personnel are evaluating all the grout records for verification of acceptance or rejection based on OE's disposition. The results of this evaluation will be provided in a future report.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Dorn
for J. W. Hufham, Manager
Licensing and Regulations

cc: Mr. James Taylor, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8507110345 850611
PDR ADOCK 05000438
S PDR

85 JUN 17 PM 12:33

OFFICIAL COPY

IE 27/16