



Northeast  
Utilities System

Millstone Offices • Rope Ferry Rd., Waterford, CT

P.O. Box 128  
Waterford, CT 06385-0128  
(203) 447-1791

October 4, 1996

Docket No. 50-245  
B15914

Re: 10CFR50.73(a)(2)(i)  
10CFR50.73(a)(2)(v)

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

This letter forwards Licensee Event Report (LER) 96-049-00, documenting an event that occurred at Millstone Nuclear Power Station, Unit No. 1 on May 24, 1996. This LER is submitted pursuant to 10CFR50.73(a)(2)(i) and 10CFR50.73(a)(2)(v).

This condition was promptly reported under 10CFR50.72(b)(2)(iii)(D) on May 24, 1996, as a condition that alone could have prevented the fulfillment of the safety function of systems needed to mitigate the consequences of an accident. The resolution of the relay issues for Millstone Unit No. 1 is an ongoing effort. As stated in LER 96-003, dated February 12, 1996, Northeast Nuclear Energy Company (NNECO) intended to report all issues identified through the USI A-46 program in one final supplement to LER 96-003 by January 10, 1997. NNECO has subsequently determined that it would be more appropriate to submit separate LERs for the relay issue and the seismic anchorage issue. This LER will be supplemented to provide the resolution of the relay issues.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY

W. J. Riffer  
Director - Millstone Unit No. 1

9610160067 961004  
PDR ADOCK 05000245  
S PDR

Attachment: LER 96-049-00

cc: H. J. Miller, Region I Administrator  
T. A. Easlick, Senior Resident Inspector, Millstone Unit No. 1  
J. W. Andersen, NRC Project Manager, Millstone Unit No. 1

IE22