

3/18/80

MEMORANDUM FOR: Regional Directors

FROM:

E. L. Jordan

SUBJECT:

IEB 79-14 / UNIFORMITY AND PART 21

The attached memorandum addresses two problems with regard to IEB 79-14.

First, the licensee for Turkey Point and the licensee's AE have been reluctant to identify the materials of construction for piping systems as requested by IEB 79-14. The licensee's AE has stated that action by IE is not uniform in this area.

Instructions for followup to the bulletin have been sent to all regions to ^{assure} that our effort will be uniform.

Second, in performing the effort requested in IEB 79-14, the licensee has identified an overstress problem which may be generic. If the problem results from an error in design or analytical methods applied by the AE, then the problem is potentially generic. If this is the case, even though the licensee has submitted

A-14

an LE2, we expect the licensee to submit a Part 21 report.

If you have questions or comments pertaining to these problems, please call.

CONTACT: R. W. Woodruff

cc:	N. Moseley,	IE
	S. Bryan,	"
	H. Wong,	"
	W. Reinmuth,	"
	V. Noonan,	NR2
	S. Hasford,	"
	R. LaGrange,	"

Attachment