

PURITAN DIAGNOSTICS, P.C.
15914 JAMES COUZENS
DETROIT, MICHIGAN 48238
313-864 8455

June 17, 1985

TO: U.S. NUCLEAR REGULATORY COMMISSION, REGION 3
ATTENTION: W.L. AXELSON, CHIEF
NUCLEAR MATERIALS SAFETY AND SAFEGUARDS BRANCH
799 ROOSEVELT ROAD
GLEN ELLYN, ILL. 60137

Dear Mr. Axelson,

This letter is to outline corrective actions taken since a routine NRC inspection on May 1, 1985.

First and foremost, we have contracted the services of Medical Physics Consultants, Inc. (MPC) of Ann Arbor, to supervise and control federal and state compliance requirements. They now make routine quarterly inspections of our facility and report to us with their findings and recommendations. I believe this should satisfy your concerns with "management control".

- Item 1: The Bicron survey meter has been shipped to MPC for calibration.
- Item 2: All sealed sources have been and will be tested for leakage by MPC at semi-annually.
- Item 3: The dose calibrator is now tested as follows.
 - Annual accuracy tests
 - Quarterly linearity tests
 - Installation geometrical test
- Item 4: Radioactive packages are now received and opened in accordance with reg. guide 10, 8, appendix F.
- Item 5: Both daily and weekly surveys are now performed in accordance with reg. guide 10, 8, appendix 1.
- Item 6: All documents and notices have been posted or referenced as required by 10CFR 19/20.

All items have been corrected as of this writing.

Sincerely,

2/20/91
Nanjappa Sadasivan M.D.

8507150424 850711
REG3 LIC30
21-20455-01 PDR

JUN 24 1985